




INQUIRY #: 8156261.8

YEAR: 1974

— = 750'



Subject boundary not shown because it exceeds image extent or image is not georeferenced.



INQUIRY #: 8156261.8

YEAR: 1969

— = 750'





INQUIRY #: 8156261.8

YEAR: 1952

— = 750'



Subject boundary not shown because it exceeds image extent or image is not georeferenced.



Henderson I-10 Site

I-10

Breaux Bridge, LA 70517

Inquiry Number: 8156261.4

October 29, 2025

EDR Historical Topo Map Report

with QuadMatch™



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

EDR Historical Topo Map Report

10/29/25

Site Name:

Henderson I-10 Site
I-10
Breaux Bridge, LA 70517
EDR Inquiry # 8156261.4

Client Name:

Chenier Environmental Consulting
PO Box 82466
Baton Rouge, LA 70884
Contact: Aaron Bass



EDR Topographic Map Library has been searched by EDR and maps covering the target property location as provided by Chenier Environmental Consulting were identified for the years listed below. EDR's Historical Topo Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDR's Historical Topo Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the late 1800s.

Search Results:**Coordinates:**

P.O.#	NA	Latitude:	30.317196 30° 19' 2" North
Project:	Henderson I-10 Site	Longitude:	-91.835519 -91° 50' 8" West
		UTM Zone:	Zone 15 North
		UTM X Meters:	611956.41
		UTM Y Meters:	3354508.44
		Elevation:	20.00' above sea level

Maps Provided:

2020	1940
2018	
2015	
2012	
1998	
1972	
1970	
1963	

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT.

ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Topo Sheet Key

This EDR Topo Map Report is based upon the following USGS topographic map sheets.

2020 Source Sheets



Cecilia
2020
7.5-minute, 24000

2018 Source Sheets



Cecilia
2018
7.5-minute, 24000

2015 Source Sheets



Cecilia
2015
7.5-minute, 24000

2012 Source Sheets




Cecilia
2012
7.5-minute, 24000

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1998 Source Sheets



Cecilia
1998
7.5-minute, 24000
Aerial Photo Revised 1998

1972 Source Sheets




Arnaudville
1972
15-minute, 62500

1970 Source Sheets



Cecilia
1970
7.5-minute, 24000
Aerial Photo Revised 1969

1963 Source Sheets



Arnaudville
1963
15-minute, 62500
Aerial Photo Revised 1963

Topo Sheet Key


This EDR Topo Map Report is based upon the following USGS topographic map sheets.

1940 Source Sheets




Arnaudville
1940
15-minute, 62500






This report includes information from the following map sheet(s).





TP, Cecilia, 2018, 7.5-minute

SITE NAME: Henderson I-10 Site
ADDRESS: I-10
Breaux Bridge, LA 70517
CLIENT: Chenier Environmental Consulting






This report includes information from the following map sheet(s).





TP, Cecilia, 2015, 7.5-minute

SITE NAME: Henderson I-10 Site
ADDRESS: I-10
Breaux Bridge, LA 70517
CLIENT: Chenier Environmental Consulting






This report includes information from the following map sheet(s).




TP, Cecilia, 2012, 7.5-minute

SITE NAME: Henderson I-10 Site
 ADDRESS: I-10
 Breaux Bridge, LA 70517
 CLIENT: Chenier Environmental Consulting






This report includes information from the following map sheet(s).





TP, Cecilia, 1998, 7.5-minute

SITE NAME: Henderson I-10 Site
ADDRESS: I-10
Breaux Bridge, LA 70517
CLIENT: Chenier Environmental Consulting






This report includes information from the following map sheet(s).




TP, Arnaudville, 1972, 15-minute

SITE NAME: Henderson I-10 Site
 ADDRESS: I-10
 Breau Bridge, LA 70517
 CLIENT: Chenier Environmental Consulting






This report includes information from the following map sheet(s).





TP, Cecilia, 1970, 7.5-minute

SITE NAME: Henderson I-10 Site
 ADDRESS: I-10
 Breaux Bridge, LA 70517
 CLIENT: Chenier Environmental Consulting






This report includes information from the following map sheet(s).





TP, Arnaudville, 1963, 15-minute

SITE NAME: Henderson I-10 Site
 ADDRESS: I-10
 Breau Bridge, LA 70517
 CLIENT: Chenier Environmental Consulting





This report includes information from the following map sheet(s).



TP, Arnaudville, 1940, 15-minute

SITE NAME: Henderson I-10 Site
ADDRESS: I-10
Breau Bridge, LA 70517
CLIENT: Chenier Environmental Consulting





Henderson I-10 Site

I-10

Breaux Bridge, LA 70517

Inquiry Number: 8156261.3

October 29, 2025

Certified Sanborn® Map Report



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Certified Sanborn® Map Report

10/29/25

Site Name:

Henderson I-10 Site
I-10
Breaux Bridge, LA 70517
EDR Inquiry # 8156261.3

Client Name:

Chenier Environmental Consulting
PO Box 82466
Baton Rouge, LA 70884
Contact: Aaron Bass



The Sanborn Library has been searched by EDR and maps covering the target property location as provided by Chenier Environmental Consulting were identified for the years listed below. The Sanborn Library is the largest, most complete collection of fire insurance maps. The collection includes maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow, and others. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by the Sanborn Library LLC, the copyright holder for the collection. Results can be authenticated by visiting www.edrnet.com/sanborn.

The Sanborn Library is continually enhanced with newly identified map archives. This report accesses all maps in the collection as of the day this report was generated.

Certified Sanborn Results:

Certification # 4141-445A-AF2C

PO # NA

Project Henderson I-10 Site

UNMAAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.



Sanborn® Library search results

Certification #: 4141-445A-AF2C

The Sanborn Library includes more than 1.2 million fire insurance maps from Sanborn, Bromley, Perris & Browne, Hopkins, Barlow and others which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

- ☒ Library of Congress
- ☒ University Publications of America
- ☒ EDR Private Collection

The Sanborn Library LLC Since 1866™

Limited Permission To Make Copies

Chenier Environmental Consulting (the client) is permitted to make up to FIVE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT.

ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT. Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

Henderson I-10 Site

I-10

Breaux Bridge, LA 70517

Inquiry Number: 8156261.5

October 31, 2025

The EDR-City Directory Image Report

TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.

Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA), ARISING OUT OF OR IN ANY WAY CONNECTED WITH THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2023 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available business directory data at approximately five year intervals.

RECORD SOURCES

The EDR City Directory Report accesses a variety of business directory sources, including Haines, InfoUSA, Polk, Cole, Bresser, and Stewart. Listings marked as EDR Digital Archive access Cole and InfoUSA records. The various directory sources enhance and complement each other to provide a more thorough and accurate report.

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

<u>Year</u>	<u>Target Street</u>	<u>Cross Street</u>	<u>Source</u>
2022	☑	☑	EDR Digital Archive
2017	☑	☑	Cole Information
2014	☑	☑	Cole Information
2010	☑	☑	Cole Information
2005	☑	☑	Cole Information
2000	☑	☑	Cole Information
1995	☑	☑	Cole Information
1992	☑	☑	Cole Information

FINDINGS

TARGET PROPERTY STREET

I-10

Breaux Bridge, LA 70517

<u>Year</u>	<u>CD Image</u>	<u>Source</u>
-------------	-----------------	---------------

I 10 FRONTAGE HWY

2022	pg A5	EDR Digital Archive
2017	pg A7	Cole Information
2014	pg A10	Cole Information
2010	pg A13	Cole Information
2005	pg A15	Cole Information
2000	pg A17	Cole Information
1995	pg A19	Cole Information
1992	pg A21	Cole Information

FINDINGS

CROSS STREETS

<u>Year</u>	<u>CD Image</u>	<u>Source</u>
-------------	-----------------	---------------

GRAND POINT HWY

2022	pg. A2	EDR Digital Archive
2017	pg. A6	Cole Information
2014	pg. A8	Cole Information
2010	pg. A11	Cole Information
2005	pg. A14	Cole Information
2000	pg. A16	Cole Information
1995	pg. A18	Cole Information
1992	pg. A20	Cole Information

City Directory Images

GRAND POINT HWY 2022

2804	THE SEAFOOD BOILER
2815	CRAWFISH TOWN USA. INC
	LSE ENTERPRISES LLC
	WENDY HEBERT
2824	ALEX KIDDER
	ANGEL KIDDER
	EARL KIDDER
	JACKIE KIDDER
	THELMA KIDDER
2825	AMPLIFY NUTRITION LLC
	BLANCHARD DEANNA
	BLANCHARD DEANNA MD
	BON AMI PHARMACY
	LAFAYETTE GENERAL MEDICAL DOCTORS
	MYLES STELLY
2829	FARMERS & MERCHANTS BANK & TRUST
	FARMERS MERCHANTS BANK
	HEATHER MASON
	PATRICIA SEIGLER
2838	DARIAN BURAS
	WILLIAM BURAS
2842	MEAGAN ANDREPONT
	MEAGAN ANDREPONT PHOTOGRAPHY
	TEX ANGELLE
2852	ANGELLE TEX
	TEX ANGELLE
2867	ANGEL POIRIER
2868	FRANKIE LAPORTE
	SPENCER LAPORTE
2875	BRAYLEN JOHNSON
	DAVID EDDY
	ETHAN EDDY
	MICHELLE EDDY
2876	JOHN ZERINGUE
2877	BUDDY EDDY
	GERTRUDE EDDY
2894	MARK ZIMMERMAN
2924	ALLISON G ENTERPRISE LLC
	BAYOU BELLE TRUCK STOP
	SOUTHWEST UTILITIIES
2926	BOUDIN & CRACKLIN EXPRESS
	LYNWOOD HEBERT
2937	DIESI DEVELOPMENT CENTER
	DIESIS LUCKY CAPITOL
	FRANK DIESI
2939	DCS LUCKY CAPITOL
	EMMA CALAIS
	EVANGELINE DOWNS
	EXXON GAS STATION
	FRANK DIESI

GRAND POINT HWY

2022

(Cont'd)

2939	LITTLE CAPITOL LITTLE CAPITOL EXXON RACES & ACES
2942	CANDI MILLER CATHY MILES CHICKEN ON THE BAYOU EILLOTT MILES HOLIDAY INN HOLIDAY INN EXPRESS TEXACO
2987	AMIN AMLANI AYRRAYN INT INC E USA HENDERSON 1-10 EXXON MIKE ORTEGO SUBWAY TOBACCO PLANT
2996	ATCHAFALAYA GOLD CASINO HENDERSON TRAVEL PLAZA JOSHUA YOUNG
2998	PRECISION CUTS BARBER SHOP THUY DOAN WAFFLE HOUSE
2999	HIT-N-RUN FOOD STORES JOHNNIE MARKS LAUREN BATISTE MCDONALDS
3002	2 PAT 2S CAJUN KITCHENS MYERS QUICKSTOP RHONDA MYERS SARAH PATOUT
3003	MISS MAMIES VIDEO POKER CASINO PHILLIP HEYMAN PILOT FLYING J PILOT TRAVEL CENTERS K LLC REAGAN DOMINGUE
3008	PILOT TRAVEL CENTERS LLC
3017	KENNY COMPTE MARIE CASTILLO POPEYES CHICKEN & BISCUITS POPEYES LOUISIANA KITCHEN
3048	BOBBY KIDDER RICHARD FRUGE SUE KIDDER
3054	GILCHRIST CONSTRUCTION CO
3060	BAILEY WILTZ HEATHER KELLEY JAMES O'CONNOR JESSIE FRANKLIN WENDY WILTZ

GRAND POINT HWY 2022 (Cont'd)

3063	CLIFFORD MOUTON
3068	HEATHER THIBODEAUX
	LILIAN NGUYEN
3069	MARTIN JONES
3073	MARION SYLVESTER
	SYLVAIN SYLVESTER
3083	DAVID AYO
	MELISSA AYO
3085	HOLDEN GUIDRY
	JENNIFER GUIDRY
	KEVIN GUIDRY
	MYKA GUIDRY
3091	CASSANDRA FELPS
	DARRYL FELPS
	DONNA FELPS
3094	GILL PATIN
3097	ELLA HARRINGTON

I 10 FRONTAGE HWY**2022**

1091	GEORGIA DUPLECHIN
	RYAN DUPLECHIN
1093	COREY DUPLECHIN
	JENNY DUPLECHIN
	MONICA DUPLECHIN
	NATASHA DUPLECHIN
	RYAN DUPLECHIN
1103	LOWELL GUIDRY
	VICKI GUIDRY
1167	DONALD POUSSON
	POUSSON FAMILY FARM
	RICHARD LORMAND

GRAND POINT HWY 2017

2810	LOUISIANA AUTO REPAIR CO LLC
	THOMAS, ADAM C
2815	CRAWFISH TOWN USA
2824	KIDDER, JACKIE J
2838	BURAS, WILLIAM J
2842	ANDREPONT, ALBERT J
2852	TEX ANGELLE
2868	HUVAL, DALE A
2872	AGS GOLF CARTS
2875	EDDY, DAVID E
2877	EDDY, BUDDY J
2894	ZIMMERMAN, MARK L
2926	BOUDIN & CRACKLIN EXPRESS
2937	EXXON
2939	EXXON
2942	HOLIDAY INN EXPRESS BREAUX BRIDGE HE
	TEXACO
	THE CAJUN PALETTE
2987	AYRRAYN INT INC
	EXXON
	SUBWAY
2996	HENDERSON TRAVEL PLAZA
2998	WAFFLE HOUSE
2999	HITNRUN FOOD STORES
	MCDONALDS
3002	DONUT QUEEN
	KYLES CAJUN KITCHEN
	MYERS QUICKSTOP
3003	MISS MAMIES HENDERSON CASINO
	PILOT TRAVEL CENTERS
3048	FRUGE, RICHARD J
	KIDDER, BOBBY C
3060	BROUSSARD, COLBY J
	CASTILAW, PAUL
	DEVILLE, JEANNETTE B
	FRANKLIN, JESSIE
	WILTZ, BRANDY
3063	MOUTON, CLIFFORD J
3068	SANCHEZ, JOSEPH C
3072	GUIDRY, LOUIS P
3085	GUIDRY, KEVIN C
3094	VOORHIES, EDDIE J
3097	HARRINGTON, DONALD P

I 10 FRONTAGE HWY

2017

1151 STATE OF LOUISIANA

GRAND POINT HWY 2014

2810	LOUISIANA AUTO REPAIR CO LLC
	OCCUPANT UNKNOWN,
2815	CRAWFISH TOWN USA
2824	KIDDER, JACKIE J
2838	BURAS, WILLIAM J
2842	OCCUPANT UNKNOWN,
2850	TRAHAN, KENNETH J
2852	ANGELLE TEX
	ANGELLE, TEX
2862	ANGELLE INDUSTRIES LLC
2868	HUVAL, SUSAN A
2876	HUVAL, DAVE A
2877	EDDY, PAUL A
2893	OCCUPANT UNKNOWN,
2894	ZIMMERMAN, MARK L
2926	BOUDIN & CRACKLIN EXPRESS
2937	DIESIS LUCKY CAPITOL
2939	DIESIS LITTLE CAPITOL EXXON
	EVANGELINE DOWNS
2942	CAJUN PALETTE THE
	CHICKEN ON THE BAYOU
	HOLIDAY INN EXPRESS
	LANDRYS I10 TEXACO
	TEXACO STATION BREAUX BRIDGE
2987	AYRRAYN INT INC
	HENDERSON I10 EXXON
	SUBWAY SANDWICHES
2996	HENDERSON TRAVEL PLAZA
	TEXACO STATION BREAUX BRIDGE
2998	WAFFLE HOUSE
2999	HITNRUN FOOD STORES
	MCDONALD, S
	MCDONALDS
3002	2PAT2S CAJUN KITCHENS
	CHEVRON STATION BREAUX BRIDGE
	DONUT QUEEN
	EL PUERTO
	MYERS QUICKSTOP
3003	MISS MAMIES HENDERSON CASINO
	PILOT TRAVEL CENTERS
3017	POPEYES CHICKEN
3048	FRIDGE, RICHARD
	FRUGE, RICHARD J
3059	CAJUN TOWING & RECOVERY INC
3060	BROUSSARD, COLBY J
	DEVILLE, JEANNETTE B
	DHAKAL, SABITRA
	JOHNSON, WILLIAM A
	KELLEY, HEATHER
3063	ALLEMAN, MARY

GRAND POINT HWY 2014 (Cont'd)

3068	SANCHEZ, JOSEPH C
3069	JONES, MARTIN J
3072	GUIDRY, LOUIS P
3075	GUIDRY, ANDRES P
3083	HEBERT, HAMOY
3085	GUIDRY, KEVIN C
3087	GUIDRY, JENNY
3091	GUIDRY, DALE R
3094	OCCUPANT UNKNOWN, VOORHIES, EDDIE J
3097	HARRINGTON, DONALD P

I 10 FRONTAGE HWY**2014**

1093	DUPLECHIN, RYAN J
	OCCUPANT UNKNOWN,
1103	GUIDRY, LOWELL T
1150	STATE OF LOUISIANA
1151	STATE OF LOUISIANA
1167	POUSSON, CHAMPAG
1187	HARMAN, NORMA M

GRAND POINT HWY 2010

2810	BIG JS AUTO REPAIR
2815	CRAWFISH TOWN USA
	J B TRUCKING
2824	WILTZ, LARRY J
2838	BURAS, WILLIAM J
2842	ANDREPONT, ALBERT J
	MEAGAN ANDREPONT PHOTOGRAPHY
2850	TRAHAN, KENNETH J
2852	ANGELLE INDUSTRIES LLC
	ANGELLE TEX
	ANGELLE, TEX
2868	HUVAL, JAMES P
2875	EDDY, DAVID E
2876	HUVAL, DALE A
2877	EDDY, PAUL A
2894	ZIMMERMAN, MARK L
2904	LANDRY, EDDIE L
2924	BAYOU BELLE TRUCK STOPCASINO
	LA GRAND FROMAGE
2937	DIESIS LUCKY CAPITOL
2939	LITTLE CAPITOL EXXON
2942	BOUDIN
	CAJUN PALETTE
	CHICKEN ON THE BAYOU
	COASTAL TEL ELECTRONICS CO
	HOLIDAY INN EXPRESSBREAUX BRG
	TEXACO
2987	EUSA
	HENDERSON I10 EXXON
2996	ATCHAFALAYA GOLD CASINO
	HENDERSON TRAVEL PLAZA
2998	NEW BEGINNINGS SALON
	ST ELIZABETH FAMILY PRACTICE
	TOUCH BY ANGEL
	WAFFLE HOUSE
2999	HIT N RUN
	MC DONALDS
3002	2 PAT 2S CAJUN KITCHENS
	CAJUN KEVINS MARKET & RSTRNT
	MYERS QUICKSTOP
3003	I 10 HENDERSON TRAVEL CTR
	MISS MAMIES HENDERSON CASINO
3017	POPEYES CHICKEN & BISCUITS
3048	FRUGE, RICHARD J
3059	CAJUN ENVIRONMENTAL
3060	BROUSSARD, COLBY J
	DEVILLE, JEANNETTE B
	DEVINE, JEANETTE B
	ELMORE, BARBARA
	HANKS, SARAH

GRAND POINT HWY 2010 (Cont'd)

3060	JOHNSON, WILLIAM A
3063	HEBERT, ANDY
3068	DUPUIS, GRACE G
3069	SINGLETON, STACY M
3072	GUIDRY, NELLIE A
3083	HEBERT, HAMOY
3085	GUIDRY, KEVIN C
3091	GUIDRY, DALE R
3094	VOORHIES, EDDIE J
3097	HARRINGTON, DONALD P

I 10 FRONTAGE HWY**2010**

1091	DUPLECHIN, GERALD D
1093	DUPLECHIN, RYAN
1103	OCCUPANT UNKNOWN,
1167	POUSSON, DONALD R
1187	HARMAN, NORMA M

GRAND POINT HWY 2005

2810	BIG J S AUTO REPAIR
2824	K & H INVESTMENTS INC
	KIDDER, EARL C
2838	BURAS, WILLIAM J
2852	TEX ANGELLE TRUCKING & MATERIALS
2868	HUVAL, JAMES
2875	EDDY, DAVID E
2876	HUVAL, DALE A
2893	EDDY, BUDDY J
2904	LANDRY, EDDIE L
2924	BAYOU BELLE TRUCK STOP AND CASINO
2937	DIESI DEVELOPMENT CENTER
	LITTLE CAPITOLLOUISIANA
2939	DIESI LUCKY CAPITAL
	LITTLE CAPITOL EXXON
2942	CHICKEN ON THE BAYOU
	HOLIDAY INN EXPRESS
	LANDRYS GRAND POINT TEXACO
2987	HENDERSON EXXON
	SUBWAY SANDWICHES
2996	HENDERSON TRAVEL PLAZA
2998	MILLER PROPERTIES INC
2999	MCDONALDS OF HENDERSON
3002	KYLES CAJUN KITCHEN
	TREASURE ISLAND FROZEN DRINKS
3048	FRUGE, RICHARD J
	KIDDER, BOBBY L
3073	VALSIN, MARION M
3075	THE BODY SHOP BAR
3083	STELLY, CYNTHIA
3085	MOUTON, DALE G
3094	BOUTIN, HILDEN J
	VOORHIES, E J
	VOORHIES, WALTER
3097	HARRINGTON, DONALD P

I 10 FRONTAGE HWY**2005**

1091	DUPLECHIN, GERALD D
1093	DUPLECHIN, COREY
	OCCUPANT UNKNOWN,
1103	GUIDRY, LOWELL T
1167	POUSSON, DONALD R

GRAND POINT HWY 2000

2815	CRAWFISH TOWN USA
	GUIDRY & COMPANY REALTORS
2824	KIDDER, ORESTE
2842	BREAUX, ASHBY
2868	HUVAL, ALTON
2872	AUGUILLARD PLASTERING
2875	EDDY, DAVID
2876	HUVAL, DALE A
2877	EDDY, BUDDY
2893	EDDY, PAUL
2937	DIESIS LUCKY CAPITOL
2942	BEE HIVE FUDGERY INCORPORATED
	CHICKEN ON THE BAYOU
	GALLERY OF CAJUN HISTORY
	HOLIDAY INN EXPRESS
2987	E U S A
	SUBWAY SANDWICHES
2992	ATCHAFALAYA GOLD CASINO
2996	HUNGRY HOBO
2997	HENDERSON I 10 EXXON
2998	WAFFLE HOUSE NO 826
3002	DAIRY QUEEN
3017	SHEPLER, RICHARD C
3060	WILTZ, LARRY J
3085	MOUTON, DALE
3091	GUIDRY, JESSIE
3094	BOUTIN, ATHALIE C
3097	HARRINGTON, DONALD

Target Street

✓

Cross Street

-

Source

Cole Information

I 10 FRONTAGE HWY

2000

1091 DUPLECHIN, GERALD

GRAND POINT HWY 1995

2667	EDS ELECTRICAL SVC INC
2691	ATCHAFALAYA AUTO SALES
2815	CRAWFISH TOWN USA
2939	LITTLE CAPITOL EXXON
2942	CAJUN VILLAGE TEXACO
	GALLERY OF CAJUN HISTORY
	VILLAGE OYSTER BAR
2987	HENDERSON I 10 EXXON
	U HAUL CO
3052	COUNTRY VIDEO
3073	ALEXANDER, J
3075	CAJUN WRECKER
3193	DOUGLAS, JOE
3595	LA MAISON DES PETITS
3610	ROBINS NEST
3613	HUVALS SEAFOOD

Target Street

✓

Cross Street

-

Source

Cole Information

I 10 FRONTAGE HWY

1995

1091 DUPLECHIN, GERALD
1148 WEIGH STATION

GRAND POINT HWY 1992

2667	EDS ELEC SRVC
3073	LEBLANC, JOHNNY
3193	DOUGLAS, JOE
3389	LATIOLAIS, CHRIS A

Target Street

✓

Cross Street

-

Source

Cole Information

I 10 FRONTAGE HWY

1992

1091 DUPLECHIN, GERALD
1173 MCMICHAEL, MYRTIE

Louisiana Department of Environmental Quality
FIELD INTERVIEW FORM

Agency Interest #:	73135	Inspection Date:	10/16/2025	Time of Arrival:	10:55 AM
		Departure Date:	10/16/2025	Time of Departure:	11:55 AM
Facility Name:	Landry's Cajun Texaco	Phone #:	(337) 667-6301		
Location:	2942A Grand Point Highway Breaux Bridge, LA 70517	Parish Name:	St. Martin		
Mailing Address:	2942A Grand Point Highway, Breaux Bridge, LA 70517				
Facility Representative:	Shawn King (Jones Environmental, Inc.)	Title:	Professional Geologist		

Inspection Type: CEI Program Involved: UST

Inspector's Observations: (e.g. Areas and Equipment Inspected, Problems, Deficiencies, Remarks, Verbal Commitments from Facility Representatives)

An amended UST-REG form was received by the Department on 4/01/20.

Tank ID #15144 has been in temporary closure since 8/08/25. Passing monthly CSLD results for this tank were achieved from 11/11/22 - 7/31/25. If this UST system is temporarily closed for three months or more, owners and operators shall leave the vent line open and functioning, cap and secure all other lines, pumps, manways, and ancillary equipment, and submit a completed copy of the UST-REG form to the Department. This tank was gauged during the CEI, and this tank contained less than one inch of product. The tank fill cap was relocked after gauging. Corrosion protection has been maintained on this tank system in temporary closure; the last CP Survey was conducted on 9/04/25 by Coastal Testing, Inc.

The site failed to conduct TTT every 12 months on the four steel tanks that were more than ten years old when the ICS CP was installed and no tank integrity assessment documentation exists. The previous TTT were conducted on 3/16/23 by Coastal Testing, Inc. These deficiencies for Tank ID #'s 15142, 15143, and 15145 were corrected via the TTT conducted on 10/16/25 by Coastal Testing, Inc. This deficiency for Tank ID #15144 was corrected via the placement of this tank in temporary closure on 9/04/25.

The site failed to ensure the ATG console and probes were inspected for proper operation at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. These deficiencies for Tank ID #'s 15142, 15143, and 15145 were corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc. This deficiency for Tank ID #15144 was corrected via the placement of this tank in temporary closure on 9/04/25.

The site failed to conduct ALLD performance testing and LTT on the pressurized lines at least once every twelve months. The previous ALLD performance tests and LTT were conducted on 3/16/23 by Coastal Testing, Inc. These deficiencies for Tank ID #'s 15142, 15143, and 15145 were corrected via the ALLD performance tests and LTT conducted on 9/04/25 by Coastal Testing, Inc. This deficiency for Tank ID #15144 was corrected via the placement of this tank in temporary closure on 9/04/25. These are repeat violations.

The site failed to inspect the shear valves on each dispenser at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. These deficiencies were corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc.

The site failed to test the spill prevention equipment (spill bucket) for each tank at least once every three years to ensure the equipment is liquid tight by using vacuum, pressure, or liquid testing. The previous tests were conducted on 3/30/20 by Coastal Testing, Inc. These deficiencies for Tank ID #'s 15142, 15143, and 15145 were corrected via the tests conducted on 9/04/25 by Coastal Testing, Inc. This deficiency for Tank ID #15144 was corrected via the placement of this tank in temporary closure on 9/04/25.

The site failed to inspect the overfill prevention equipment (drop device) for each tank at least once every three years to ensure that the overfill prevention is set to activate at the correct level. The previous inspections were conducted on 3/30/20 by Coastal Testing, Inc. These deficiencies for Tank ID #'s 15142, 15143, and 15145 were corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc. This

NOTE: The information contained on this form reflects only the preliminary observations of the inspector(s). It should not be interpreted as a final determination by the Department of Environmental Quality or any of its officers or personnel as to any matter, including, but not limited to, a determination of compliance or lack thereof by the facility operator with any requirements of statutes regulations or permits. Each day of non-compliance constitutes a separate violation of the regulations and/or the Louisiana Environmental Quality Act.

Louisiana Department of Environmental Quality
FIELD INTERVIEW FORM

Agency Interest #: 73135 Inspection Date: 10/16/2025 Time of Arrival: 10:55 AM
Departure Date: 10/16/2025 Time of Departure: 11:55 AM

Facility Name: Landry's Cajun Texaco Phone #: (337) 667-6301

deficiency for Tank ID #15144 was corrected via the placement of this tank in temporary closure on 9/04/25.

Areas of Concern	Explanation	Resolved?
To Be Determined		

Photos Taken? YES NO X Samples Taken? YES NO (Attach Chain-of-Custody)

Signature

Received by: Signature: Title: Class A/B Operator

Print Name: Shawn King (Jones Environmental, Inc.)
(NOTE: Signature DOES NOT indicate agreement with Inspector's Notes)

Inspector(s): Steve Luman Attachments:
steveluman@gmail.com

NOTE: The information contained on this form reflects only the preliminary observations of the inspector(s). It should not be interpreted as a final determination by the Department of Environmental Quality or any of its officers or personnel as to any matter, including, but not limited to, a determination of compliance or lack thereof by the facility operator with any requirements of statutes regulations or permits. Each day of non-compliance constitutes a separate violation of the regulations and/or the Louisiana Environmental Quality Act.



STATE OF LOUISIANA

DEPARTMENT OF ENVIRONMENTAL QUALITY
OFFICE OF ENVIRONMENTAL ASSESSMENT

October 21, 2025

Rozina Amlani
Landry's Cajun Texaco
2942A Grand Point Highway
Breaux Bridge, LA 70517

RE: NOTICE OF CORRECTED DEFICIENCY
Landry's Cajun Texaco, **Agency Interest # 73135**
2942A Grand Point Highway
Breaux Bridge, LA 70517 AR
ACTIVITY NUMBER: INS20260001

Dear Rozina Amlani:

On or about October 16, 2025, an inspection of the above referenced facility was conducted to determine compliance with the Louisiana Environmental Quality Act and supporting regulations. The following area of concern was noted in the inspection report and/or subsequent file review:

The following violation(s) was(were) noted during the inspection. These violation(s) are resolved and / or require no further action:

Regulation: 303.E.3.b.vi

Violation Description:

The respondent failed to perform an annual tank tightness test on a tank that was greater than 10 years old when corrosion protection was installed and no tank integrity assessment documentation exists.

Required Corrective Action:

This violation has been corrected.

Inspector Comment: *The site failed to conduct TTT every 12 months on this steel tank that was more than ten years old when the ICS CP was installed and no tank integrity assessment documentation exists. The previous TTT was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the TTT conducted on 10/16/25 by Coastal Testing, Inc.*

Applies to: Tank #15142(LO-ETH)(9994 gals), Tank #15145(DIES)(9994 gals), Tank #15143(PREM)(9994 gals)

Regulation: 511.A.1.b

Violation Description:

The respondent failed to ensure the spill containment device is double-walled and the interstice is

monitored monthly or the primary containment is tested every 3 years.

Required Corrective Action:

This violation has been corrected.

Applies to: Tank #15145(DIES)(9994 gals) (Inspector Comment: *The site failed to test the spill prevention equipment (spill bucket) for this tank at least once every three years to ensure the equipment is liquid tight by using vacuum, pressure, or liquid testing. The previous test was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the test conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15143(PREM)(9994 gals) (Inspector Comment: *The site failed to test the spill prevention equipment (spill bucket) for this tank at least once every three years to ensure the equipment is liquid tight by using vacuum, pressure, or liquid testing. The previous test was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the test conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15142(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to test the spill prevention equipment (spill bucket) for this tank at least once every three years to ensure the equipment is liquid tight by using vacuum, pressure, or liquid testing. The previous test was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the test conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15144(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to test the spill prevention equipment (spill bucket) for this tank at least once every three years to ensure the equipment is liquid tight by using vacuum, pressure, or liquid testing. The previous test was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the test conducted on 9/04/25 by Coastal Testing, Inc. This deficiency was corrected via the placement of this tank in temporary closure on 9/04/25.*)

Regulation: 511.A.3

Violation Description:

The respondent failed to ensure the overfill device is inspected every 3 years.

Required Corrective Action:

This violation has been corrected.

Applies to: Tank #15144(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to inspect the overfill prevention equipment (drop device) for this tank at least once every three years to ensure that the overfill prevention is set to activate at the correct level. The previous inspection was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the placement of this tank in temporary closure on 9/04/25.*), Tank #15143(PREM)(9994 gals) (Inspector Comment: *The site failed to inspect the overfill prevention equipment (drop device) for this tank at least once every three years to ensure that the overfill prevention is set to activate at the correct level. The previous inspection was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the inspection conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15142(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to inspect the overfill prevention equipment (drop device) for this tank at least once every three years to ensure that the overfill prevention is set to activate at the correct level. The previous inspection was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the inspection conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15145(DIES)(9994 gals) (Inspector

Comment: The site failed to inspect the overfill prevention equipment (drop device) for this tank at least once every three years to ensure that the overfill prevention is set to activate at the correct level. The previous inspection was conducted on 3/30/20 by Coastal Testing, Inc. This deficiency was corrected via the inspection conducted on 9/04/25 by Coastal Testing, Inc.)

Regulation: 515.A.1

Violation Description:

The respondent failed to ensure the shear valves were inspected every 12 months.

Required Corrective Action:

This violation has been corrected.

Inspector Comment: *The site failed to inspect the shear valves on this dispenser at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc.*

Applies to:Dispenser #3/4, Dispenser #5/6, Dispenser #1/2

Regulation: 701.B.1

Violation Description:

The respondent failed to conduct a test of the operation of the automatic line leak detector every twelve months.

Required Corrective Action:

This violation has been corrected.

Applies to:Tank #15145(DIES)(9994 gals) (Inspector Comment: *The site failed to conduct ALLD performance testing on this pressurized line at least once every twelve months. The previous ALLD performance test was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the ALLD performance test conducted on 9/04/25 by Coastal Testing, Inc. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*), Tank #15144(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to conduct ALLD performance testing on this pressurized line at least once every twelve months. The previous ALLD performance test was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the ALLD performance test conducted on 9/04/25 by Coastal Testing, Inc. This deficiency was corrected via the placement of this tank in temporary closure on 9/04/25. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*), Tank #15143(PREM)(9994 gals) (Inspector Comment: *The site failed to conduct ALLD performance testing on this pressurized line at least once every twelve months. The previous ALLD performance test was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the ALLD performance test conducted on 9/04/25 by Coastal Testing, Inc. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*), Tank #15142(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to conduct ALLD performance testing on this pressurized line at least once every twelve months. The previous ALLD performance test was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the ALLD performance test conducted on 9/04/25 by Coastal*

Testing, Inc. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.)

Regulation: 703.A.2.d.i

Violation Description:

Failure to test the tank release detection equipment annually in accordance with 703.A.2.d.i.

Required Corrective Action:

This violation has been corrected.

Applies to: Tank #15144(LO-ETH)(9994 gals) (Inspector Comment: *Prior to temporary closure, the site failed to ensure the ATG console and probe were inspected for proper operation at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc. This deficiency was corrected via the placement of this tank in temporary closure on 9/04/25.*), Tank #15142(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to ensure the ATG console and probe were inspected for proper operation at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15145(DIES)(9994 gals) (Inspector Comment: *The site failed to ensure the ATG console and probe were inspected for proper operation at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc.*), Tank #15143(PREM)(9994 gals) (Inspector Comment: *The site failed to ensure the ATG console and probe were inspected for proper operation at least once every twelve months. The previous inspections were conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the inspections conducted on 9/04/25 by Coastal Testing, Inc.*)

Regulation: 703.B.2.a.i.(b)

Violation Description:

The respondent failed to conduct a line tightness test every 12 months in accordance with LAC 33:XI.701.B.2, or conduct monthly monitoring in accordance with LAC 33:XI.701.B.3.

Required Corrective Action:

This violation has been corrected.

Applies to: Tank #15142(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to conduct LTT on this pressurized line at least once every twelve months. The previous LTT was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the LTT conducted on 9/04/25 by Coastal Testing, Inc. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*), Tank #15144(LO-ETH)(9994 gals) (Inspector Comment: *The site failed to conduct LTT on this pressurized line at least once every twelve months. The previous LTT was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the LTT conducted on 9/04/25 by Coastal Testing, Inc. This deficiency was corrected via the placement of this tank in temporary closure on 9/04/25. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*), Tank #15145(DIES)(9994 gals)

(Inspector Comment: *The site failed to conduct LTT on this pressurized line at least once every twelve months. The previous LTT was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the LTT conducted on 9/04/25 by Coastal Testing, Inc. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*), Tank #15143(PREM)(9994 gals) (Inspector Comment: *The site failed to conduct LTT on this pressurized line at least once every twelve months. The previous LTT was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the LTT conducted on 9/04/25 by Coastal Testing, Inc. This is a repeat violation which was previously cited during the CEI conducted on 11/11/22.*)

Regulation: 903.A

Violation Description:

The respondent failed to perform an annual tank tightness test on a tank that was greater than 10 years old when corrosion protection was installed and no tank integrity assessment documentation exists as specified by LAC 33:XI.303.E.3.b.vi.

Required Corrective Action:

This violation has been corrected.

Inspector Comment: *Prior to temporary closure, the site failed to conduct TTT every 12 months on this steel tank that was more than ten years old when the ICS CP was installed and no tank integrity assessment documentation exists. The previous TTT was conducted on 3/16/23 by Coastal Testing, Inc. This deficiency was corrected via the placement of this tank in temporary closure on 9/04/25.*

Applies to: Tank #15144(LO-ETH)(9994 gals)

The area of concern has been addressed during or shortly after the inspection. The LDEQ herein notes your timely response in correcting the subject area of concern.

This Notice of Corrected Deficiency will be placed in the official agency record. This Notice of Corrected Deficiency refers only to the above-mentioned area of concern. It does not prevent nor hinder LDEQ from seeking penalties and compliance for this or other deficiencies discovered by this inspection.

To reduce document-handling time, please refer to the Agency Interest Number and Activity Number listed at the top of the page on all correspondence that references this notice.

If you have any questions or comments regarding this matter, please contact Jessica Holland at 337-262-5599 or Jessica.Holland@la.gov.

Sincerely,

A handwritten signature in blue ink that reads "Jessica Holland". The signature is written in a cursive, flowing style.

Jessica Holland
UST Prevention Supervisor
Underground Storage Tank Division

c: Imaging Operations – UST



COMPLIANCE INSPECTION REPORT FOR UNDERGROUND STORAGE TANKS

Document Date: 7/7/2025 12:50 PM

Inspection Result: Passed

Partial Inspection: No

Inspection Date: 7/7/2025

Arrive and Depart Times: 10:45 AM-11:45 AM

Additional Records Requested: No

Stage 2 Decommissioned: N/A

Facility ID:	100130	Inspector	Steve Luman
Facility Name	Bayou Belle Truck Stop & Casino	Insp. Type	Compliance
Facility Address	2924 Grand Point Highway Breaux Bridge, LA 70517 Parish: St. Martin Region: Acadiana	Location	30.31926574, -91.82930332

CONTACTS

Contact Type	Contact Information
UST Billing Party (ORGANIZATION RELATION)	Allison G. Enterprise, LLC Work: (337) 667-6579 Address: 2924 Grand Point Highway Breaux Bridge, LA 70517
Class A/B Operator	Jessie Spence Fax: (225) 664-6528 Cell: (225) 445-1171 Email: ca.jspence@gmail.com Address: 10144 Autumn Court Denham Springs, LA 70726 (Was present at inspection)
Underground Storage Tank Contact (PERSON RELATION)	Suleman Bashzr Work: (337) 667-6579 Address: 2924 Grand Point Highway Breaux Bridge, LA 70517 (Responsible Party)

Operator Training	
Is this a manned facility?	Yes
Have the individuals designated as class A, B, and C been trained and certified in accordance with the operator training regulations and applicable deadlines listed below (603.A.2)?	Yes
Have the certified class A or B operator(s) for this facility met the 3 year re-training requirement? (609.A)	Yes
Were certified class C operator(s) re-trained prior to assuming the responsibility at a facility owned by a different UST owner that did not provide their initial training? (609.B)	N/A
Training certificate for each person who is currently serving as a class A, B, or C operator? (611.A.1)	Yes
Posted site-specific emergency procedures, location of emergency shut-off devices, and appropriate emergency contact telephone numbers in a prominent area easily visible to the class C operator? (611.A.2)	Yes

Walkthrough Inspections	
Current Annual Walkthrough Inspection Date	8/7/2024
Previous Annual Walkthrough Inspection Date	8/14/2023

Walkthrough Inspections	
3rd Annual Walkthrough Inspection Date	9/6/2022
Walkthrough inspections performed for the current month?	Yes
Walkthrough inspections performed every month?	Yes
Walkthrough inspection type	Min. Reg. Requirements or DEQ Checklist (513.A.1)
Monthly walkthrough inspections performed correctly?	Yes
Are walkthrough inspection records maintained as specified in 513.B?	Yes
Walkthrough inspections comment	The monthly and annual walkthrough inspections are conducted by Compliance Assistance, LLC.

FINANCIAL RESPONSIBILITY

Is Financial Responsibility Required? Yes

COMMENTS: LA MFUSTTF

Evidence of all financial assurance mechanisms used to demonstrate financial responsibility under Chapter 11 maintained? (1133.A)	Yes
Does the facility have a current registration certificate? (1133.B.5 or 307.F)	Yes

INSPECTOR COMMENTS

An amended UST-REG form was received by the Department on 2/26/20.

TANK INFORMATION

Tanks	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
TEMPO subject item #	3	2	1
Tank registered with LA DEQ? (301.A.1 or 301.B or 301.C.1)	Yes	Yes	Yes
Capacity	4000	15000	15000
Tank Status	Active	Active	Active
Tank Construction Material	Composite (Steel w/Fiberglass)	Composite (Steel w/Fiberglass)	Composite (Steel w/Fiberglass)
Tank Containment (303.C)	None	None	None
GPS coordinates of tank	GPS:30.31949 892, -91.82925649	GPS:30.31948 502, -91.82927259	GPS:30.31951 004, -91.82930162
Tank Comment	ACT-100®	ACT-100®	ACT-100®
Install Date	7/12/2002	7/12/2002	7/12/2002
In-Service Date	12/12/2002	12/12/2002	12/12/2002

COMPARTMENT/PIPING INFORMATION

Compartments	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Capacity	4000	15000	15000
Compartment status	Active	Active	Active
Product	Gasoline – Super/Prem	Diesel	Gasoline – Regular
Is used for emergency generator only?	No	No	No
Is the substance stored compatible with the materials or liner in the UST system? (505.A)	Yes	Yes	Yes
Is a compatibility determination required (10% ethanol, 20% biodiesel, or other)?	No	No	No
Piping installed (or 100% replaced) date	9/12/2002	9/12/2002	9/12/2002
Pipe type	Pressure	Pressure	Pressure
Pipe construction material	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic
Pipe containment method (303.D.2.f(new install), 303.D.2.g(>25% repair) or 303.D.2.h(replacement))	None	None	None

DISPENSER INFORMATION

Dispensers	Dispenser #1(1/2)	Dispenser #2(3/4)	Dispenser #3(5/6)	Dispenser #4(7/8)
Dispenser ID	1/2	3/4	5/6	7/8
Compartments	55684(LO-ETH), 55685(DIES), 55686(PREM)	55684(LO-ETH), 55686(PREM)	55684(LO-ETH), 55686(PREM)	55684(LO-ETH), 55686(PREM)
Was the dispenser installed or replaced after 12/20/2008?	Yes	Yes	Yes	Yes
Were any components below the shear valve replaced after 12/20/2008?	No	No	No	No
Is a dispenser containment sump present?	Yes	Yes	Yes	Yes
Shear valves installed/anchored correctly? (303.D.6.a OR 303.E.6 for existing systems)	Yes	Yes	Yes	Yes
Inspection type (515.A.1)	PEI RP 1200	PEI RP 1200	PEI RP 1200	PEI RP 1200
Inspection date (515.A.1)	6/6/2025	6/6/2025	6/6/2025	6/6/2025
Inspection records maintained for 3 years per 515.C? (509.B.11)	Yes	Yes	Yes	Yes

Dispensers	Dispenser #5(9/10)	Dispenser #6(11)	Dispenser #7(11S/12)	Dispenser #8(12S/13)
Dispenser ID	9/10	11	11S/12	12S/13

Dispensers	Dispenser #5(9/10)	Dispenser #6(11)	Dispenser #7(11S/12)	Dispenser #8(12S/13)
Compartments	55684(LO-ETH), 55686(PREM)	55685(DIES)	55685(DIES)	55685(DIES)
Was the dispenser installed or replaced after 12/20/2008?	Yes	Yes	Yes	Yes
Were any components below the shear valve replaced after 12/20/2008?	No	No	No	No
Is a dispenser containment sump present?	Yes	Yes	Yes	Yes
Shear valves installed/anchored correctly? (303.D.6.a OR 303.E.6 for existing systems)	Yes	Yes	Yes	Yes
Inspection type (515.A.1)	PEI RP 1200	PEI RP 1200	PEI RP 1200	PEI RP 1200
Inspection date (515.A.1)	6/6/2025	6/6/2025	6/6/2025	6/6/2025
Inspection records maintained for 3 years per 515.C? (509.B.11)	Yes	Yes	Yes	Yes

Dispensers	Dispenser #9(13S/14)			
Dispenser ID	13S/14			
Compartments	55685(DIES)			
Was the dispenser installed or replaced after 12/20/2008?	Yes			
Were any components below the shear valve replaced after 12/20/2008?	No			
Is a dispenser containment sump present?	Yes			
Shear valves installed/anchored correctly? (303.D.6.a OR 303.E.6 for existing systems)	Yes			
Inspection type (515.A.1)	PEI RP 1200			
Inspection date (515.A.1)	6/6/2025			
Inspection records maintained for 3 years per 515.C? (509.B.11)	Yes			

CORROSION PROTECTION

Tank Corrosion Protection	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Tank construction material	Composite (Steel w/Fiberglass)	Composite (Steel w/Fiberglass)	Composite (Steel w/Fiberglass)
Tank containment	None	None	None
Corrosion protection method (303.E.1)	Steel-FRP Composite	Steel-FRP Composite	Steel-FRP Composite
Dielectric coating?	Yes	Yes	Yes

Tank Corrosion Protection	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
CP requirement	None	None	None
Has the tank been repaired?	No	No	No

Pipe Corrosion Protection	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Pipe construction material	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic
Pipe containment method	None	None	None
Piping External Corrosion Protection Date	9/12/2002	9/12/2002	9/12/2002
CP method	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic
Dielectric coating	N/A	N/A	N/A
Is piping (in contact with soil, backfill, or water) designed, constructed, and protected to prevent corrosion? (303.D.2)	Yes	Yes	Yes
CP requirement	CP Testing of Metal Fittings	CP Testing of Metal Fittings	CP Testing of Metal Fittings
Current CP test date (503.A.2.a)	6/8/2023	6/8/2023	6/8/2023
Previous CP test date (503.A.2.a)	7/24/2020	7/24/2020	7/24/2020
Is documentation of CP tests available? (509.B.2)	Yes	Yes	Yes
Are inspections/tests by qualified testers? (503.A.2)?	Yes	Yes	Yes
Does the inspection meet the requirements of code of practice developed by a nationally recognized association? (503.A.2.b)?	Yes	Yes	Yes

Tank Top Components Corrosion Protection	Tank 55686(PRE M)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Pipe construction material	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic	Fiberglass-Reinforced Plastic
Piping sump present?	Yes	Yes	Yes
Flex connector, piping extensions, and/or other metal fittings present?	STP Head, Other Metal, Flex Connector, Elbow, Ball Valve	STP Head, Other Metal, Flex Connector, Elbow, Ball Valve	STP Head, Other Metal, Flex Connector, Elbow, Ball Valve
Is soil, backfill, or water currently or periodically in contact with metal components?	Yes	Yes	Yes
Are metal components protected from corrosion?	Yes	Yes	Yes

Tank Top Components Corrosion Protection	Tank 55686(PRE M)	Tank 55685(DIES)	Tank 55684(LO- ETH)
Metal components corrosion protection method	Sacrificial Anodes	Sacrificial Anodes	Sacrificial Anodes

Dispenser Corrosion Protection	Dispenser #1(1/2)	Dispenser #2(3/4)	Dispenser #3(5/6)	Dispenser #4(7/8)
Dispenser sump present?	Yes	Yes	Yes	Yes
Flex connector, piping extensions, and/or other metal fittings present?	Flex Connector	Flex Connector	Flex Connector	Flex Connector
Is soil, backfill, or water currently or periodically in contact with metal components?	Yes	Yes	Yes	Yes
Are flex connectors, piping extensions and/or other metal fittings protected from corrosion?	Yes	Yes	Yes	Yes
Corrosion protection method	Sacrificial Anodes	Sacrificial Anodes	Sacrificial Anodes	Sacrificial Anodes

Dispenser Corrosion Protection	Dispenser #5(9/10)	Dispenser #6(11)	Dispenser #7(11S/12)	Dispenser #8(12S/13)
Dispenser sump present?	Yes	Yes	Yes	Yes
Flex connector, piping extensions, and/or other metal fittings present?	Flex Connector	Flex Connector	Flex Connector	Flex Connector
Is soil, backfill, or water currently or periodically in contact with metal components?	Yes	Yes	Yes	Yes
Are flex connectors, piping extensions and/or other metal fittings protected from corrosion?	Yes	Yes	Yes	Yes
Corrosion protection method	Sacrificial Anodes	Sacrificial Anodes	Sacrificial Anodes	Sacrificial Anodes

Dispenser Corrosion Protection	Dispenser #9(13S/14)			
Dispenser sump present?	Yes			
Flex connector, piping extensions, and/or other metal fittings present?	Flex Connector			
Is soil, backfill, or water currently or periodically in contact with metal components?	Yes			
Are flex connectors, piping extensions and/or other metal fittings protected from corrosion?	Yes			
Corrosion protection method	Sacrificial Anodes			

SPILL/OVERFILL PREVENTION

Primary Fill Ports	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Are all deliveries less than 25 gallons?	No	No	No
Does tank compartment have a second fill?	No	No	No
Is spill prevention equipment provided? (303.E.1 if install < 12/12/88 otherwise 303.D.3.a.i)	Yes	Yes	Yes
Spill prevention installed date	9/12/2002	9/12/2002	9/12/2002
Is spill prevention equipment liquid tight at sides,bottom, and any penetrations? (303.D.3.a.i)	Yes	Yes	Yes
Is spill bucket free of liquid and debris?	Yes	Yes	Yes
Is the bucket double-walled with interstitial monitoring conducted once every 30 days ? (511.A.1.a)?	No	No	No
Triennial test type as required by 511.A.1.b (511.A)	PEI RP 1200	PEI RP 1200	PEI RP 1200
Triennial test date (511.A)	6/7/2024	6/7/2024	6/7/2024
Previous triennial test date (511.A)	6/11/2021	6/11/2021	6/11/2021
Monitoring or testing records maintained for 3 years per 511.C.1? (509.B.9)	Yes	Yes	Yes

Overfill Control	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Is an overfill device present? (303.D.3.a.ii)	Yes	Yes	Yes
Overfill type	Ball Float Vent Valve	Ball Float Vent Valve	Ball Float Vent Valve
Overfill installed date	9/12/2002	9/12/2002	9/12/2002
Alert the transfer operator when <=90 % full by restricting flow into the tank? (303.D.3.a.ii.(b))	Yes	Yes	Yes
Did an overfill event occur?	No	No	No
If a ball float valve was removed after 9/20/18, was the entire ball float assembly removed from the tank? (303.D.3.c)	N/A	N/A	N/A
Triennial test type (511.A.3)	PEI RP 1200	PEI RP 1200	PEI RP 1200
Triennial test date (511.A.3)	6/7/2024	6/7/2024	6/7/2024
Previous triennial test date (511.A.3)	6/11/2021	6/11/2021	6/11/2021
Monitoring or testing records maintained for 3 years per 511.C.1? (509.B.9)	Yes	Yes	Yes

RELEASE DETECTION

Tanks	Tank 55686(PR EM)	Tank 55685(DIE S)	Tank 55684(LO- ETH)
Primary release detection method Choose "None" if no RD conducted (703.A.1)	Automatic Tank Gauging	Automatic Tank Gauging	Automatic Tank Gauging

Tanks	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Tank diameter	96	96	96
Requirement	Monthly Monitoring	Monthly Monitoring	Monthly Monitoring
Capable of detecting a release from any portion of the tank that routinely contains product? (703.A.2.a)	Yes	Yes	Yes
Installed and calibrated in accordance with the manufacturer's instructions including routine maintenance, etc.? (703.A.2.b)	Yes	Yes	Yes
Meet the performance standards outlined in 703.A.2.c? (Check 3rd party certification against equipment or method present) (703.A.2.c)	Yes	Yes	Yes
Is there any tank RD equipment that requires annual function testing?	Yes	Yes	Yes
Current function test date	6/6/2025	6/6/2025	6/6/2025
Previous function test date	6/7/2024	6/7/2024	6/7/2024
3rd function test date	6/8/2023	6/8/2023	6/8/2023
Test Method	RP1200	RP1200	RP1200
Method followed properly	Yes	Yes	Yes
Equipment Tested	ATG console & probe	ATG console & probe	ATG console & probe
Most recent test result	Pass	Pass	Pass
Testing comments	conducted by Coastal Testing, Inc.	conducted by Coastal Testing, Inc.	conducted by Coastal Testing, Inc.
Has the tank been tightness tested recently?	No	No	No

Piping Catastrophic (3 GPH)	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Piping type	Pressure	Pressure	Pressure
Catastrophic leak (3 GPH) detection method Choose "None" if no LLD (703.B.2.a.i)	Automatic Line Leak Detectors	Automatic Line Leak Detectors	Automatic Line Leak Detectors
Requirement	Annual Function Check	Annual Function Check	Annual Function Check
Current LLD function check (701.B.1)	6/6/2025	6/6/2025	6/6/2025
Previous LLD function check	6/7/2024	6/7/2024	6/7/2024
3rd LLD function check	6/8/2023	6/8/2023	6/8/2023
Tested according to the manufacturer's requirements? (701.B.1.a)	Yes	Yes	Yes

Piping Catastrophic (3 GPH)	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Tested by simulating a release in order to determine if the system is fully operational and can detect leaks of 3gph at 10psi line pressure within 1 hour? (701.B.1.b)	Yes	Yes	Yes
Tested to ensure that the STP is not continuously running? (701.B.1.c)	Yes	Yes	Yes
Is the STP continuously running?	No	No	No
Most recent test result	Pass	Pass	Pass
Comments	Mechanical ALLD	Mechanical ALLD	Mechanical ALLD

Piping Periodic (.2 GPH)	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Periodic release detection method Choose "None" if no RD conducted (703.B.2.a.i.(b))	Line Tightness Testing	Line Tightness Testing	Line Tightness Testing
Requirement	Annual Line Tightness Test	Annual Line Tightness Test	Annual Line Tightness Test
Current LTT test (703.B.2.a.i.(b))	6/6/2025	6/6/2025	6/6/2025
Previous LTT test	6/7/2024	6/7/2024	6/7/2024
3rd LTT test	6/8/2023	6/8/2023	6/8/2023
Is LTT method capable of detecting a 0.1 gal/hr leak rate from any portion of the piping routinely containing product? (701.B.2)	Yes	Yes	Yes
Comments	conducted by Coastal Testing, Inc.	conducted by Coastal Testing, Inc.	conducted by Coastal Testing, Inc.

Piping Sumps	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Sump requirements	None	None	None
Tank top containment sump present?	Yes	Yes	Yes
Sump is liquid-tight at sides, bottom, and any penetrations? (303.D.5.b if installed after 12/20/2008)	No	No	No
Product visibly leaked/leaking into sump or soil?	No	No	No
Is a hydrostatic test required?	No	No	No

Dispensers	Dispenser #1(1/2)	Dispenser #2(3/4)	Dispenser #3(5/6)	Dispenser #4(7/8)
Sump requirements	None	None	None	None

Dispensers	Dispenser #1(1/2)	Dispenser #2(3/4)	Dispenser #3(5/6)	Dispenser #4(7/8)
Is a dispenser containment sump present?	Yes	Yes	Yes	Yes
Sump construction material	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic
Sump is liquid-tight at sides, bottom, and any penetrations? (303.D.4.b if installed after 12/20/2008)	No	No	No	No
Product visibly leaked/leaking into sump or soil?	No	No	No	No
Is a hydrostatic test required?	No	No	No	No

Dispensers	Dispenser #5(9/10)	Dispenser #6(11)	Dispenser #7(11S/12)	Dispenser #8(12S/13)
Sump requirements	None	None	None	None
Is a dispenser containment sump present?	Yes	Yes	Yes	Yes
Sump construction material	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic
Sump is liquid-tight at sides, bottom, and any penetrations? (303.D.4.b if installed after 12/20/2008)	No	No	No	No
Product visibly leaked/leaking into sump or soil?	No	No	No	No
Is a hydrostatic test required?	No	No	No	No

Dispensers	Dispenser #9(13S/14)			
Sump requirements	None			
Is a dispenser containment sump present?	Yes			
Sump construction material	Fiberglass Reinforced Plastic			
Sump is liquid-tight at sides, bottom, and any penetrations? (303.D.4.b if installed after 12/20/2008)	No			
Product visibly leaked/leaking into sump or soil?	No			
Is a hydrostatic test required?	No			

Release Detection Records	Tank 55686(PRE M)	Tank 55685(DIES)	Tank 55684(LO-ETH)
Does the facility maintain all written performance claims provided by the RD vendor throughout the operating life of the equipment? (509.B.4)	Yes	Yes	Yes
Are all tank tightness-testing records retained until the next test is conducted? (509.B.4)	Yes	Yes	Yes
Are schedules of required calibration and maintenance for RD equipment retained for 5 years from date of installation? (509.B.4)	Yes	Yes	Yes
Are results of the annual operation and maintenance tests retained for 3 years as required by 705.A.4? (509.B.4)	Yes	Yes	Yes

Automatic Tank Gauge	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
2025 Jul	Pass	Pass	Pass
2025 Jun	Pass	Pass	Pass
2025 May	Pass	Pass	Pass
2025 Apr	Pass	Pass	Pass
2025 Mar	Pass	Pass	Pass
2025 Feb	Pass	Pass	Pass
2025 Jan	Pass	Pass	Pass
2024 Dec	Pass	Pass	Pass
2024 Nov	Pass	Pass	Pass
2024 Oct	Pass	Pass	Pass
2024 Sep	Pass	Pass	Pass
2024 Aug	Pass	Pass	Pass
2024 Jul	Pass	Pass	Pass
2024 Jun	Pass	Pass	Pass
2024 May	Pass	Pass	Pass
2024 Apr	Pass	Pass	Pass
2024 Mar	Pass	Pass	Pass
2024 Feb	Pass	Pass	Pass
2024 Jan	Pass	Pass	Pass
2023 Dec	Pass	Pass	Pass
2023 Nov	Pass	Pass	Pass
2023 Oct	Pass	Pass	Pass
2023 Sep	Pass	Pass	Pass
2023 Aug	Pass	Pass	Pass
2023 Jul	Pass	Pass	Pass
2023 Jun	Pass	Pass	Pass
2023 May	Pass	Pass	Pass
2023 Apr	Pass	Pass	Pass
2023 Mar	Pass	Pass	Pass
2023 Feb	Pass	Pass	Pass
2023 Jan	Pass	Pass	Pass
2022 Dec	Pass	Pass	Pass
2022 Nov	Pass	Pass	Pass
2022 Oct	Pass	Pass	Pass

Automatic Tank Gauge	Tank 55686(PREM)	Tank 55685(DIES)	Tank 55684(LO-ETH)
2022 Sep	Pass	Pass	Pass
2022 Aug	Pass	Pass	Pass

ATG Details	Tank 55686(PRE M)	Tank 55685(DIES)	Tank 55684(LO-ETH)
ATG Make/Model?	Veeder-Root/Gilbarco/Marconi:EMC BasicPAO2 65XXX0000	Veeder-Root/Gilbarco/Marconi:EMC BasicPAO2 65XXX0000	Veeder-Root/Gilbarco/Marconi:EMC BasicPAO2 65XXX0000
ATG Probe Type?	Magnetostri ctive Probe	Magnetostri ctive Probe	Magnetostri ctive Probe
ATG Test Mode?	Continuous	Continuous	Continuous
Is the ATG capable of detecting a leak of 0.2 gal/hr leak rate? (701.A.4.a.i)	Yes	Yes	Yes
Does the ATG meet the inventory control requirements of LAC 33:XI.701.A.1.b and 701.A.1.f or another test of equivalent performance? (701.A.4.a.ii.)	Yes	Yes	Yes
The time, date, or period covered for the test? (705.A.2.d.i.(a))	Yes	Yes	Yes
The tank and / or piping identifier? (705.A.2.d.i.(b))	Yes	Yes	Yes
A qualitative result of pass, fail, inconclusive, or alarm code where applicable? (705.A.2.d.i.(c))	Yes	Yes	Yes
Other information needed to verify compliance with LAC 33:XI.703.A.2.c as applicable to the equipment and method used? (705.A.2.d.i.(e))	Yes	Yes	Yes


SUSPECTED RELEASE

Release	
Has the facility reported, investigated, and cleaned-up any spills and overfills as required by 713.A (501.C)	Yes

ADDITIONAL PAPERWORK REQUIREMENTS	
Has an updated UST-REG form been submitted within 30 days of any changes of any of the items reflected on their most current registration forms? (301.C.2)	N/A
Has an amended registration form been submitted within 30 days of acquiring a UST? (301.C.5)	N/A
Is the most current registration forms (UST-REG-01, UST-REG-02, or UST-REG) kept on-site or at the nearest staffed facility? (509.B.5)	Yes
Is a copy of the current registration certificate kept on-site or at the nearest staffed facility? (509.B.5)	Yes

ADDITIONAL PAPERWORK REQUIREMENTS	
Was the facility able to provide the records upon request by the inspector? (509.C)	Yes
Is documentation of tanks and piping construction as well as leak detection, corrosion protection, and spill and overfill equipment provided? (509.B.6)	Yes
Was the owner or operator provided a UST-REG form to be submitted within 60 days of the inspection date? {301.C.3}	Yes
Has a UST-REG form been submitted to the department within 60 days of the inspection date or before 9/20/2021, whichever comes first? {301.C.3}	Yes

SITE DIAGRAM




AREAS OF CONCERN

No issues identified at this time

PHOTOS



Geoportal Map



DISCLAIMER: Every reasonable effort has been made to assure the accuracy of the parcel data presented. The Saint Martin Parish Assessor makes no warranties, express or implied, regarding the completeness, reliability or suitability of the site data and assumes no liability associated with the use or misuse of said data. The Assessor retains the right to make changes and update data on this site at anytime without notification. The parcel data on the base map is used to locate, identify and inventory parcels of land in Saint Martin Parish for assessment purposes only and is not to be used or interpreted as a legal survey or legal document. Additional data layers not originating in the Assessors Office are also presented for informational purposes only. Before proceeding in any legal matter, all data should be verified by contacting the appropriate parish or municipal office.

0 0.15 0.3mi

Appendix C: Regulatory Database Report



Henderson I-10 Site

I-10

Breaux Bridge, LA 70517

Inquiry Number: 8156261.2s

October 29, 2025

The EDR Radius Map™ Report with GeoCheck®



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

TABLE OF CONTENTS

LIGHTBOX LIVE

Open [LightBox Live](http://www.web.edrnet.com/ordering/switchboard/login.aspx?s=goto_lightbox&pguid=3E6BBDB7-8CD6-4EFF-8DC7-177A03F63B6F) to access data, tools, and advanced analytics in one online platform.

http://www.web.edrnet.com/ordering/switchboard/login.aspx?s=goto_lightbox&pguid=3E6BBDB7-8CD6-4EFF-8DC7-177A03F63B6F

<u>SECTION</u>	<u>PAGE</u>
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	8
Orphan Summary	133
Government Records Searched/Data Currency Tracking	GR-1

GEOCHECK ADDENDUM

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting SSURGO Soil Map	A-5
Physical Setting Source Map	A-10
Physical Setting Source Map Findings	A-12
Physical Setting Source Records Searched	PSGR-1

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, LLC. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. This Report is provided on an "AS IS", "AS AVAILABLE" basis. **NO WARRANTY EXPRESS OR IMPLIED IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, LLC AND ITS SUBSIDIARIES, AFFILIATES AND THIRD PARTY SUPPLIERS DISCLAIM ALL WARRANTIES, OF ANY KIND OR NATURE, EXPRESS OR IMPLIED, ARISING OUT OF OR RELATED TO THIS REPORT OR ANY OF THE DATA AND INFORMATION PROVIDED IN THIS REPORT, INCLUDING WITHOUT LIMITATION, ANY WARRANTIES REGARDING ACCURACY, QUALITY, CORRECTNESS, COMPLETENESS, COMPREHENSIVENESS, SUITABILITY, MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, TITLE, NON-INFRINGEMENT, MISAPPROPRIATION, OR OTHERWISE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, LLC OR ITS SUBSIDIARIES, AFFILIATES OR THIRD PARTY SUPPLIERS BE LIABLE TO ANYONE FOR ANY DIRECT, INCIDENTAL, INDIRECT, SPECIAL, CONSEQUENTIAL OR OTHER DAMAGES OF ANY TYPE OR KIND (INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS, LOSS OF USE, OR LOSS OF DATA) INFORMATION PROVIDED IN THIS REPORT.** Any analyses, estimates, ratings, environmental risk levels, or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only an assessment performed by a qualified environmental professional can provide findings, opinions or conclusions regarding the environmental risk or conditions in, on or at any property.

Copyright 2025 by Environmental Data Resources, LLC. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, LLC, or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, LLC or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E1527 - 21), the ASTM Standard Practice for Environmental Site Assessments for Forestland or Rural Property (E2247 - 23), the ASTM Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process (E1528 - 22) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

I-10
BREAUX BRIDGE, LA 70517

COORDINATES

Latitude (North):	30.3171960 - 30° 19' 1.90"
Longitude (West):	91.8355190 - 91° 50' 7.86"
Universal Tranverse Mercator:	Zone 15
UTM X (Meters):	611958.7
UTM Y (Meters):	3354327.2
Elevation:	20 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	16395679 CECILIA, LA
Version Date:	2020

AERIAL PHOTOGRAPHY IN THIS REPORT

Portions of Photo from:	20230602, 20230726
Source:	USDA

MAPPED SITES SUMMARY

Target Property Address:
I-10
BREAUX BRIDGE, LA 70517

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
1	HENDERSON TRAVEL PLA	2996 GRAND POINT HWY	HIST LUST, UST		TP
A2	BAYOU BELLE TRUCK ST	2924 GRAND POINT HWY	UST, SPILLS, NPDES	Higher	102, 0.019, ENE
A3	BAYOU BELLE TRUCK ST	2924 GRAND POINT HWY	EDR Hist Auto	Higher	102, 0.019, ENE
A4	O'REILLY AUTO PARTS	2889 GRAND POINT HWY	RCRA-VSQG, ECHO	Higher	231, 0.044, ENE
B5	LANDRY'S CAJUN TEXAC	2942 A GRAND POINT H	UST	Higher	234, 0.044, ESE
B6	LANDRYS CAJUN TEXACO	2942-A GRAND POINT H	EDR Hist Auto	Higher	234, 0.044, ESE
C7	LITTLE CAPITOL OF LO	2939 GRAND POINT HWY	UST, NPDES	Higher	290, 0.055, East
C8	LITTLE CAPITOL OF LO	2939 GRAND POINT HWY	EDR Hist Auto	Higher	290, 0.055, East
C9	DIESI'S LITTLE CAPIT	2939 GRAND POINT HWY	HIST LUST, SPILLS	Higher	290, 0.055, East
D10	FEDEX FREIGHT	2937 GRAND POINT HWY	E MANIFEST	Higher	526, 0.100, East
D11	LITTLE CAPITOL OF LO	2937 GRAND POINT HWY	EDR Hist Auto	Higher	526, 0.100, East
D12	FEDEX FREIGHT INC	2937 GRAND POINT HWY	RCRA-SQG	Higher	526, 0.100, East
13	HENDERSON TRAVEL PLA	2996 GRAND POINT HWY	LUST, AUL, SPILLS, NPDES, REM	Lower	741, 0.140, SE
14	CECILIA FIELD COMMUN	ON HWY 347 1.3 MI S	DEL SHWS, ICIS, US AIRS, AIRS, REM	Higher	757, 0.143, West
15	CECILIA FIELD COMMUN	ON HWY 347 OFF MELVI	PFAS ECHO	Higher	957, 0.181, West
E16	VED'S 5 LLC	3002 GRAND POINT HWY	UST	Higher	1070, 0.203, SSE
E17	VED'S 5 LLC	3002 GRAND POINT HWY	LUST, SPILLS, REM	Higher	1070, 0.203, SSE
F18	HENDERSON I-10 EXXON	2987 GRAND POINT HWY	LUST, AUL, SPILLS, NPDES, REM	Higher	1073, 0.203, SE
F19	HENDERSON I-10 EXXON	2987 GRAND POINT	RCRA-VSQG, UST	Higher	1073, 0.203, SE
G20	BRENTON INVESTMENT C	2999 GRAND POINT HWY	UST	Lower	1177, 0.223, SE
G21	BRENTON INVESTMENT C	2999 GRAND POINT HWY	LUST, SPILLS, NPDES, REM	Lower	1177, 0.223, SE
22	DOLLAR GENERAL #847	1053 B HENERSON HWY	RCRA-VSQG, FINDS, ECHO	Lower	1313, 0.249, ESE
G23	I-10 HENDERSON TRAVE	3003 GRAND POINT HWY	AUL	Lower	1343, 0.254, SSE
G24	I-10 HENDERSON TRAVE	3003 GRAND POINT HWY	LUST, UST, AUL, NPDES, REM	Lower	1343, 0.254, SSE
G25	WILLIAMS TRAVEL CENT	1018 MARTHA HEBERT R	HIST LUST, SPILLS	Lower	1440, 0.273, SE

EXECUTIVE SUMMARY

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 8 of the attached EDR Radius Map report:

Site	Database(s)	EPA ID
HENDERSON TRAVEL PLA 2996 GRAND POINT HWY BREAUX BRIDGE, LA 70517	HIST LUST Facility Id: 50-012828 UST Tank Status: Active Master Agency Id: 70537	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL..... National Priority List
Proposed NPL..... Proposed National Priority List Sites
NPL LIENS..... Federal Superfund Liens

Lists of Federal Delisted NPL sites

Delisted NPL..... National Priority List Deletions

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY..... Federal Facility Site Information listing
SEMS..... Superfund Enterprise Management System

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE..... Superfund Enterprise Management System Archive

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS..... Corrective Action Report

Lists of Federal RCRA TSD facilities

RCRA-TSDF..... RCRA - Treatment, Storage and Disposal

Lists of Federal RCRA generators

RCRA-LQG..... RCRA - Large Quantity Generators

EXECUTIVE SUMMARY

Federal institutional controls / engineering controls registries

LUCIS..... Land Use Control Information System
US ENG CONTROLS..... Engineering Controls Sites List
US INST CONTROLS..... Institutional Controls Sites List

Federal ERNS list

ERNS..... Emergency Response Notification System

Lists of state- and tribal hazardous waste facilities

SHWS..... Potential and Confirmed Sites List

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF..... Landfill List
DEBRIS..... LDEQ Approved Debris Sites
HIST DEBRIS..... LDEQ Approved Debris Sites

Lists of state and tribal leaking storage tanks

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

Lists of state and tribal registered storage tanks

FEMA UST..... Underground Storage Tank Listing
INDIAN UST..... Underground Storage Tanks on Indian Land

Lists of state and tribal voluntary cleanup sites

VCP..... Voluntary Remediation Program Sites
INDIAN VCP..... Voluntary Cleanup Priority Listing

Lists of state and tribal brownfield sites

BROWNFIELDS..... Brownfields Inventory

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY..... Recycling Directory
INDIAN ODI..... Report on the Status of Open Dumps on Indian Lands
DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations
ODI..... Open Dump Inventory
IHS OPEN DUMPS..... Open Dumps on Indian Land

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL..... Delisted National Clandestine Laboratory Register

EXECUTIVE SUMMARY

CDL..... Clandestine Drug Lab
US CDL..... National Clandestine Laboratory Register

Local Land Records

LIENS..... Environmental Liens
LIENS 2..... CERCLA Lien Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System
SPILLS..... Emergency Response Section Incidents
SPILLS 90..... SPILLS 90 data from FirstSearch

Other Ascertainable Records

RCRA NonGen / NLR..... RCRA - Non Generators / No Longer Regulated
FUDS..... Formerly Used Defense Sites
DOD..... Department of Defense Sites
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
US FIN ASSUR..... Financial Assurance Information
EPA WATCH LIST..... EPA WATCH LIST
2020 COR ACTION..... 2020 Corrective Action Program List
TSCA..... Toxic Substances Control Act
TRIS..... Toxic Chemical Release Inventory System
SSTS..... Section 7 Tracking Systems
ROD..... Records Of Decision
RMP..... Risk Management Plans
RAATS..... RCRA Administrative Action Tracking System
PRP..... Potentially Responsible Parties
PADS..... PCB Activity Database System
ICIS..... Integrated Compliance Information System
FTTS..... FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
MLTS..... Material Licensing Tracking System
COAL ASH DOE..... Steam-Electric Plant Operation Data
COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List
PCB TRANSFORMER..... PCB Transformer Registration Database
RADINFO..... Radiation Information Database
HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing
DOT OPS..... Incident and Accident Data
CONSENT..... Superfund (CERCLA) Consent Decrees
INDIAN RESERV..... Indian Reservations
FUSRAP..... Formerly Utilized Sites Remedial Action Program
UMTRA..... Uranium Mill Tailings Sites
LEAD SMELTERS..... Lead Smelter Sites
US AIRS..... Aerometric Information Retrieval System Facility Subsystem
US MINES..... Mines Master Index File
ABANDONED MINES..... Abandoned Mines
MINES MRDS..... Mineral Resources Data System
FINDS..... Facility Index System/Facility Registry System
UXO..... Unexploded Ordnance Sites
DOCKET HWC..... Hazardous Waste Compliance Docket Listing
ECHO..... Enforcement & Compliance History Information
FUELS PROGRAM..... EPA Fuels Program Registered Listing

EXECUTIVE SUMMARY

PFAS NPL.....	Superfund Sites with PFAS Detections Information
PFAS FEDERAL SITES.....	Federal Sites PFAS Information
PFAS TRIS.....	List of PFAS Added to the TRI
PFAS TSCA.....	PFAS Manufacture and Imports Information
PFAS RCRA MANIFEST.....	PFAS Transfers Identified In the RCRA Database Listing
PFAS ATSDR.....	PFAS Contamination Site Location Listing
PFAS WQP.....	Ambient Environmental Sampling for PFAS
PFAS NPDES.....	Clean Water Act Discharge Monitoring Information
PFAS PROJECT.....	NORTHEASTERN UNIVERSITY PFAS PROJECT
PFAS ECHO FIRE TRAIN....	Facilities in Industries that May Be Handling PFAS Listing
PFAS PT 139 AIRPORT.....	All Certified Part 139 Airports PFAS Information Listing
AQUEOUS FOAM NRC.....	Aqueous Foam Related Incidents Listing
BIOSOLIDS.....	ICIS-NPDES Biosolids Facility Data
UST FINDER RELEASE.....	UST Finder Releases Database
UST FINDER.....	UST Finder Database
PFAS.....	Per- and Polyfluoroalkyl Substances (PFAS) Data
AQUEOUS FOAM.....	A listing of reported incidents involving firefighting foam.
AIRS.....	Air Permit List
ASBESTOS.....	Asbestos Projects List
COAL ASH.....	Coal Ash Disposal Sites
DRYCLEANERS.....	Drycleaner Facility Listing
Financial Assurance.....	Financial Assurance Information
NPDES.....	LPDES Permits Database
UIC.....	Underground Injection Wells Listing

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP.....	EDR Proprietary Manufactured Gas Plants
EDR Hist Cleaner.....	EDR Exclusive Historical Cleaners

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS.....	Recovered Government Archive State Hazardous Waste Facilities List
RGA LF.....	Recovered Government Archive Solid Waste Facilities List
RGA LUST.....	Recovered Government Archive Leaking Underground Storage Tank

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property. Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal RCRA generators

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 RCRA-SQG site within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FEDEX FREIGHT INC EPA ID:: LAR000102605	2937 GRAND POINT HWY	E 0 - 1/8 (0.100 mi.)	D12	56

RCRA-VSQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-VSQG list, as provided by EDR, and dated 06/02/2025 has revealed that there are 3 RCRA-VSQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
O'REILLY AUTO PARTS EPA ID:: LAR000103413	2889 GRAND POINT HWY	ENE 0 - 1/8 (0.044 mi.)	A4	28
HENDERSON I-10 EXXON EPA ID:: LAD985213164	2987 GRAND POINT	SE 1/8 - 1/4 (0.203 mi.)	F19	89
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
DOLLAR GENERAL #847 EPA ID:: LAR000093435	1053 B HENERSON HWY	ESE 1/8 - 1/4 (0.249 mi.)	22	108

Lists of state and tribal leaking storage tanks

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Quality's list: LDEQ's Leaking UST Database.

A review of the LUST list, as provided by EDR, and dated 07/09/2025 has revealed that there are 5 LUST sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
VED'S 5 LLC	3002 GRAND POINT HWY	SSE 1/8 - 1/4 (0.203 mi.)	E17	86

EXECUTIVE SUMMARY

Facility Id: 79336

HENDERSON I-10 EXXON Facility Id: 23599	2987 GRAND POINT HWY	SE 1/8 - 1/4 (0.203 mi.)	F18	87
---	-----------------------------	---------------------------------	------------	-----------

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HENDERSON TRAVEL PLA Facility Id: 70537	2996 GRAND POINT HWY	SE 1/8 - 1/4 (0.140 mi.)	13	59
BRENTON INVESTMENT C Facility Id: 96391	2999 GRAND POINT HWY	SE 1/8 - 1/4 (0.223 mi.)	G21	104
I-10 HENDERSON TRAVE Facility Id: 31056	3003 GRAND POINT HWY	SSE 1/4 - 1/2 (0.254 mi.)	G24	112

HIST LUST: Department of Environmental Quality's Underground Storage Tank Case History Incidents database.

A review of the HIST LUST list, as provided by EDR, and dated 11/01/1999 has revealed that there are 2 HIST LUST sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
DIESI'S LITTLE CAPIT Facility Id: 50-014643	2939 GRAND POINT HWY	E 0 - 1/8 (0.055 mi.)	C9	52

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
WILLIAMS TRAVEL CENT Facility Id: 50-006699	1018 MARTHA HEBERT R	SE 1/4 - 1/2 (0.273 mi.)	G25	126

Lists of state and tribal registered storage tanks

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Quality's Louisiana Underground Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 07/08/2025 has revealed that there are 6 UST sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BAYOU BELLE TRUCK ST Tank Status: Active Master Agency Id: 100130	2924 GRAND POINT HWY	ENE 0 - 1/8 (0.019 mi.)	A2	19
LANDRY'S CAJUN TEXAC Tank Status: Active Master Agency Id: 73135	2942 A GRAND POINT H	ESE 0 - 1/8 (0.044 mi.)	B5	32
LITTLE CAPITOL OF LO Tank Status: Active Master Agency Id: 19443	2939 GRAND POINT HWY	E 0 - 1/8 (0.055 mi.)	C7	40
VED'S 5 LLC	3002 GRAND POINT HWY	SSE 1/8 - 1/4 (0.203 mi.)	E16	80

EXECUTIVE SUMMARY

Tank Status: Active
Master Agency Id: 79336

HENDERSON I-10 EXXON	2987 GRAND POINT	SE 1/8 - 1/4 (0.203 mi.)	F19	89
Tank Status: Active				
Tank Status: Temp Out of Service				
Master Agency Id: 23599				

<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BRENTON INVESTMENT C	2999 GRAND POINT HWY	SE 1/8 - 1/4 (0.223 mi.)	G20	100
Tank Status: Active				
Master Agency Id: 96391				

State and tribal institutional control / engineering control registries

AUL: A notice of contamination (nature and levels of contaminants) and restriction of property to non-residential use are placed in the conveyance records for the property.

A review of the AUL list, as provided by EDR, and dated 03/27/2025 has revealed that there are 4 AUL sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HENDERSON I-10 EXXON	2987 GRAND POINT HWY	SE 1/8 - 1/4 (0.203 mi.)	F18	87
Lower Elevation	Address	Direction / Distance	Map ID	Page
HENDERSON TRAVEL PLA	2996 GRAND POINT HWY	SE 1/8 - 1/4 (0.140 mi.)	13	59
I-10 HENDERSON TRAVE	3003 GRAND POINT HWY	SSE 1/4 - 1/2 (0.254 mi.)	G23	111
I-10 HENDERSON TRAVE	3003 GRAND POINT HWY	SSE 1/4 - 1/2 (0.254 mi.)	G24	112
Facility Id: 31056				

ADDITIONAL ENVIRONMENTAL RECORDS

Local Lists of Hazardous waste / Contaminated Sites

DEL SHWS: A listing of sites removed from the Potential and Confirmed Listing.

A review of the DEL SHWS list, as provided by EDR, and dated 07/09/2025 has revealed that there is 1 DEL SHWS site within approximately 1 mile of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CECILIA FIELD COMMUN	ON HWY 347 1.3 MI S	W 1/8 - 1/4 (0.143 mi.)	14	65
AI #: 13117				

EXECUTIVE SUMMARY

Other Ascertainable Records

PFAS ECHO: Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

A review of the PFAS ECHO list, as provided by EDR, and dated 06/23/2025 has revealed that there is 1 PFAS ECHO site within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CECILIA FIELD COMMIN	ON HWY 347 OFF MELVI	W 1/8 - 1/4 (0.181 mi.)	15	78

E MANIFEST: EPA established a national system for tracking hazardous waste shipments electronically. This system, known as e-Manifest, will modernize the nation's cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

A review of the E MANIFEST list, as provided by EDR, and dated 06/02/2025 has revealed that there is 1 E MANIFEST site within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FEDEX FREIGHT	2937 GRAND POINT HWY	E 0 - 1/8 (0.100 mi.)	D10	54

REM: Facilities or sites come to the Underground Storage Tank and Remediation Division either through self notification or referral. These sites are designated for remediation via the following regulatory paths: Solid Waste (SW), Hazardous Waste (Haz Waste), Groundwater (Grwater), Inactive & Abandoned Sites (Confirmed or Potential), or Underground Storage Tanks (UST).

A review of the REM list, as provided by EDR, and dated 07/09/2025 has revealed that there are 6 REM sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
CECILIA FIELD COMMIN AI Num: 13117	ON HWY 347 1.3 MI S	W 1/8 - 1/4 (0.143 mi.)	14	65
VED'S 5 LLC AI Num: 79336	3002 GRAND POINT HWY	SSE 1/8 - 1/4 (0.203 mi.)	E17	86
HENDERSON I-10 EXXON AI Num: 23599	2987 GRAND POINT HWY	SE 1/8 - 1/4 (0.203 mi.)	F18	87
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
HENDERSON TRAVEL PLA AI Num: 70537	2996 GRAND POINT HWY	SE 1/8 - 1/4 (0.140 mi.)	13	59
BRENTON INVESTMENT C AI Num: 96391	2999 GRAND POINT HWY	SE 1/8 - 1/4 (0.223 mi.)	G21	104
I-10 HENDERSON TRAVE AI Num: 31056	3003 GRAND POINT HWY	SSE 1/4 - 1/2 (0.254 mi.)	G24	112

EXECUTIVE SUMMARY

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 4 EDR Hist Auto sites within approximately 0.125 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BAYOU BELLE TRUCK ST	2924 GRAND POINT HWY	ENE 0 - 1/8 (0.019 mi.)	A3	28
LANDRYS CAJUN TEXACO	2942-A GRAND POINT H	ESE 0 - 1/8 (0.044 mi.)	B6	40
LITTLE CAPITOL OF LO	2939 GRAND POINT HWY	E 0 - 1/8 (0.055 mi.)	C8	51
LITTLE CAPITOL OF LO	2937 GRAND POINT HWY	E 0 - 1/8 (0.100 mi.)	D11	56

EXECUTIVE SUMMARY

There were no unmapped sites in this report.

OVERVIEW MAP - 8156261.2S



Target Property

Sites at elevations higher than or equal to the target property

Sites at elevations lower than the target property

Manufactured Gas Plants

National Priority List Sites

Dept. Defense Sites

Indian Reservations BIA

Power transmission lines

Pipelines

Special Flood Hazard Area (1%)

0.2% Annual Chance Flood Hazard

National Wetland Inventory


0 1/4 1/2 1 Miles

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Henderson I-10 Site
ADDRESS: I-10
Breau Bridge LA 70517
LAT/LONG: 30.317196 / 91.835519

CLIENT: Chenier Environmental Consulting
CONTACT: Aaron Bass
INQUIRY #: 8156261.2s
DATE: October 29, 2025 3:15 pm

DETAIL MAP - 8156261.2S



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Dept. Defense Sites
- Indian Reservations BIA
- Power transmission lines
- Pipelines
- Special Flood Hazard Area (1%)
- 0.2% Annual Chance Flood Hazard
- National Wetland Inventory

0 1/8 1/4 1/2 Miles

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Henderson I-10 Site
 ADDRESS: I-10
 Breaux Bridge LA 70517
 LAT/LONG: 30.317196 / 91.835519

CLIENT: Chenier Environmental Consulting
 CONTACT: Aaron Bass
 INQUIRY #: 8156261.2s
 DATE: October 29, 2025 3:18 pm

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTAL RECORDS								
<i>Lists of Federal NPL (Superfund) sites</i>								
NPL	1.000		0	0	0	0	NR	0
Proposed NPL	1.000		0	0	0	0	NR	0
NPL LIENS	1.000		0	0	0	0	NR	0
<i>Lists of Federal Delisted NPL sites</i>								
Delisted NPL	1.000		0	0	0	0	NR	0
<i>Lists of Federal sites subject to CERCLA removals and CERCLA orders</i>								
FEDERAL FACILITY	0.500		0	0	0	NR	NR	0
SEMS	0.500		0	0	0	NR	NR	0
<i>Lists of Federal CERCLA sites with NFRAP</i>								
SEMS-ARCHIVE	0.500		0	0	0	NR	NR	0
<i>Lists of Federal RCRA facilities undergoing Corrective Action</i>								
CORRACTS	1.000		0	0	0	0	NR	0
<i>Lists of Federal RCRA TSD facilities</i>								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
<i>Lists of Federal RCRA generators</i>								
RCRA-LQG	0.250		0	0	NR	NR	NR	0
RCRA-SQG	0.250		1	0	NR	NR	NR	1
RCRA-VSQG	0.250		1	2	NR	NR	NR	3
<i>Federal institutional controls / engineering controls registries</i>								
LUCIS	0.500		0	0	0	NR	NR	0
US ENG CONTROLS	0.500		0	0	0	NR	NR	0
US INST CONTROLS	0.500		0	0	0	NR	NR	0
<i>Federal ERNS list</i>								
ERNS	0.001		0	NR	NR	NR	NR	0
<i>Lists of state- and tribal hazardous waste facilities</i>								
SHWS	1.000		0	0	0	0	NR	0
<i>Lists of state and tribal landfills and solid waste disposal facilities</i>								
SWF/LF	0.500		0	0	0	NR	NR	0
DEBRIS	0.500		0	0	0	NR	NR	0
HIST DEBRIS	0.500		0	0	0	NR	NR	0
<i>Lists of state and tribal leaking storage tanks</i>								
LUST	0.500		0	4	1	NR	NR	5

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
INDIAN LUST	0.500		0	0	0	NR	NR	0
HIST LUST	0.500	1	1	0	1	NR	NR	3
<i>Lists of state and tribal registered storage tanks</i>								
FEMA UST	0.250		0	0	NR	NR	NR	0
UST	0.250	1	3	3	NR	NR	NR	7
INDIAN UST	0.250		0	0	NR	NR	NR	0
<i>State and tribal institutional control / engineering control registries</i>								
AUL	0.500		0	2	2	NR	NR	4
<i>Lists of state and tribal voluntary cleanup sites</i>								
VCP	0.500		0	0	0	NR	NR	0
INDIAN VCP	0.500		0	0	0	NR	NR	0
<i>Lists of state and tribal brownfield sites</i>								
BROWNFIELDS	0.500		0	0	0	NR	NR	0
<u>ADDITIONAL ENVIRONMENTAL RECORDS</u>								
<i>Local Brownfield lists</i>								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
<i>Local Lists of Landfill / Solid Waste Disposal Sites</i>								
SWRCY	0.500		0	0	0	NR	NR	0
INDIAN ODI	0.500		0	0	0	NR	NR	0
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500		0	0	0	NR	NR	0
IHS OPEN DUMPS	0.500		0	0	0	NR	NR	0
<i>Local Lists of Hazardous waste / Contaminated Sites</i>								
US HIST CDL	0.001		0	NR	NR	NR	NR	0
CDL	0.001		0	NR	NR	NR	NR	0
DEL SHWS	1.000		0	1	0	0	NR	1
US CDL	0.001		0	NR	NR	NR	NR	0
<i>Local Land Records</i>								
LIENS	0.001		0	NR	NR	NR	NR	0
LIENS 2	0.001		0	NR	NR	NR	NR	0
<i>Records of Emergency Release Reports</i>								
HMIRS	0.001		0	NR	NR	NR	NR	0
SPILLS	0.001		0	NR	NR	NR	NR	0
SPILLS 90	0.001		0	NR	NR	NR	NR	0
<i>Other Ascertainable Records</i>								
RCRA NonGen / NLR	0.250		0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FUDS	1.000		0	0	0	0	NR	0
DOD	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US FIN ASSUR	0.001		0	NR	NR	NR	NR	0
EPA WATCH LIST	0.001		0	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
TSCA	0.001		0	NR	NR	NR	NR	0
TRIS	0.001		0	NR	NR	NR	NR	0
SSTS	0.001		0	NR	NR	NR	NR	0
ROD	1.000		0	0	0	0	NR	0
RMP	0.001		0	NR	NR	NR	NR	0
RAATS	0.001		0	NR	NR	NR	NR	0
PRP	0.001		0	NR	NR	NR	NR	0
PADS	0.001		0	NR	NR	NR	NR	0
ICIS	0.001		0	NR	NR	NR	NR	0
FTTS	0.001		0	NR	NR	NR	NR	0
MLTS	0.001		0	NR	NR	NR	NR	0
COAL ASH DOE	0.001		0	NR	NR	NR	NR	0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
PCB TRANSFORMER	0.001		0	NR	NR	NR	NR	0
RADINFO	0.001		0	NR	NR	NR	NR	0
HIST FTTS	0.001		0	NR	NR	NR	NR	0
DOT OPS	0.001		0	NR	NR	NR	NR	0
CONSENT	1.000		0	0	0	0	NR	0
INDIAN RESERV	1.000		0	0	0	0	NR	0
FUSRAP	1.000		0	0	0	0	NR	0
UMTRA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.001		0	NR	NR	NR	NR	0
US AIRS	0.001		0	NR	NR	NR	NR	0
US MINES	0.250		0	0	NR	NR	NR	0
ABANDONED MINES	0.250		0	0	NR	NR	NR	0
MINES MRDS	0.250		0	0	NR	NR	NR	0
FINDS	0.001		0	NR	NR	NR	NR	0
UXO	1.000		0	0	0	0	NR	0
DOCKET HWC	0.001		0	NR	NR	NR	NR	0
ECHO	0.001		0	NR	NR	NR	NR	0
FUELS PROGRAM	0.250		0	0	NR	NR	NR	0
PFAS NPL	0.250		0	0	NR	NR	NR	0
PFAS FEDERAL SITES	0.250		0	0	NR	NR	NR	0
PFAS TRIS	0.250		0	0	NR	NR	NR	0
PFAS TSCA	0.250		0	0	NR	NR	NR	0
PFAS RCRA MANIFEST	0.250		0	0	NR	NR	NR	0
PFAS ATSDR	0.250		0	0	NR	NR	NR	0
PFAS WQP	0.250		0	0	NR	NR	NR	0
PFAS NPDES	0.250		0	0	NR	NR	NR	0
PFAS PROJECT	0.250		0	0	NR	NR	NR	0
PFAS ECHO	0.250		0	1	NR	NR	NR	1
PFAS ECHO FIRE TRAIN	0.250		0	0	NR	NR	NR	0
PFAS PT 139 AIRPORT	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM NRC	0.250		0	0	NR	NR	NR	0
BIOSOLIDS	0.001		0	NR	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
UST FINDER RELEASE	0.500		0	0	0	NR	NR	0
UST FINDER	0.250		0	0	NR	NR	NR	0
E MANIFEST	0.250		1	0	NR	NR	NR	1
PFAS	0.250		0	0	NR	NR	NR	0
AQUEOUS FOAM	0.250		0	0	NR	NR	NR	0
AIRS	0.001		0	NR	NR	NR	NR	0
ASBESTOS	0.001		0	NR	NR	NR	NR	0
COAL ASH	0.500		0	0	0	NR	NR	0
DRYCLEANERS	0.250		0	0	NR	NR	NR	0
Financial Assurance	0.001		0	NR	NR	NR	NR	0
NPDES	0.001		0	NR	NR	NR	NR	0
REM	0.500		0	5	1	NR	NR	6
UIC	0.001		0	NR	NR	NR	NR	0

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP	1.000		0	0	0	0	NR	0
EDR Hist Auto	0.125		4	NR	NR	NR	NR	4
EDR Hist Cleaner	0.125		0	NR	NR	NR	NR	0

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS	0.001		0	NR	NR	NR	NR	0
RGA LF	0.001		0	NR	NR	NR	NR	0
RGA LUST	0.001		0	NR	NR	NR	NR	0

- Totals --		2	11	18	5	0	0	36
-------------	--	---	----	----	---	---	---	----

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

1
Target
Property

HENDERSON TRAVEL PLAZA & CASINO
2996 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

HIST LUST
UST

U001896691
N/A

Actual:
20 ft.

HIST LUST:

Facility ID: 50-012828
Facility Parish: ST. MARTIN
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 06/12/1990
Date Confirmed 2: Not reported
Incident Number: 90-4-0121
Incident Date: 06/12/1990
Type of Incident: DISPENSER LEAK
Type of Incident No2: Not reported
Reported By: JOHNNIE MAYEUX/ DEQ UST
Reported By 2: Not reported
Owner ID: 00322800
Owner Name: WURSTER OIL CO., INC.
Owner Address: P.O. BOX 38
Owner City,St,Zip: JONESVILLE, LA 71343
Assessment Pending Info: Yes
Assessment Request Date: 06/22/1990
Assessment Plan Due Date: 09/12/1990
Assessment Plan Received Date: 09/13/1990
Assessment Approved Date: 11/02/1990
Assessment Contractor: PETRON INC.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: Not reported

LA HIST LUST ASSESMENT:

Comments: DEQ INSPECTION FOUND PRODUCT IN 2 OBSERVATION WELLS. THE SITE WASSHUT DOWN UNTIL THE SOURCE OF THE LEAK WAS FOUND. THE PROBLEM WASFOUND WITH THE PUMP. SHEEN WAS FOUND IN A NEARBY DITCH.DEQ DENIES 3/6/92 REQUEST FOR TERM. OF REMEDIATION.

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

Facility ID: 50-012828
Facility Parish: ST. MARTIN
Substance Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 90-4-0121
Incident Date: 06/12/1990
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00322800
Owner Name: WURSTER OIL CO., INC.
Owner Address: P.O. BOX 38
Owner City,St,Zip: JONESVILLE, LA 71343
Assessment Pending Info: Yes
Assessment Request Date: 06/22/1990
Assessment Plan Due Date: 09/12/1990
Assessment Plan Received Date: 09/13/1990
Assessment Approved Date: 11/02/1990
Assessment Contractor: PETRON INC.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: Not reported

LA HIST LUST ASSESMENT:

Comments: DEQ INSPECTION FOUND PRODUCT IN 2 OBSERVATION WELLS. THE SITE WAS SHUT DOWN UNTIL THE SOURCE OF THE LEAK WAS FOUND. THE PROBLEM WAS FOUND WITH THE PUMP. SHEEN WAS FOUND IN A NEARBY DITCH. DEQ DENIES 3/6/92 REQUEST FOR TERM. OF REMEDIATION.

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

UST:

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
Address 2: Not reported
City: BREAUX BRIDGE
Master Agency Id: 70537
Subject Item ID: 1

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

UST Tank Num:	36619
Tank Status:	Active
Install Date:	01/01/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Yes
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	36619-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	12/22/1989
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1989
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/01/1989
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	12/01/1989
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Y
Install certification date:	10/01/1999
Install alt certificate num:	IRC 0104
Install cert worker name:	JOSEPH JACKSON
Install cert worker emp name:	PETRON INC
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	12/22/1989
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	36620
Tank Status:	Active
Install Date:	01/01/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Yes

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	36620-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	12/22/1989
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	12/01/1989
Alt spill overfill equip flag:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/01/1989
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	12/01/1989
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Y
Install certification date:	10/01/1999
Install alt certificate num:	IRC 0104
Install cert worker name:	JOSEPH JACKSON
Install cert worker emp name:	PETRON INC
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	12/22/1989
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	36621
Tank Status:	Active
Install Date:	01/01/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	36621-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	12/22/1989
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	12/01/1989
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/01/1989
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Cpt impressed curr:	Y
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	12/01/1989
Cpp fibrgls plastic:	Not reported
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Y
Install certification date:	10/01/1999
Install alt certificate num:	IRC 0104
Install cert worker name:	JOSEPH JACKSON
Install cert worker emp name:	PETRON INC
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	12/22/1989
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	50326
Tank Status:	Active
Install Date:	11/21/1995
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	50326-diesel
Service change date:	Not reported
Last service date:	12/01/1995
Current status start date:	01/10/1997
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Y
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	11/21/1995
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	11/21/1995
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	11/21/1995

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Cpp fibrgls plastic:	Not reported
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Y
Install certification date:	10/01/1999
Install alt certificate num:	IRC-0104
Install cert worker name:	JOSEPH JACKSON
Install cert worker emp name:	PETRON INC.
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	01/10/1997
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	50327
Tank Status:	Active
Install Date:	11/21/1995
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	50327-diesel
Service change date:	Not reported
Last service date:	12/01/1995
Current status start date:	12/22/1989
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fibrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	11/21/1995
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	11/21/1995
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	11/21/1995
Cpp fibrgls plastic:	Not reported
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

U001896691

Cpp other: Y
Install certification date: 10/01/1999
Install alt certificate num: IRC-0104
Install cert worker name: JOSEPH JACKSON
Install cert worker emp name: PETRON INC.
Install cert by mfr flag: Y
Install insp by reg eng flag: Not reported
Install insp by dept flag: Not reported
Install mfr chklst comp flag: Y
Install cert alt method flag: Not reported
Install cert alt method desc: Not reported
Closure certification date: Not reported
Closure alt cert num: Not reported
Closure cert worker name: Not reported
Closure cert worker emp name: Not reported
Active: 12/22/1989
Bankrupt: Not reported
Closed: Not reported
Deferred: Not reported
Filled: Not reported
Hold: Not reported
Inactive: Not reported
Removed: Not reported
Sold: Not reported
Temp out of service: Not reported

A2
ENE
< 1/8
0.019 mi.
102 ft.

BAYOU BELLE TRUCK STOP & CASINO
2924 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

UST
SPILLS
NPDES

U004010429
N/A

Site 1 of 3 in cluster A

Relative:
Higher
Actual:
21 ft.

UST:
Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 GRAND POINT HWY
Address 2: Not reported
City: BREAUX BRIDGE
Master Agency Id: 100130
Subject Item ID: 1

UST Tank Num: 55684
Tank Status: **Active**
Install Date: 07/12/2002
Total Capacity: 15000
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Not reported
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	55684-gasohol
Service change date:	Not reported
Last service date:	12/12/2002
Current status start date:	03/31/2003
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	09/12/2002
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	09/12/2002
Cpt fibrgls plstc:	Y
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	09/12/2002

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Cpp fibrgls plastic:	Y
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	01/09/2003
Install alt certificate num:	IRC 0371
Install cert worker name:	Danny Durbin
Install cert worker emp name:	Jones Brothers
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/31/2003
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	55685
Tank Status:	Active
Install Date:	07/12/2002
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	55685-diesel
Service change date:	Not reported
Last service date:	12/12/2002
Current status start date:	03/31/2003
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fibrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	09/12/2002
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	09/12/2002
Cpt fibrgls plstc:	Y
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	09/12/2002
Cpp fibrgls plastic:	Y
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Cpp other:	Not reported
Install certification date:	01/09/2003
Install alt certificate num:	IRC 0371
Install cert worker name:	Danny Durbin
Install cert worker emp name:	Jones Brothers
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/31/2003
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	55686
Tank Status:	Active
Install Date:	07/12/2002
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Subject item desc:	55686-gasohol
Service change date:	Not reported
Last service date:	12/12/2002
Current status start date:	03/31/2003
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	09/12/2002
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	09/12/2002
Cpt fibrgls plstc:	Y
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	09/12/2002
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	01/09/2003
Install alt certificate num:	IRC 0371
Install cert worker name:	Danny Durbin
Install cert worker emp name:	Jones Brothers
Install cert by mfr flag:	Y

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/31/2003
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

SPILLS:

Name:	BAYOU BELLE TRUCK STOP & CASINO
Address:	2924 Grand Point Hwy
City,State,Zip:	BREAUX BRIDGE, LA 70517
Receive Date:	02/19/2023
Incident Date:	02/19/2023
Quantity:	45
Units:	gallons
Parameter:	Diesel
Incident ID:	212882
Other Description:	Not reported
AI ID:	100130
Incident Status:	Closed
Media Desc:	Water/Soil
Location Description:	2824 GRANDPOINT HWY Breaux Bridge
Start Date:	Not reported
Region:	AR
Reporter Name:	Dixie Santiny
Mailing Address:	2924 Grand Point Hwy
Mailing City:	Breaux Bridge
Mailing State:	LA
Mailing Zip:	70517
Organization Name:	BAYOU BELLE
Incident Desc:	SPILL Release of diesel to soil at facility CML
Incident Type Desc:	Release/Spill, Facility Water Discharge
Comments:	On February 19, 2023 Matt Henry with LDEQ Surveillance responded via telephone only to an incident in Breaux Bridge, Louisiana related to a diesel spill at Bayou Belle Truck Stop. Spill was caused by overfilling at a diesel pump that was unattended; spilling diesel onto the concrete pad around diesel pumps. The amount of diesel spilled was estimated to be approximately 20 gallons, which is below the reportable quantity of 42 gallons for diesel. Diesel did not migrate offsite and did not escape the concrete pad. Diesel did not impact vegetation or reach waters of the State. Crews at the Bayou Belle Truck Stop used between 4-5 bags of cat litter to curb the spreading of the diesel, and when St Martin Fire Dept arrived they used absorbents to further absorb any standing diesel on the concrete pad.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Both of the methods were effective in removing all standing diesel; and absorbents and cat litter were properly disposed of by St Martin Fire Dept. On February 24, 2023 Matt Henry conducted a site visit to Bayou Belle to assess the area of the spill. There was no diesel staining on the concrete pad around the pumps. During this incident there were no reports of injury, fire, or road closures. (Photos Attached) MH

Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 Grand Point Hwy
City,State,Zip: BREAUX BRIDGE, LA 70517
Receive Date: 07/28/2022
Incident Date: 07/28/2022
Quantity: 50
Units: gallons
Parameter: Diesel
Incident ID: 209810
Other Description: Not reported
AI ID: 100130
Incident Status: Closed
Media Desc: Water/Soil
Location Description: Bayou Bell Truck Stop 2924 Grand Point Hwy Breaux Bridge
Start Date: Not reported
Region: AR
Reporter Name: Trisha Henderson
Mailing Address: 2924 Grand Point Hwy
Mailing City: Breaux Bridge
Mailing State: LA
Mailing Zip: 70517
Organization Name: Performance Food Group
Incident Desc: SPILL Release of diesel to soil from a damaged saddle tank CML
Incident Type Desc: Release/Spill, Highway Transport
Comments: At 1:15am on 7/28/2022 an 18 wheeler owned by performance food group arrived at the Bayou Bell Truckstop while leaking diesel from one of its saddle tanks. The driver believed that he ran over some debris that punctured a hole in the tank. Approximately 50 gallons of diesel released to the gas station's rear, concrete parking lot. The driver deployed a spill kit at the site and the RP contacted OMI for remediation. The diesel collected in a puddle that was in a low spot in the concrete. OMI was able to recover the diesel with absorbents and Spagh Sorb. I met Matt with OMI onsite on 7/28/2022, and I drove past the site on 7/29/2022 to confirm that no diesel remained. -RAG

Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 Grand Point Hwy
City,State,Zip: BREAUX BRIDGE, LA 70517
Receive Date: 03/02/2017
Incident Date: 03/02/2017
Quantity: Not reported
Units: Not reported
Parameter: Not reported
Incident ID: 176277
Other Description: Not reported
AI ID: 100130
Incident Status: Closed
Media Desc: Not reported
Location Description: Breaux Bridge Pit Stop ; 2021 Rees St

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Start Date: Not reported
Region: AR
Reporter Name: Ginger Kubi
Mailing Address: 2924 Grand Point Hwy
Mailing City: Breaux Bridge
Mailing State: LA
Mailing Zip: 70517
Organization Name: BREAUX BRIDGE PIT STOP
Incident Desc: s17-93546 UST - regular gasoline release detected on tank in august of 2016. col
Incident Type Desc: UST, Release Detection Failure
Comments: Spoke with Ginger Koubi on March 31, 2017. The ATG reported a release detection failure for the regular unleaded gas tank in August, 2016. Lines were tested in October, 2016. Tank tested for tightness and passed on April 4, 2017.

NPDES:

Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 100130
Facility Phone: (337) 667-6579
Issued Date: 10/19/2018
Title Description: LAG54 Reauthorization
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20180001
Effective Date: 10/19/2018
Expiration Date: 07/31/2023
Permit Number: LAG541140
Mailing Address: 2924 Grand Point Hwy Breaux Bridge, LA 70517
Effective Flag: Y

Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 100130
Facility Phone: (337) 667-6579
Issued Date: 05/16/2014
Title Description: Renewed Coverage
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20130001
Effective Date: 05/16/2014
Expiration Date: 06/30/2018
Permit Number: LAG541140
Mailing Address: 2924 Grand Point Hwy Breaux Bridge, LA 70517
Effective Flag: N

Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 100130
Facility Phone: (337) 667-6579
Issued Date: 10/23/2003
Title Description: LAG541140 Permit
Permit Type Description: Gen-LAG54-Sanitary Class II

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BAYOU BELLE TRUCK STOP & CASINO (Continued)

U004010429

Program: Water
Activity Number: GEN20030001
Effective Date: 10/23/2003
Expiration Date: 02/29/2008
Permit Number: LAG541140
Mailing Address: 2924 Grand Point Hwy Breau Bridge, LA 70517
Effective Flag: N

Name: BAYOU BELLE TRUCK STOP & CASINO
Address: 2924 GRAND POINT HWY
City,State,Zip: BREAU BRIDGE, LA 70517
Facility Id: 100130
Facility Phone: (337) 667-6579
Issued Date: 11/21/2008
Title Description: Permit-Renewed Coverage
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20080001
Effective Date: 11/21/2008
Expiration Date: 06/30/2013
Permit Number: LAG541140
Mailing Address: 2924 Grand Point Hwy Breau Bridge, LA 70517
Effective Flag: N

**A3
ENE
< 1/8
0.019 mi.
102 ft.**

**BAYOU BELLE TRUCK STOP
2924 GRAND POINT HWY
BREAU BRIDGE, LA 70517**

**EDR Hist Auto 1021585319
N/A**

Site 2 of 3 in cluster A

**Relative:
Higher**

EDR Hist Auto

**Actual:
21 ft.**

Year:	Name:	Type:
2003	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2004	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2005	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2006	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2007	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2008	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2009	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2010	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2011	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2012	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2013	BAYOU BELLE TRUCK STOP	Gasoline Service Stations
2014	BAYOU BELLE TRUCK STOP	Gasoline Service Stations

**A4
ENE
< 1/8
0.044 mi.
231 ft.**

**O'REILLY AUTO PARTS #6778
2889 GRAND POINT HWY
BREAU BRIDGE, LA 70517**

**RCRA-VSQG 1031784504
ECHO LAR000103413**

Site 3 of 3 in cluster A

**Relative:
Higher**

RCRA Listings:

**Actual:
20 ft.**

Date Form Received by Agency: 20250514
Handler Name: O'Reilly Auto Parts #6778
Handler Address: Grand Point Hwy

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

O'REILLY AUTO PARTS #6778 (Continued)

1031784504

Handler City,State,Zip:	BREAUX BRIDGE, LA 70517
EPA ID:	LAR000103413
Contact Name:	JAMES J DAVIS
Contact Address:	S PATTERSON AVE
Contact City,State,Zip:	BREAUX BRIDGE, LA 70517
Contact Telephone:	417-730-1147
Contact Fax:	Not reported
Contact Email:	Not reported
Contact Title:	EHS SPECIALIST
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Conditionally Exempt Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	S PATTERSON AVE
Mailing City,State,Zip:	BREAUX BRIDGE, LA 70517
Owner Name:	O'Reilly Automotive Stores Inc
Owner Type:	Private
Operator Name:	O'Reilly Automotive Stores Inc
Operator Type:	Private
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20250527

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

O'REILLY AUTO PARTS #6778 (Continued)

1031784504

Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Waste Code:	D002
Waste Description:	Corrosive Waste

Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone

Waste Code:	F001
Waste Description:	The Following Spent Halogenated Solvents Used In Degreasing: Tetrachloroethylene, Trichloroethylene, Methylene Chloride, 1,1,1-Trichloroethane, Carbon Tetrachloride And Chlorinated Fluorocarbons; All Spent Solvent Mixtures/Blends Used In Degreasing Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code:	F002
Waste Description:	The Following Spent Halogenated Solvents: Tetrachloroethylene, Methylene Chloride, Trichloroethylene, 1,1,1-Trichloroethane, Chlorobenzene, 1,1,2-Trichloro-1,2,2-Trifluoroethane, Ortho-Dichlorobenzene, Trichlorofluoromethane, And 1,1,2, Trichloroethane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of One Or More Of The Above Halogenated Solvents Or Those Solvents Listed In F001, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code:	F003
Waste Description:	The Following Spent Nonhalogenated Solvents: Xylene, Acetone, Ethyl Acetate, Ethyl Benzene, Ethyl Ether, Methyl Isobutyl Ketone, N-Butyl Alcohol, Cyclohexanone, And Methanol; All Spent Solvent Mixtures/Blends Containing, Before Use, Only The Above Spent Nonhalogenated Solvents; And All Spent Solvent Mixtures/Blends Containing, Before Use, One Or More Of The Above Nonhalogenated Solvents, And A Total Of Ten Percent Or More (By Volume) Of One Or More Of Those Solvents Listed In F001, F002, F004, And F005; And Still Bottoms From The Recovery Of These Spent Solvents And Spent Solvent Mixtures.

Waste Code:	F005
Waste Description:	The Following Spent Nonhalogenated Solvents: Toluene, Methyl Ethyl Ketone, Carbon Disulfide, Isobutanol, Pyridine, Benzene, 2-Ethoxyethanol, And 2-Nitropropane; All Spent Solvent Mixtures/Blends Containing, Before Use, A Total Of Ten Percent Or More (By Volume) Of

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

O'REILLY AUTO PARTS #6778 (Continued)

1031784504

One Or More Of The Above Nonhalogenated Solvents Or Those Solvents
Listed In F001, F002, Or F004; And Still Bottoms From The Recovery Of
These Spent Solvents And Spent Solvent Mixtures.

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	O'REILLY AUTOMOTIVE STORES INC
Legal Status:	Private
Date Became Current:	20240612
Date Ended Current:	Not reported
Owner/Operator Address:	233 S PATTERSON AVE
Owner/Operator City,State,Zip:	BREAUX BRIDGE, LA 70517
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	O'REILLY AUTOMOTIVE STORES INC
Legal Status:	Private
Date Became Current:	20240612
Date Ended Current:	Not reported
Owner/Operator Address:	233 S PATTERSON AVE
Owner/Operator City,State,Zip:	BREAUX BRIDGE, LA 70517
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20250514
Handler Name:	O'REILLY AUTO PARTS #6778
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator)
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	441330
NAICS Description:	Automotive Parts And Accessories Retailers

Facility Has Received Notices of Violations:

Violations:	No Violations Found
-------------	---------------------

Evaluation Action Summary:

Evaluations:	No Evaluations Found
--------------	----------------------

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

O'REILLY AUTO PARTS #6778 (Continued)

1031784504

ECHO:

Envid: 1031784504
Registry ID: Not reported

[DFR URL:](#)

Name: O'REILLY AUTO PARTS #6778
Address: 2889 Grand Point Hwy
City,State,Zip: BREAUX BRIDGE, LA 70517

B5
ESE
< 1/8
0.044 mi.
234 ft.
Relative:
Higher
Actual:
20 ft.

LANDRY'S CAJUN TEXACO
2942 A GRAND POINT HWY
BREAUX BRIDGE, LA 70517

UST U001894903
N/A

Site 1 of 2 in cluster B

UST:

Name: LANDRY'S CAJUN TEXACO
Address: 2942 A GRAND POINT HWY
Address 2: Not reported
City: BREAUX BRIDGE
Master Agency Id: 73135
Subject Item ID: 1

UST Tank Num: 15142
Tank Status: **Active**
Install Date: 05/01/1979
Total Capacity: 9994
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Not reported
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported
Steel Tank Covered With Asphalt: Not reported
Cathodically Protected: Yes
Epoxy Coated Tank: Not reported
A Composite Of Different Materials: Not reported
Fiberglass Or Plastic: Y
Interior Line With Some Material: Not reported
Double Wall As Opposed To Single Wall: Not reported
Outside Lined w/ Polyethylen Jacket: Not reported
Made Of Concrete: Not reported
Liner Covering Excavation Hole: Not reported
Other Material: Not reported
Pipe Method Description: Pressure
Subject item desc: 15142-gasoline
Service change date: Not reported
Last service date: Not reported
Current status start date: 05/07/1986

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1998
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	Not reported
Install cert alt method flag:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	05/07/1986
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	15143
Tank Status:	Active
Install Date:	05/01/1979
Total Capacity:	9994
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	15143-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	05/07/1986
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1998
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fbrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fbrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	05/07/1986

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	15144
Tank Status:	Active
Install Date:	05/01/1979
Total Capacity:	9994
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	15144-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	05/07/1986
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1998
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	05/07/1986
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	15145
Tank Status:	Active
Install Date:	05/01/1979
Total Capacity:	9994
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	15145-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	05/07/1986
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LANDRY'S CAJUN TEXACO (Continued)

U001894903

Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1998
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	05/07/1986
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

	Site	Database(s)	EDR ID Number EPA ID Number
B6 ESE < 1/8 0.044 mi. 234 ft. Relative: Higher Actual: 20 ft.	LANDRYS CAJUN TEXACO 2942-A GRAND POINT HWY CECILIA, LA 70521 Site 2 of 2 in cluster B EDR Hist Auto Year: Name: Type: 1991 LANDRYS CAJUN TEXACO Gasoline Service Stations, NEC 1992 LANDRYS CAJUN TEXACO Gasoline Service Stations, NEC 1993 LANDRYS CAJUN TEXACO Gasoline Service Stations, NEC 1994 LANDRYS CAJUN TEXACO Gasoline Service Stations, NEC	EDR Hist Auto	1021745960 N/A

C7 East < 1/8 0.055 mi. 290 ft. Relative: Higher Actual: 20 ft.	LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE C 2939 GRAND POINT HWY BREAUX BRIDGE, LA 70517 Site 1 of 3 in cluster C UST: Name: LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL Address: 2939 GRAND POINT HWY Address 2: Not reported City: BREAUX BRIDGE Master Agency Id: 19443 Subject Item ID: 1 UST Tank Num: 42178 Tank Status: Active Install Date: 01/01/1985 Total Capacity: 10000 Number Of Compartments: 1 Gasoline: Not reported Diesel: Not reported Gasohol: Not reported Kerosene: Not reported Heating Oil: Not reported New Used Oil: Not reported MS Aviation Fuel: Not reported MS Additive: Not reported MS Antifreeze: Not reported MS Naptha: Not reported MS Varsol: Not reported Unknown: Not reported Other Sub: Not reported Steel Tank Covered With Asphalt: Not reported Cathodically Protected: Not reported Epoxy Coated Tank: Yes A Composite Of Different Materials: Not reported Fiberglass Or Plastic: Y Interior Line With Some Material: Not reported Double Wall As Opposed To Single Wall: Not reported Outside Lined w/ Polyethylen Jacket: Not reported Made Of Concrete: Not reported Liner Covering Excavation Hole: Not reported Other Material: Not reported Pipe Method Description: Pressure Subject item desc: 42178-gasoline Service change date: Not reported	UST NPDES	U003921864 N/A
---	---	----------------------------	---------------------------------

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Last service date:	Not reported
Current status start date:	03/07/1994
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1985
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Install mfr chkst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/07/1994
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	42179
Tank Status:	Active
Install Date:	01/01/1985
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	42179-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	03/07/1994
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1985
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fbrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fbrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Closure cert worker emp name:	Not reported
Active:	03/07/1994
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	42180
Tank Status:	Active
Install Date:	01/01/1985
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	42180-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	03/07/1994
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1985
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/07/1994
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	42181
Tank Status:	Active
Install Date:	01/01/1985
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	42181-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	03/07/1994
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1985
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/07/1994
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

UST Tank Num:	44268
Tank Status:	Active
Install Date:	05/01/1994
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	44268-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	03/07/1994
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	01/01/1985
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	Not reported
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	07/19/1990
Install alt certificate num:	Not reported
Install cert worker name:	Not reported
Install cert worker emp name:	Not reported
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	03/07/1994
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

NPDES:

Name:	DIESIS LITTLE CAPITOL EXXON
Address:	2939 GRAND POINT HWY
City,State,Zip:	BREAUX BRIDGE, LA 70517
Facility Id:	19443
Facility Phone:	337-667-7150
Issued Date:	05/05/1999

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Title Description: Fiscal Migration: LAG540922
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN19980001
Effective Date: Not reported
Expiration Date: Not reported
Permit Number: Not reported
Mailing Address: Not reported
Effective Flag: Not reported

Name: LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL
Address: 2939 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 19443
Facility Phone: (337) 667-7150
Issued Date: 10/19/2018
Title Description: LAG54 Reauthorization
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20180001
Effective Date: 10/19/2018
Expiration Date: 07/31/2023
Permit Number: LAG540922
Mailing Address: 2939 Grand Point Hwy BreauX Bridge, LA 70517
Effective Flag: Y

Name: DIESI'S LITTLE CAPITOL
Address: 2939 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 19443
Facility Phone: (337) 667-7150
Issued Date: 05/16/2014
Title Description: Renewed Coverage
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20130001
Effective Date: 05/16/2014
Expiration Date: 06/30/2018
Permit Number: LAG540922
Mailing Address: 2939 Grand Point Hwy BreauX Bridge, LA 70517
Effective Flag: N

Name: DIESIS LITTLE CAPITOL EXXON
Address: 2939 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 19443
Facility Phone: (337) 667-7150
Issued Date: 02/24/2003
Title Description: LAG540922
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20030001
Effective Date: 03/01/2003
Expiration Date: 02/29/2008
Permit Number: LAG540922
Mailing Address: 2939 Grand Point Hwy BreauX Bridge, LA 70517
Effective Flag: N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LITTLE CAPITOL OF LOUISIANA INC - DIESI'S LITTLE CAPITOL (Continued)

U003921864

Name: DIESIS LITTLE CAPITOL EXXON
Address: 2939 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 19443
Facility Phone: (337) 667-7150
Issued Date: 12/04/2008
Title Description: Permit
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20080001
Effective Date: 12/13/2008
Expiration Date: 06/30/2013
Permit Number: LAG540922
Mailing Address: 2939 Grand Point Hwy BreauX Bridge, LA 70517
Effective Flag: N

C8
East
< 1/8
0.055 mi.
290 ft.

LITTLE CAPITOL OF LOUISIANA
2939 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

EDR Hist Auto 1021502283
N/A

Site 2 of 3 in cluster C

Relative:
Higher

EDR Hist Auto

Actual:
20 ft.

Year:	Name:	Type:
1992	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1993	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1994	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1995	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1996	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1997	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1998	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
1999	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
2000	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
2001	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
2002	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
2003	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
2004	LITTLE CAPITOL OF LOUISIANA	Convenience Stores
2005	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2006	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2007	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2008	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2009	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2010	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2011	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2012	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2013	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2014	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

C9
East
< 1/8
0.055 mi.
290 ft.

DIESI'S LITTLE CAPITOL EXXON
2939 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

HIST LUST
SPILLS
S106034241
N/A

Site 3 of 3 in cluster C

Relative:
Higher

HIST LUST:

Actual:
20 ft.

Facility ID: 50-014643
Facility Parish: ST. MARTIN
Substance Name: UNKNOWN
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 04/12/1995
Date Confirmed 2: Not reported
Incident Number: 95-4-0044
Incident Date: Not reported
Type of Incident: UNKNOWN
Type of Incident No2: Not reported
Reported By: UNKNOWN
Reported By 2: Not reported
Owner ID: 00660100
Owner Name: LITTLE CAPITOL OF LOUISIANA, INC
Owner Address: 2939 GRAND POINT HWY
Owner City,St,Zip: BREAUX BRIDGE, LA 70517
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: Not reported

LA HIST LUST ASSESMENT:

Comments: SITE IS DIESI'S LITTLE CAPITAL, BREAUX BFIDGE, ST. MARTINPARISH. WAITING
RELEASE NOTIFICATION FORM.

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

Facility ID: 50-014643
Facility Parish: ST. MARTIN
Substance Name: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIESI'S LITTLE CAPITOL EXXON (Continued)

S106034241

Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 95-4-0044
Incident Date: Not reported
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00660100
Owner Name: LITTLE CAPITOL OF LOUISIANA, INC
Owner Address: 2939 GRAND POINT HWY
Owner City,St,Zip: BREAUX BRIDGE, LA 70517
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: Not reported

LA HIST LUST ASSESMENT:

Comments: SITE IS DIESI'S LITTLE CAPITAL, BREAUX BFIDGE, ST. MARTINPARISH. WAITING
RELEASE NOTIFICATION FORM.

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

SPILLS:

Name: DIESIS LITTLE CAPITOL EXXON
Address: 2939 Grand Point Hwy
City,State,Zip: LA 70517
Receive Date: 01/11/2021
Incident Date: 01/11/2021
Quantity: Not reported
Units: Not reported
Parameter: Not reported
Incident ID: 200574

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DIESI'S LITTLE CAPITOL EXXON (Continued)

S106034241

Other Description: Diesel
AI ID: 19443
Incident Status: Closed
Media Desc: Not reported
Location Description: 2939 Grand Point Hwy
Start Date: Not reported
Region: AR
Reporter Name: Dixie Santiny
Mailing Address: 2939 Grand Point Hwy
Mailing City: Breaux Bridge
Mailing State: LA
Mailing Zip: 70517
Organization Name: St Martin Sherif Office
Incident Desc: UST - AI# 19443. DIESEL. There was someone who was pumping gas & not watching it causing diesel spill The diesel has been stopped. No longer being released. Fire Department is en route to scene It was released inside ditch Updates to follow ..

Incident Type Desc: UST Release, Dispenser / Overfill
Comments: I contacted the St. Martin Parish Sheriff's Office who had contacted SPOC on 1/11/2021. I was routed to Mr. David Douget with the St. Martin Parish Fire District. Mr. Douget stated that his department responded after they received a call about 20 gallons of Diesel that had overflowed while a customer was pumping diesel. He stated that the Fire Dept. diked off the product and prevented it from entering storm drains or the ditch and they placed oil dry material over the fuel. They then turned it over to the facility to handle. He emailed the report from the incident. I then called Ms. Emma Calais, the store manager, to discuss the incident. She stated that she arrived at the store about 13 minutes after the spill occurred and due to the small size of the spill, she had placed absorbent pads and oil dry/kitty litter over the spill area prior to the Fire Department arriving. She stated that the spilled fuel did not leave the concrete or go into storm drains or ditches. She said she scraped the oil dry material up for disposal. Since this diesel spill was less than 25 gallons and was immediately cleaned up, it is non-reportable. This incident has been closed.

D10
East
< 1/8
0.100 mi.
526 ft.

FEDEX FREIGHT
2937 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

E MANIFEST 1032046066
N/A

Site 1 of 3 in cluster D

Relative:
Higher

Actual:
20 ft.

E MANIFEST:
Manifest Tracking Number: 011977808JJK
Last Updated Date: 20220719
Shipped Date: 20220708
Received Date: 20220714
Manifest Status: Signed
Submission Type: DataImage5Copy
Origin Type: Service
Generator EPA ID: LAR000102605
Generator Name: Fedex Freight
Generator Location Street Number: Not reported
Generator Location Street 1: 2937 GRAND POINT HWY
Generator Location Street 2: Not reported
Generator Location City: BREAUX BRIDGE
Generator Location State: LA

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDEX FREIGHT (Continued)

1032046066

Generator Location Zip: 70517
Generator Mail Street Number: Not reported
Generator Mail Street 1: 2937 GRAND POINT HWY
Generator Mail Street 2: Not reported
Generator Mail City: BREAUX BRIDGE
Generator Mail Zip: 70517
Generator Mail State: LA
Generator Contact Company Name: Not reported
Designated Facility EPA ID: LA0000365668
Designated Facility Name: Lei, Inc. - Hammond
Designated Facility Mail Street Number: Not reported
Designated Facility Mail Street 1: Not reported
Designated Facility Mail Street 2: PO BOX 550
Designated Facility Mail City: INDEPENDENCE
Designated Facility Mail Zip: 70443
Designated Facility Mail State: LA
Designated Facility Location Street Number: 46257
Designated Facility Location Street 1: MORRIS ROAD
Designated Facility Location Street 2: Not reported
Designated Facility Location City: HAMMOND
Designated Facility Location Zip: 70401
Designated Facility Location State: LA
Designated Facility Contact Company Name: Not reported
Manifest Residue Indicator: N
Rejection Indicator: N

Transporter:

Manifest Tracking Number: 011977808JJK
Transporter Line Number: 1
Transporter EPA ID: LAD482557357
Transporter Name: Ampol

Manifest Tracking Number: 011977808JJK
Transporter Line Number: 2
Transporter EPA ID: LAR000055467
Transporter Name: Lei, Inc.

Waste Line:

Manifest Tracking Number: 011977808JJK
Waste Line Number: 1
U.S. DOT Hazardous Indicator: Y
U.S. DOT ID Number: UN1268
U.S. DOT Description: Un1268, Waste Petroleum Distillates, N.O.S. , 3, Pgiii, Rq(D001)
[Crown Paint Thinner]

Non-Hazardous Waste Description: Not reported
Number of Containers: 1
Container Type Code: DM
Container Type Description: Metal drums, barrels, kegs
Waste Quantity: 200
Quantity Unit of Measure Code: P
Quantity Unit of Measure Description: Pounds
Waste Quantity, in Tons: 0.1
Acute Waste Quantity, in Tons: 0
Non-Acute Waste Quantity, in Tons: 0.1
Waste Quantity, in Kilograms: 90.703
Acute Waste Quantity, in Kilograms: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDEX FREIGHT (Continued)

1032046066

Non-Acute Waste Quantity, in Kilograms:	90.703
Management Method Code:	H141
Management Method Description:	STORAGE, BULKING AND/OR TRANSFER OFF SITE
Waste Residue Indicator:	N
Quantity Discrepancy Indicator:	N
Waste Type Discrepancy Indicator:	N
Waste Density:	Not reported
Waste Density Unit of Measure Code:	Not reported
Waste Density Unit of Measure Description:	Not reported
Form Code:	Not reported
Form Code Description:	Not reported
Source Code:	Not reported
Source Code Description:	Not reported
Waste Minimization Code:	Not reported
Waste Minimization Code Description:	Not reported
Consent Number:	Not reported
EPA Waste Indicator:	Y
Federal Waste Codes:	D001
Quantity Haz Kg:	90.703
Quantity Haz Tons:	0.1
Quantity Non Haz Kg:	0
Quantity Non Haz Tons:	0
State Waste Codes:	Not reported

D11
East
< 1/8
0.100 mi.
526 ft.

LITTLE CAPITOL OF LOUISIANA
2937 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

EDR Hist Auto **1021273049**
N/A

Site 2 of 3 in cluster D

Relative:
Higher

EDR Hist Auto

Actual:
20 ft.

Year:	Name:	Type:
1996	LITTLE CAPITAL OF LOUISIANA	Gasoline Service Stations, NEC
1997	LITTLE CAPITAL OF LOUISIANA	Gasoline Service Stations, NEC
1998	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
1999	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2000	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2001	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2002	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2003	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC
2004	LITTLE CAPITOL OF LOUISIANA	Gasoline Service Stations, NEC

D12
East
< 1/8
0.100 mi.
526 ft.

FEDEX FREIGHT INC
2937 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

RCRA-SQG **1027704406**
LAR000102605

Site 3 of 3 in cluster D

Relative:
Higher

RCRA Listings:

Actual:
20 ft.

Date Form Received by Agency:	20220609
Handler Name:	Fedex Freight Inc
Handler Address:	Grand Point Hwy
Handler City,State,Zip:	BREAUX BRIDGE, LA 70517
EPA ID:	LAR000102605
Contact Name:	YOLANDA MITCHELL

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDEX FREIGHT INC (Continued)

1027704406

Contact Address:	ALCOA RD
Contact City,State,Zip:	BENTON, AR 72015
Contact Telephone:	501-860-7904
Contact Fax:	Not reported
Contact Email:	YOLANDA.MITCHELL@FEDEX.COM
Contact Title:	Not reported
EPA Region:	06
Land Type:	Private
Federal Waste Generator Description:	Small Quantity Generator
Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	Not reported
State District:	Not reported
Mailing Address:	ALCOA RD
Mailing City,State,Zip:	BENTON, AR 72015
Owner Name:	Fedex Freight Inc
Owner Type:	Other
Operator Name:	Fedex Freight Inc
Operator Type:	Other
Short-Term Generator Activity:	Yes
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20230619
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDEX FREIGHT INC (Continued)

1027704406

Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	FEDEX FREIGHT INC
Legal Status:	Other
Date Became Current:	20220422
Date Ended Current:	Not reported
Owner/Operator Address:	2200 FORWARD DR DC 2219
Owner/Operator City,State,Zip:	HARRISON, AR 72601
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Operator
Owner/Operator Name:	FEDEX FREIGHT INC
Legal Status:	Other
Date Became Current:	20220422
Date Ended Current:	Not reported
Owner/Operator Address:	2200 FORWARD DR DC 2219
Owner/Operator City,State,Zip:	HARRISON, AR 72601
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20220609
Handler Name:	FEDEX FREIGHT INC
Federal Waste Generator Description:	Small Quantity Generator
State District Owner:	Not reported
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	No
Electronic Manifest Broker:	No

List of NAICS Codes and Descriptions:

NAICS Code:	484122
NAICS Description:	General Freight Trucking, Long-Distance, Less Than Truckload

Facility Has Received Notices of Violations:

Violations:	No Violations Found
-------------	---------------------

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FEDEX FREIGHT INC (Continued)

1027704406

Evaluation Action Summary:
Evaluations:

No Evaluations Found

13
SE
1/8-1/4
0.140 mi.
741 ft.

HENDERSON TRAVEL PLAZA & CASINO
2996 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

LUST **S108595821**
AUL **N/A**
SPILLS
NPDES
REM

Relative:
Lower
Actual:
17 ft.

LUST:

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 70537
Comments: UST

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 70537
Comments: UST

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 70537
Comments: UST

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 70537
Comments: UST

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 70537
Comments: UST

AUL:

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: Not reported
Type: Underground Storage Tanks
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Underground Storage Tanks
Custom Tank Desc: Not reported
Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

S108595821

Description: Not reported
PGS: Not reported
Document Link: Not reported

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility ID: Not reported
Type: Underground Storage Tanks
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Underground Storage Tanks
Custom Tank Desc: Not reported
Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported
Description: Not reported
PGS: Not reported
Document Link: Not reported

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility ID: Not reported
Type: Underground Storage Tanks
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Underground Storage Tanks
Custom Tank Desc: Not reported
Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported
Description: Not reported
PGS: Not reported
Document Link: Not reported

SPILLS:

Name: HENDERSON TRAVEL PLAZA
Address: 2996 Grand Point Hwy
City,State,Zip: BREAUx BRIDGE, LA
Receive Date: 05/26/2010
Incident Date: 05/26/2010
Quantity: 0
Units: 0
Parameter: 0
Incident ID: 123799
Other Description: Diesel
AI ID: 70537
Incident Status: Referred to USTD for TL Assignment
Media Desc: Soil
Location Description: Henderson Travel Plaza 2996 Grand Point Hwy Breaux Bridge

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

S108595821

Start Date: 05/27/2010
Region: AR
Reporter Name: Not reported
Mailing Address: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Organization Name: Henderson Travel Plaza & Casino
Incident Desc: - Referred to USTD for TL Assignment
Incident Type Desc: UST Release, Piping / Physical or Mechanical Damage
Comments: 1. Performed a follow up visit for Incident No. T123324 and upon arriving at the facility on May 26, 2010, the facility manager (Ms. Adrian Bailey) informed me that they just discovered another leak in the piping between the auto diesel STP and dispenser. 2. The leak occurred in the portion of piping between the auto diesel STP and auto diesel dispenser. 3. Free product was removed from the sumps (approximately 50 gal of diesel/water mix). 4. It was not evident until the cement slab around the island and STP was removed but at that time a sheen was noted on the ground. 5. This incident will be referred to LDEQ USTD for further review. 6. CONFIRMED RELEASE DATE = 05/26/2010

Name: LOBDELL VENTURES
Address: 2996 Grand Point Hwy
City,State,Zip: BREAUx BRIDGE, LA
Receive Date: 01/20/2009
Incident Date: 01/20/2009
Quantity: 0
Units: 0
Parameter: 0
Incident ID: 112151
Other Description: 0
AI ID: 70537
Incident Status: Closed
Media Desc: Soil
Location Description: Lobdell Ventures Henderson Travel Plaza 2996 Grand Point Hwy Breaux Bridge, LA

Start Date: Not reported
Region: Not reported
Reporter Name: Not reported
Mailing Address: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Organization Name: Henderson Travel Plaza & Casino
Incident Desc: 0
Incident Type Desc: Not reported
Comments: Not reported

Name: USA TRUCK STOP
Address: 2996 Grand Point Hwy
City,State,Zip: BREAUx BRIDGE, LA
Receive Date: 04/20/2004
Incident Date: 04/20/2004
Quantity: Not reported
Units: Not reported
Parameter: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

S108595821

Incident ID: 69621
Other Description: Not reported
AI ID: 70537
Incident Status: Referred to Remediation
Media Desc: Soil
Location Description: USA Truck Stop 2996 Grand Point Hwy, Breaux Bridge
Start Date: Not reported
Region: Not reported
Reporter Name: Not reported
Mailing Address: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Organization Name: Henderson Travel Plaza
Incident Desc: s04-1461 pin hole in a secondary line on an underground tank at a truck stop.....gkh
Incident Type Desc: Not reported
Comments: Not reported

Name: CITGO ACHAFALAYA GOLD
Address: 2996 Grand Point Hwy
City,State,Zip: BREAUX BRIDGE, LA
Receive Date: 04/14/2009
Incident Date: 04/14/2009
Quantity: 0
Units: 0
Parameter: 0
Incident ID: 114160
Other Description: 0
AI ID: 70537
Incident Status: Closed
Media Desc: Water
Location Description: Citgo Achafalaya Gold 2996 Grand Point Hwy Breaux Bridge
Start Date: Not reported
Region: Not reported
Reporter Name: Not reported
Mailing Address: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Organization Name: Henderson Travel Plaza & Casino
Incident Desc: This was in response to a citizen complaint of used oil being released on groun and in ditch, at Henderson Travel Plaza, Breaux Bridge. Arrived on site and contacted Mr. Amin Amlani (owner). DEQ personnel and Mr. Amlani conducted a walkthrough of the facility and no release of use oil was observed.
Incident Type Desc: Not reported
Comments: Not reported

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 Grand Point Hwy
City,State,Zip: HENDERSON, LA 70517
Receive Date: 03/12/2012
Incident Date: 03/12/2012
Quantity: Not reported
Units: Unknown quantity
Parameter: Diesel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

S108595821

Incident ID: 138094
Other Description: Not reported
AI ID: 70537
Incident Status: Closed
Media Desc: Water/Soil
Location Description: USA Truck Stop I-10 Exit 115 Henderson
Start Date: Not reported
Region: AR
Reporter Name: Stacy Eddie
Mailing Address: 400 Travis St Ste 1006
Mailing City: Shreveport
Mailing State: LA
Mailing Zip: 71101
Organization Name: St. Martin Parish SO
Incident Desc: s12-5427 UST - Diesel flowing offsite due to heavy rains. col
Incident Type Desc: Release/Spill, Oil Sheen/Spill
Comments: 3/12/12 - Notified of estimated sheen reported as 1/2 acre along flood waters suspected coming from USA Truck Stop in Henderson, LA just off I-10 EB Exit 115. Responded to incident. Heavy rains occurred causing flooding of businesses and roads in Henderson, LA just off of I-10 . Off ramp and Grand Point Hwy flooded with est 6 - 10 inches of water. Sheen was observed on waters surface and noticeable diesel odor was present. Henderson Truck Plaza (Texaco) / USA Truck Stop Signage on large sign seen from interstate. Site visit to facility and met with Erica Living, Manager. Facility checked for additional sheen and free phase fuel. Discovered free phase fuel and sheen originating from oil/water separator. Inside oil/water separator found to be full of diesel. Sheen seen leaving location with lite free phase diesel seen on water surrounding sump/separator in est 5 - 10 ft. Suspected flood waters were at one time above covered separator/sump. Currently sides of separator/sump above water line. Suggested facility have oil/water separator emptied to end potential for further release. Jones Environmental contacted for response to check for possible leaks and arrange vac truck and absorbents to respond to incident. Site visit planned for 3/13/12 to check on cleanup and containment measures. 3/13/2012 - Site revisited to perform visual assessment of incident location and assess cleanup measures by Jones Environmental. Vac truck yet to arrive on location and diesel still present in oil/water separator/sump. Flood waters receding with sheen still present along location parking lot, neighboring ditch off of I-10 off ramp. Staining seen on soil and vegetation at sump location in est 30 ft x 10 ft area. Requested from Manager, Mrs. Erica Living, the last known date that oil/water separator/sump was emptied, as well as last date that facility had line/leak tightness testing. Last documented tightness testing was shown to have been conducted on 4/4/2011 and showed
(Continued)

NPDES:

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 70537
Facility Phone: (337) 332-2090
Issued Date: 09/08/2008
Title Description: Gen Sanit Permit - LAG541665
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

S108595821

Activity Number: GEN20080001
Effective Date: 09/08/2008
Expiration Date: 06/30/2013
Permit Number: LAG541665
Mailing Address: 400 Travis St Ste 1006 Shreveport, LA 71101
Effective Flag: N

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility Id: 70537
Facility Phone: (337) 507-3440
Issued Date: 10/19/2018
Title Description: LAG54 Reauthorization
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20180001
Effective Date: 10/19/2018
Expiration Date: 07/31/2023
Permit Number: LAG541665
Mailing Address: 400 Travis St Ste 1006 Shreveport, LA 71101
Effective Flag: Y

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility Id: 70537
Facility Phone: (337) 332-2090
Issued Date: 05/16/2014
Title Description: Renewed Coverage
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20130001
Effective Date: 05/16/2014
Expiration Date: 06/30/2018
Permit Number: LAG541665
Mailing Address: 400 Travis St Ste 1006 Shreveport, LA 71101
Effective Flag: N

REM:

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUx BRIDGE, LA 70517
AI Num: 70537
Evaluated And Closed: 06/06/2001
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Completion NFA w/ BOD
Comments: NFA-BOD; Alps ID # 18797720

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUx BRIDGE, LA 70517
AI Num: 70537

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON TRAVEL PLAZA & CASINO (Continued)

S108595821

Evaluated And Closed: 01/05/2007
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Investigation NFA w/ BOD
Comments: EDMS ID 3167220

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUX BRIDGE, LA 70517
AI Num: 70537
Evaluated And Closed: 01/31/2007
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Investigation NFA w/ BOD
Comments: Not reported

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUX BRIDGE, LA 70517
AI Num: 70537
Evaluated And Closed: 07/08/2009
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Comfort Letter
Comments: Not reported

Name: HENDERSON TRAVEL PLAZA & CASINO
Address: 2996 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUX BRIDGE, LA 70517
AI Num: 70537
Evaluated And Closed: 12/20/2011
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 8223139.

14
West
1/8-1/4
0.143 mi.
757 ft.

CECILIA FIELD COMMINGLING FACILITY
ON HWY 347 1.3 MI S OF
CECILIA, LA 70521

DEL SHWS **1004515259**
ICIS **N/A**
US AIRS
AIRS
REM

Relative:
Higher

Actual:
23 ft.

DEL SHWS:
Name: CECILIA FIELD COMMINGLING FACILITY
Address: ON HWY 347 1.3 MI S OF
City,State,Zip: CECILIA, LA 70521
Program: Potential
EAC Type: REM-Issue NFA
AI #: 13117
Evaluated And Closed: 01/08/2025
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

ICIS:

Enforcement Action ID: LA000A0000220990001800017
FRS ID: 110007037642
Action Name: CECILIA FIELD COMMINGLING FACILITY 220990001800017
Facility Name: CECILIA FIELD COMMINGLING FACILITY
Facility Address: ON HWY 347 1.3 MI S OF
CECILIA, LA 70521
Enforcement Action Type: Administrative Order
Facility County: ST. MARTIN
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 1311
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.31632
Longitude in Decimal Degrees: -91.84652
Permit Type Desc: Not reported
Program System Acronym: LA0000002209900018
Facility NAICS Code: 211111
Tribal Land Code: Not reported

Enforcement Action ID: LA000A0000220990001800016
FRS ID: 110007037642
Action Name: CECILIA FIELD COMMINGLING FACILITY 220990001800016
Facility Name: CECILIA FIELD COMMINGLING FACILITY
Facility Address: ON HWY 347 1.3 MI S OF
CECILIA, LA 70521
Enforcement Action Type: Administrative Order
Facility County: ST. MARTIN
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 1311
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.31632
Longitude in Decimal Degrees: -91.84652
Permit Type Desc: Not reported
Program System Acronym: LA0000002209900018
Facility NAICS Code: 211111
Tribal Land Code: Not reported

Enforcement Action ID: LA000A0000220990001800008
FRS ID: 110007037642
Action Name: CECILIA FIELD COMMINGLING FACILITY 220990001800008
Facility Name: CECILIA FIELD COMMINGLING FACILITY
Facility Address: ON HWY 347 1.3 MI S OF
CECILIA, LA 70521
Enforcement Action Type: Notice of Violation
Facility County: ST. MARTIN
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: NOV
Facility SIC Code: 1311
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.31632
Longitude in Decimal Degrees: -91.84652
Permit Type Desc: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Program System Acronym: LA0000002209900018
Facility NAICS Code: 211111
Tribal Land Code: Not reported

Enforcement Action ID: 06-2005-A065
FRS ID: 110007037642
Action Name: CECILIA FIELD COMMINGLING FACILITY 220990001800009
Facility Name: CECILIA FIELD COMMINGLING FACILITY
Facility Address: ON HWY 347 1.3 MI S OF
CECILIA, LA 70521

Enforcement Action Type: CAA 113D1 Action For Penalty
Facility County: ST. MARTIN
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 113D1
Facility SIC Code: 1311
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.31632
Longitude in Decimal Degrees: -91.84652
Permit Type Desc: Not reported
Program System Acronym: LA0000002209900018
Facility NAICS Code: 211111
Tribal Land Code: Not reported

US AIRS MINOR:

Envid: 1004515259
Region Code: 06
Programmatic ID: AIR LA0000002209900018
Facility Registry ID: 110007037642
D and B Number: Not reported
Primary SIC Code: 1311
NAICS Code: 211111
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF
Air CMS Category Code: Not reported
HPV Status: Not reported

US AIRS MINOR:

Region Code: 06
Programmatic ID: AIR LA0000002209900018
Facility Registry ID: 110007037642
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1990-09-11 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002209900018
Facility Registry ID: 110007037642
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Activity Date:	1992-08-14 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	06
Programmatic ID:	AIR LA0000002209900018
Facility Registry ID:	110007037642
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1994-08-16 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	06
Programmatic ID:	AIR LA0000002209900018
Facility Registry ID:	110007037642
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1994-08-19 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	06
Programmatic ID:	AIR LA0000002209900018
Facility Registry ID:	110007037642
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1996-02-28 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	06
Programmatic ID:	AIR LA0000002209900018
Facility Registry ID:	110007037642
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1997-02-12 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported
Region Code:	06
Programmatic ID:	AIR LA0000002209900018
Facility Registry ID:	110007037642

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2003-11-19 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002209900018
Facility Registry ID: 110007037642
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-05-09 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002209900018
Facility Registry ID: 110007037642
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-07-27 00:00:00
Activity Status Date: 2005-07-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Formal
Activity Status: Final Order Issued

Region Code: 06
Programmatic ID: AIR LA0000002209900018
Facility Registry ID: 110007037642
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2005-07-27 00:00:00
Activity Status Date: 2005-07-27 00:00:00
Activity Group: Enforcement Action
Activity Type: Administrative - Informal
Activity Status: Achieved

AIRS:

Name: CECILIA FIELD COMMINGLING FACILITY
Address: ON HWY 347 1.3 MI S OF
Address 2: 1.3 Mi S of
Address 3: Not reported
City,State,Zip: CECILIA, LA 70521
Latitude: 30
Longitude: 91.84652200
AI No#: 13117
Region Code: Acadiana

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Permits:

Permit Number: 2620-00018-00
Permit Type Desc: State permit (unspecified)
Activity No#: PER19880001
Title Desc: CECILIA COMM. FAC.
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 10/18/1988
Expiration Date: 07/22/2003
Effective End Date: 07/22/2003
Effective Flag: N
Extended Flag: N

Permit Number: 2620-00018-00
Permit Type Desc: State permit (unspecified)
Activity No#: PER19880001
Title Desc: CECILIA COMM. FAC.
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 10/18/1988
Expiration Date: 07/22/2003
Effective End Date: 07/22/2003
Effective Flag: N
Extended Flag: N

Permit Number: 2620-00018-01
Permit Type Desc: Minor Source/Small Source Mod
Activity No#: PER19970001
Title Desc: Per/entire facility
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 07/22/2003
Expiration Date: 03/15/2007
Effective End Date: 03/15/2007
Effective Flag: N
Extended Flag: N

Permit Number: 2620-00018-01
Permit Type Desc: Minor Source/Small Source Mod
Activity No#: PER19970001
Title Desc: Per/entire facility
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 07/22/2003
Expiration Date: 03/15/2007
Effective End Date: 03/15/2007
Effective Flag: N
Extended Flag: N

Permit Number: 2620-00018-01
Permit Type Desc: SOGA Permit Modification
Activity No#: PER20070001
Title Desc: Permit 2620-00018-01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 03/16/2007
Expiration Date: 10/20/2012
Effective End Date: 10/20/2012
Effective Flag: N
Extended Flag: N

Permit Number: 2620-00018-01
Permit Type Desc: SOGA Permit Modification
Activity No#: PER20070001
Title Desc: Permit 2620-00018-01
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 03/16/2007
Expiration Date: 10/20/2012
Effective End Date: 10/20/2012
Effective Flag: N
Extended Flag: N

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/15/2020
Effective End Date: 05/13/2021
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Permit Number: 2620-00018-02
Permit Type Desc: Minor Gen Permit-Oil and Gas Initial
Activity No#: PER20120001
Title Desc: MSOG Initial
Mailing Address: PO Box 52584
Mailing Address2: Not reported
Mailing City/State/Zip: Lafayette, LA 705052584
Issue Date: 11/20/2012
Expiration Date: 09/16/2030
Effective End Date: 06/02/2023
Effective Flag: Y
Extended Flag: Y

Emissions:

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2019
Parameter Description: Carbon monoxide
Total: 1.05
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2019
Parameter Description: Nitrogen oxides
Total: 1.25
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2019
Parameter Description: Particulate matter (10 microns or less)

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Total:	0.10000000
Unit:	tons
Pollutant Name:	Not reported
Primary SIC Code:	1311
Primary NACIS Code:	211111
Owner Name:	J P Oil Co Inc
Reporting Year:	2019
Parameter Description:	Particulate matter (2.5 microns or less)
Total:	0.10000000
Unit:	tons
Pollutant Name:	Not reported
Primary SIC Code:	1311
Primary NACIS Code:	211111
Owner Name:	J P Oil Co Inc
Reporting Year:	2019
Parameter Description:	VOC, Total
Total:	11.7899999
Unit:	tons
Pollutant Name:	Not reported
Primary SIC Code:	1311
Primary NACIS Code:	211111
Owner Name:	J P Oil Co Inc
Reporting Year:	2018
Parameter Description:	Carbon monoxide
Total:	0.21
Unit:	tons
Pollutant Name:	Not reported
Primary SIC Code:	1311
Primary NACIS Code:	211111
Owner Name:	J P Oil Co Inc
Reporting Year:	2018
Parameter Description:	Nitrogen oxides
Total:	0.25
Unit:	tons
Pollutant Name:	Not reported
Primary SIC Code:	1311
Primary NACIS Code:	211111
Owner Name:	J P Oil Co Inc
Reporting Year:	2018
Parameter Description:	Particulate matter (10 microns or less)
Total:	0.02
Unit:	tons
Pollutant Name:	Not reported
Primary SIC Code:	1311
Primary NACIS Code:	211111
Owner Name:	J P Oil Co Inc
Reporting Year:	2018
Parameter Description:	Particulate matter (2.5 microns or less)
Total:	0.02
Unit:	tons
Pollutant Name:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2018
Parameter Description: VOC, Total
Total: 3.35
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: Carbon monoxide
Total: 1.05
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: Nitrogen oxides
Total: 1.25
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: Particulate matter (10 microns or less)
Total: 0.1
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: Particulate matter (2.5 microns or less)
Total: 0.1
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: PM Condensable
Total: 0.07
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Reporting Year: 2021
Parameter Description: PM10 Filterable
Total: 0.025
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: PM2.5 Filterable
Total: 0.025
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211120
Owner Name: J P Oil Co Inc
Reporting Year: 2021
Parameter Description: VOC, Total
Total: 11.6
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2020
Parameter Description: Carbon monoxide
Total: 1.05
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2020
Parameter Description: Nitrogen oxides
Total: 1.25
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2020
Parameter Description: PM Condensable
Total: 5.00000000
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2020
Parameter Description: PM10 Filterable
Total: 0

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1004515259

Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2020
Parametter Description: PM2.5 Filterable
Total: 0
Unit: tons
Pollutant Name: Not reported

Primary SIC Code: 1311
Primary NACIS Code: 211111
Owner Name: J P Oil Co Inc
Reporting Year: 2020
Parametter Description: VOC, Total
Total: 10.3199999
Unit: tons
Pollutant Name: Not reported

REM:

Name: CECILIA FIELD COMMINGLING FACILITY
Address: ON HWY 347 1.3 MI S OF
Address 2: Not reported
City,State,Zip: CECILIA, LA 70521
Al Num: 13117
Evaluated And Closed: 01/08/2025
Program: Potential
Activity Description: Not reported
Title Description: Not reported
EAC Type: REM-Issue NFA
Comments: Not reported

15
West
1/8-1/4
0.181 mi.
957 ft.

CECILIA FIELD COMMINGLING FACILITY
ON HWY 347 OFF MELVIN DUPUIS R
CECILIA, LA 70521

PFAS ECHO 1027338566
N/A

Relative:
Higher
Actual:
22 ft.

PFAS ECHO:
Facility ID: 110007037642
Name: Cecilia Field Commingling Facility
Address: ON HWY 347 OFF MELVIN DUPUIS R
City,State,Zip: CECILIA, LA 70521
Latitude: 30.31632
Longitude: -91.84652
Count: 1
County: ST MARTIN
Status: Active
Region: 06
Industry: Oil and Gas

[ECHO Facility Report:](#)

Facility Percent Minority: 32.198
Facility Derived Tribes: -
Facility Population: 337.34

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

CECILIA FIELD COMMINGLING FACILITY (Continued)

1027338566

EPA Programs:	CAA
Federal Facility:	No
Federal Agency:	-
Facility FIPS Code:	22099
Facility Indian Country Flag:	N
Facility Collection Method:	CLASSICAL SURVEYING TECHNIQUES
Facility Derived HUC:	08080102
Facility Derived WBD:	080801020702
Facility Derived CD113:	03
Facility Derived CB2010:	220990203011039
Facility Major Flag:	-
Facility Active Flag:	Y
Facility Inspection Count:	1
Facility Date Last Inspection:	1/21/2022
Facility Days Last Inspection:	1,247
Facility Informal Count:	0
Facility Date Last Informal Action:	7/27/2005
Facility Formal Action Count:	0
Facility Date Last Formal Action:	7/27/2005
Facility Total Penalties:	0
Facility Penalty Count:	-
Facility Date Last Penalty:	7/27/2005
Facility Last Penalty AMT:	500
Facility QTRS With NC:	0
Facility Programs With SNC:	0
Facility Compliance Status:	No Violation Identified
Facility SNC Flag:	N
AIR Flag:	Y
NPDES Flag:	N
SDWIS Flag:	N
RCRA Flag:	N
TRI Flag:	N
GHG Flag:	N
AIR IDS:	LA0000002209900018
CAA Permit Types:	Minor Emissions
CAA NAICS:	211111 211120
CAA SICS:	1311
NPDES IDS:	-
CWA Permit Types:	-
CWA NAICS:	-
CWA SICS:	-
RCRA IDS:	-
RCRA Permit Types:	-
RCRA NAICS:	-
SDWA IDS:	-
SDWA System Types:	-
SDWA Compliance Status:	-
SDWA SNC Flag:	N
TRI IDS:	-
TRI Releases Transfers:	-
TRI On Site Releases:	-
TRI Off Site Transfers:	-
TRI Reporter:	-
Facility IMP Water Flag:	-

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

E16
SSE
1/8-1/4
0.203 mi.
1070 ft.

VED'S 5 LLC
3002 GRAND POINT HWY
HENDERSON, LA 70517

Site 1 of 2 in cluster E

UST **U003194860**
N/A

Relative:
Higher

UST:

Actual:
21 ft.

Name: VED'S 5 LLC
Address: 3002 GRAND POINT HWY
Address 2: Not reported
City: HENDERSON
Master Agency Id: 79336
Subject Item ID: 1

UST Tank Num: 51107
Tank Status: **Active**
Install Date: 04/30/1997
Total Capacity: 12000
Number Of Compartments: 1
Gasoline: Yes
Diesel: Not reported
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported
Steel Tank Covered With Asphalt: Not reported
Cathodically Protected: Not reported
Epoxy Coated Tank: Not reported
A Composite Of Different Materials: Yes
Fiberglass Or Plastic: Y
Interior Line With Some Material: Not reported
Double Wall As Opposed To Single Wall: Not reported
Outside Lined w/ Polyethylen Jacket: Not reported
Made Of Concrete: Not reported
Liner Covering Excavation Hole: Not reported
Other Material: Not reported
Pipe Method Description: Pressure
Subject item desc: 51107-gasoline
Service change date: Not reported
Last service date: 08/26/1997
Current status start date: 08/25/1997
Current status end date: Not reported
Emer gen fuel only flag: Not reported
Tank inert material desc: Not reported
Mct fibrgls plastic: Not reported
Mcp bare steel: Not reported
Mcp galvanized steel: Not reported
Mcp part stl fbrgls lines: Not reported
Mcp copper: Not reported
Mcp double walled: Not reported
Mcp secondary contain: Not reported
Mcp unknown: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VED'S 5 LLC (Continued)

U003194860

Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	08/26/1997
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	04/03/1997
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	07/01/1997
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	08/21/1997
Install alt certificate num:	IRC-0090
Install cert worker name:	Randy Hall
Install cert worker emp name:	R. L. Hall & Associates, Inc.
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Y
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/25/1997
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VED'S 5 LLC (Continued)

U003194860

Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	51108
Tank Status:	Active
Install Date:	04/30/1997
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Yes
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	51108-gasoline
Service change date:	Not reported
Last service date:	08/26/1997
Current status start date:	08/25/1997
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VED'S 5 LLC (Continued)

U003194860

Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	08/26/1997
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	04/03/1997
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	07/01/1997
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	08/21/1997
Install alt certificate num:	IRC-0090
Install cert worker name:	Randy Hall
Install cert worker emp name:	R. L. Hall & Associates, Inc.
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Y
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/25/1997
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VED'S 5 LLC (Continued)

U003194860

UST Tank Num:	51109
Tank Status:	Active
Install Date:	04/30/1997
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	51109-diesel
Service change date:	Not reported
Last service date:	08/26/1997
Current status start date:	08/25/1997
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

VED'S 5 LLC (Continued)

U003194860

Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	08/26/1997
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	04/03/1997
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	07/01/1997
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	08/21/1997
Install alt certificate num:	IRC-0090
Install cert worker name:	Randy Hall
Install cert worker emp name:	R. L. Hall & Associates, Inc.
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Y
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/25/1997
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

E17
SSE
1/8-1/4
0.203 mi.
1070 ft.
VED'S 5 LLC
3002 GRAND POINT HWY
HENDERSON, LA 70517
Site 2 of 2 in cluster E

LUST
SPILLS
REM
S112659298
N/A

Relative:
Higher

LUST:

Actual:
21 ft.

Name: VED'S 5 LLC
Address: 3002 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility ID: 79336
Comments: UST

SPILLS:

Name: MYERS QUICKSTOP
Address: 3002 Grand Point Hwy
City,State,Zip: BREAUX BRIDGE, LA 70517
Receive Date: 02/12/2017
Incident Date: 02/12/2017
Quantity: Not reported
Units: Not reported
Parameter: Not reported
Incident ID: 175937
Other Description: Not reported
AI ID: 79336
Incident Status: Closed
Media Desc: Not reported
Location Description: 3002 Grandpoint Hwy ; BreauX Bridge
Start Date: Not reported
Region: AR
Reporter Name: Eric Myers
Mailing Address: 3002 Grand Point Hwy
Mailing City: Henderson
Mailing State: LA
Mailing Zip: 70517
Organization Name: CHEVRON STATION
Incident Desc: s17-92648 UST - customer's fuel tank leaked during gasoline fill-up.
col
Incident Type Desc: UST Release, Dispenser / Spill
Comments: I spoke with Eric Myers on Thursday February 16, 2017. He indicated that a small amount of gasoline (maybe 1/2 gallon) had spilled during an overfill at the station. Spilled product was picked up with absorbent material and the entire spill was contained to the pavement.

REM:

Name: VED'S 5 LLC
Address: 3002 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: HENDERSON, LA 70517
AI Num: 79336
Evaluated And Closed: 07/16/2007
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Real Estate Transaction NFA
Comments: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F18
SE
1/8-1/4
0.203 mi.
1073 ft.

HENDERSON I-10 EXXON
2987 GRAND POINT HWY
BREAUX BRIDGE, LA 70517

Site 1 of 2 in cluster F

LUST
AUL
SPILLS
NPDES
REM

S111284577
N/A

Relative:
Higher

Actual:
20 ft.

LUST:

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 23599
Comments: UST

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 23599
Comments: UST

AUL:

Name: AYRRAYN INTERNATIONAL INC - HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: Not reported
Type: Underground Storage Tanks
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Underground Storage Tanks
Custom Tank Desc: Not reported
Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported
Description: Not reported
PGS: Not reported
Document Link: Not reported

SPILLS:

Name: AYRRAYN INTERNATIONAL INC - HENDERSON I-10 EXXON
Address: 2987 Grand Point Hwy
City,State,Zip: BREAUX BRIDGE, LA 70517
Receive Date: 07/03/2017
Incident Date: 07/03/2017
Quantity: Not reported
Units: Not reported
Parameter: Not reported
Incident ID: 178675
Other Description: Not reported
AI ID: 23599
Incident Status: Pending Review
Media Desc: Soil
Location Description: Ayrran-Henderson I-10 Exxon 2987 Grand Point Hwy BreauX Bridge
Start Date: Not reported
Region: AR
Reporter Name: Shawn King
Mailing Address: 738 N Bryan St

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

S111284577

Mailing City: Merryville
Mailing State: LA
Mailing Zip: 70653
Organization Name: JONES ENVIRONMENTAL, INC.
Incident Desc: s17-98932 UST - Regular tank# 2 took on water & failed tightness test.
col
Incident Type Desc: UST, Tank Tightness Test Failure
Comments: Left a message for Shawn King on July 6, 2017. I spoke with him on July 7, 2017 and requested they do a site check. I contacted him again on August 10, 2017 to check on the status of the site check. He indicated they has scheduled one to be completed in September. I spoke with him again on October 10, 2017. He indicated the site check had been completed approximately two weeks prior. He was waiting on final results, because he'd requested SPLP and fractions be run, but he confirmed that they did encounter a small amount of product in one of the borings. He stated he would forward the final results to me as soon as he received them. Confirmed Release Date = October 10, 2017

NPDES:

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility Id: 23599
Facility Phone: (337) 332-4833
Issued Date: 02/21/2018
Title Description: LAG53 Reauthorization
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20170001
Effective Date: 02/21/2018
Expiration Date: 11/30/2022
Permit Number: LAG533881
Mailing Address: 2987 Grand Point Hwy Breaux Bridge, LA 70517
Effective Flag: Y

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility Id: 23599
Facility Phone: (337) 332-4833
Issued Date: 10/06/2011
Title Description: Permit
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20110001
Effective Date: 10/06/2011
Expiration Date: 11/30/2012
Permit Number: LAG533881
Mailing Address: 2987 Grand Point Hwy Breaux Bridge, LA 70517
Effective Flag: N

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility Id: 23599
Facility Phone: (337) 332-4833
Issued Date: 07/01/2013

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

S111284577

Title Description: Renewal
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20120001
Effective Date: 07/01/2013
Expiration Date: 11/30/2017
Permit Number: LAG533881
Mailing Address: 2987 Grand Point Hwy Breaux Bridge, LA 70517
Effective Flag: N

REM:

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUX BRIDGE, LA 70517
AI Num: 23599
Evaluated And Closed: 05/12/2009
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 6435056

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUX BRIDGE, LA 70517
AI Num: 23599
Evaluated And Closed: 05/13/2020
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Completion NFA w/ BOD
Comments: Not reported

F19
SE
1/8-1/4
0.203 mi.
1073 ft.

HENDERSON I-10 EXXON
2987 GRAND POINT
HENDERSON, LA 70517
Site 2 of 2 in cluster F

RCRA-VSQG **1004711784**
UST **LAD985213164**

Relative:
Higher
Actual:
20 ft.

RCRA Listings:
Date Form Received by Agency: 19911217
Handler Name: Henderson I-10 Exxon
Handler Address: Grand Point
Handler City,State,Zip: HENDERSON, LA 70517
EPA ID: LAD985213164
Contact Name: AMIN AMLANI
Contact Address: GRAND POINT HWY
Contact City,State,Zip: BREAUX BRIDGE, LA 70517
Contact Telephone: 337-332-4833
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: Not reported
EPA Region: 06
Land Type: Private
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Non-Notifier:	Not reported
Biennial Report Cycle:	Not reported
Accessibility:	Not reported
Active Site Indicator:	Handler Activities
State District Owner:	La
State District:	AC
Mailing Address:	GRAND POINT HWY
Mailing City,State,Zip:	BREAUX BRIDGE, LA 70517
Owner Name:	Chester Lormand
Owner Type:	Private
Operator Name:	Not reported
Operator Type:	Not reported
Short-Term Generator Activity:	No
Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility Activity:	No
Recycler Activity with Storage:	No
Small Quantity On-Site Burner Exemption:	No
Smelting Melting and Refining Furnace Exemption:	No
Underground Injection Control:	No
Off-Site Waste Receipt:	No
Universal Waste Indicator:	No
Universal Waste Destination Facility:	No
Federal Universal Waste:	No
Active Site State-Reg Handler:	---
Federal Facility Indicator:	Not reported
Hazardous Secondary Material Indicator:	N
Sub-Part K Indicator:	Not reported
2018 GPRA Permit Baseline:	Not on the Baseline
2018 GPRA Renewals Baseline:	Not on the Baseline
202 GPRA Corrective Action Baseline:	No
Subject to Corrective Action Universe:	No
Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20090219
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Waste Code:	D006
Waste Description:	Cadmium
Waste Code:	D008
Waste Description:	Lead
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichloroethylene

Handler - Owner Operator:

Owner/Operator Indicator:	Owner
Owner/Operator Name:	HENDERSON I-10 EXXON
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 159
Owner/Operator City,State,Zip:	BREAUX BRIDGE, LA 70517
Owner/Operator Telephone:	337-332-4833
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	CHESTER LORMAND
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	PO BOX 159
Owner/Operator City,State,Zip:	BREAUX BRIDGE, LA 70517
Owner/Operator Telephone:	337-363-4426
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	19911217
Handler Name:	HENDERSON I-10 EXXON
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator)
State District Owner:	La
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes
Non Storage Recycler Activity:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Code: 44111
NAICS Description: New Car Dealers

NAICS Code: 811111
NAICS Description: General Automotive Repair

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

UST:

Name: HENDERSON I-10 EXXON
Address: 2987 GRAND POINT HWY
Address 2: Not reported
City: BREAUX BRIDGE
Master Agency Id: 23599
Subject Item ID: 1

UST Tank Num: 11455
Tank Status: **Active**
Install Date: 04/12/1981
Total Capacity: 10000
Number Of Compartments: 1
Gasoline: Yes
Diesel: Not reported
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported
Steel Tank Covered With Asphalt: Not reported
Cathodically Protected: Yes
Epoxy Coated Tank: Not reported
A Composite Of Different Materials: Not reported
Fiberglass Or Plastic: Y
Interior Line With Some Material: Not reported
Double Wall As Opposed To Single Wall: Not reported
Outside Lined w/ Polyethylen Jacket: Not reported
Made Of Concrete: Not reported
Liner Covering Excavation Hole: Not reported
Other Material: Not reported
Pipe Method Description: Pressure
Subject item desc: 11455-gasoline

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Service change date:	Not reported
Last service date:	Not reported
Current status start date:	09/05/2017
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	10/01/1989
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/08/1998
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Y
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	12/14/1998
Install alt certificate num:	IRC-0202
Install cert worker name:	JOHN WALLACE
Install cert worker emp name:	R.L. HALL & ASSOCIATES
Install cert by mfr flag:	Y
Install insp by reg eng flag:	N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Install insp by dept flag:	N
Install mfr chkfst comp flag:	Y
Install cert alt method flag:	N
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	09/05/2017
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	05/01/2005
UST Tank Num:	11456
Tank Status:	Temp Out of Service
Install Date:	04/12/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Yes
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	11456-gasoline, temp-out-of-service
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	07/03/2017
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fibrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	10/01/1989
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/08/1998
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Y
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	12/14/1998
Install alt certificate num:	IRC-0202
Install cert worker name:	JOHN WALLACE
Install cert worker emp name:	R.L. HALL & ASSOCIATES
Install cert by mfr flag:	Y
Install insp by reg eng flag:	N
Install insp by dept flag:	N
Install mfr chklst comp flag:	Y
Install cert alt method flag:	N
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	05/02/1986
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	07/03/2017
UST Tank Num:	11457
Tank Status:	Active
Install Date:	04/12/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Yes
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	11457-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	09/05/2017
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fibrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	10/01/1989
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/08/1998
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Y
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	12/14/1998
Install alt certificate num:	IRC-0202
Install cert worker name:	JOHN WALLACE
Install cert worker emp name:	R.L. HALL & ASSOCIATES
Install cert by mfr flag:	Y
Install insp by reg eng flag:	N
Install insp by dept flag:	N
Install mfr chklst comp flag:	Y
Install cert alt method flag:	N
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	09/05/2017
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	05/01/2005

UST Tank Num:	11458
Tank Status:	Active
Install Date:	04/12/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	11458-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	09/05/2017
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fibrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Not reported
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

HENDERSON I-10 EXXON (Continued)

1004711784

Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	10/01/1989
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	12/08/1998
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Y
Cpt cathodic protect:	Y
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	Not reported
Cpp fibrgls plastic:	Not reported
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	12/14/1998
Install alt certificate num:	IRC-0202
Install cert worker name:	JOHN WALLACE
Install cert worker emp name:	R.L. HALL & ASSOCIATES
Install cert by mfr flag:	Y
Install insp by reg eng flag:	N
Install insp by dept flag:	N
Install mfr chklst comp flag:	Y
Install cert alt method flag:	N
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	09/05/2017
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	05/01/2005

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

G20
SE
1/8-1/4
0.223 mi.
1177 ft.
BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #1
2999 GRAND POINT HWY
HENDERSON, LA 70517
Site 1 of 5 in cluster G

UST **U003987674**
N/A

Relative:
Lower

UST:

Actual:
17 ft.

Name:	BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10
Address:	2999 GRAND POINT HWY
Address 2:	Not reported
City:	HENDERSON
Master Agency Id:	96391
Subject Item ID:	1
UST Tank Num:	55149
Tank Status:	Active
Install Date:	07/15/2001
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	55149-gasoline
Service change date:	Not reported
Last service date:	09/01/2001
Current status start date:	11/09/2001
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

U003987674

Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	08/15/2001
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	07/15/2001
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/2001
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	11/02/2001
Install alt certificate num:	IRC 0371
Install cert worker name:	DANNY DURBIN
Install cert worker emp name:	JONES BROTHERS
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	11/09/2001
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

U003987674

Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported
UST Tank Num:	55150
Tank Status:	Active
Install Date:	07/15/2001
Total Capacity:	15000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	55150-gasoline/diesel
Service change date:	Not reported
Last service date:	09/01/2001
Current status start date:	11/09/2001
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Not reported
Rdt invent control:	Not reported
Rdt auto gauge:	Y
Rdt grndwtr monitor:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

U003987674

Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Not reported
Rdp line tightness:	Y
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Not reported
Overfill prevent install date:	08/15/2001
Alt spill overfill equip flag:	Not reported
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	07/15/2001
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Y
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Not reported
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/2001
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	11/02/2001
Install alt certificate num:	IRC 0371
Install cert worker name:	DANNY DURBIN
Install cert worker emp name:	JONES BROTHERS
Install cert by mfr flag:	Not reported
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Not reported
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	11/09/2001
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

G21
SE
1/8-1/4
0.223 mi.
1177 ft.

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #1
2999 GRAND POINT HWY
HENDERSON, LA 70517

Site 2 of 5 in cluster G

LUST
SPILLS
NPDES
REM

S109352782
N/A

Relative:
Lower

Actual:
17 ft.

LUST:

Name: BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10
Address: 2999 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility ID: 96391
Comments: UST

SPILLS:

Name: MCDONALD'S RESTAURANT
Address: 2999 Grand Point Hwy
City,State,Zip: HENDERSON, LA 70517
Receive Date: 09/16/2019
Incident Date: 09/16/2019
Quantity: Not reported
Units: Not reported
Parameter: Not reported
Incident ID: 193295
Other Description: Not reported
AI ID: 88427
Incident Status: Closed
Media Desc: Water
Location Description: 2999 Grand Point Hwy.
Start Date: Not reported
Region: AR
Reporter Name: LDEQ
Mailing Address: PO Box 92638
Mailing City: Lafayette
Mailing State: LA
Mailing Zip: 70509
Organization Name: Not reported
Incident Desc: c19-137336 Our 2018-2019 bimonthly sampling at site 4800 shows consistently extremely high bacteria, TDS, and nutrients. LB

Incident Type Desc: Complaint, Facility Water Discharge
Comments: On 4/12/19, the Department received an incident report (T193295) from the Louisiana Department of Environmental Quality (LDEQ) Nonpoint Unit regarding several DMR excursions and constantly high sample readings near the McDonald s discharge. The location of the incident is at 2999 Grand Point Hwy, Henderson, LA. On 10/3/19, I met with Calvin Marks/Owner and he gave me a tour of the plant. The facility is a mechanical Sewage Treatment Plant (STP). The plants discharges into the roadside ditch, thence Coulee Nicole Guidry, thence the Bayou du Portage (Subsegment LA060211). During the facility tour it was noted that 1 of the 2 aerator motors were down. There was no chlorine in the Chlorine Contact Chamber (CCC) at the time of the inspection. There were solids and sludge mats observed in the aeration chamber, clarifier, and the CCC. Outfall 001 was inaccessible due to overgrown vegetation around the local drainage ditch. The monthly Discharge Monitoring Reports were reviewed for a timeframe of 12/31/14 through 6/30/18. During this timeframe, the facility had 24 permit exceedances: TSS (8), Fecal Coliform (2), Oil and Grease (2), and BOD (12). Also the facility did not submit DMRs for December 2018 and June 2019.

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

S109352782

NPDES:

Name: CJM INVESTMENTS INC - MCDONALD'S OF HENDERSON
Address: 2999 GRAND POINT HWY
City,State,Zip: BREAUx BRIDGE, LA 70517
Facility Id: 88427
Facility Phone: (337) 565-6774
Issued Date: 02/21/2018
Title Description: LAG53 Reauthorization
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20170002
Effective Date: 02/21/2018
Expiration Date: 11/30/2022
Permit Number: LAG531148
Mailing Address: PO Box 92638 Lafayette, LA 70509-2638
Effective Flag: Y

Name: BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10
Address: 2999 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility Id: 96391
Facility Phone: (337) 332-3753
Issued Date: 05/31/2019
Title Description: Automatic Reauthorization
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20190001
Effective Date: 05/31/2019
Expiration Date: 04/25/2024
Permit Number: LAG750508
Mailing Address: PO Box 61 Youngsville, LA 70592-0061
Effective Flag: N

Name: BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10
Address: 2999 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility Id: 96391
Facility Phone: (337) 332-3753
Issued Date: 04/02/2025
Title Description: Permit
Permit Type Description: Gen-LAG83-Petroleum UST Rem
Program: Water
Activity Number: GEN20240001
Effective Date: 04/02/2025
Expiration Date: 03/31/2028
Permit Number: LAG830368
Mailing Address: PO Box 61 Youngsville, LA 70592-0061
Effective Flag: Y

Name: BRENTON INVESTMENT CORPORATION - HIT-N-RUN #10
Address: 2999 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility Id: 96391
Facility Phone: (337) 332-3753
Issued Date: 05/21/2014
Title Description: Renewed Coverage
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

S109352782

Program: Water
Activity Number: GEN20140001
Effective Date: 05/21/2014
Expiration Date: 03/14/2019
Permit Number: LAG750508
Mailing Address: PO Box 61 Youngsville, LA 70592-0061
Effective Flag: N

Name: BRENTON INVESTMENT CORPORATION - HIT-N-RUN #10
Address: 2999 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility Id: 96391
Facility Phone: (337) 332-3753
Issued Date: 02/28/2005
Title Description: LAG750508 Permit
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20040001
Effective Date: 02/28/2005
Expiration Date: 03/14/2009
Permit Number: LAG750508
Mailing Address: PO Box 61 Youngsville, LA 70592-0061
Effective Flag: N

Name: BRENTON INVESTMENT CORPORATION - HIT-N-RUN #10
Address: 2999 GRAND POINT HWY
City,State,Zip: HENDERSON, LA 70517
Facility Id: 96391
Facility Phone: (337) 332-3753
Issued Date: 06/12/2009
Title Description: Automatic Reauthorization
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20090001
Effective Date: 06/18/2009
Expiration Date: 05/20/2014
Permit Number: LAG750508
Mailing Address: PO Box 61 Youngsville, LA 70592-0061
Effective Flag: N

Name: CJM INVESTMENTS INC - MCDONALD'S OF HENDERSON
Address: 2999 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 88427
Facility Phone: (337) 565-6774
Issued Date: 05/14/2001
Title Description: LAG531148 Permit
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20010001
Effective Date: 06/01/2001
Expiration Date: 11/18/2002
Permit Number: LAG531148
Mailing Address: PO Box 92638 Lafayette, LA 70509-2638
Effective Flag: N

Name: CJM INVESTMENTS INC - MCDONALD'S OF HENDERSON

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

S109352782

Address: 2999 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 88427
Facility Phone: (337) 565-6774
Issued Date: 11/20/2002
Title Description: LAG531148
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20020001
Effective Date: 12/01/2002
Expiration Date: 11/30/2007
Permit Number: LAG531148
Mailing Address: PO Box 92638 Lafayette, LA 70509-2638
Effective Flag: N

Name: CJM INVESTMENTS INC - MCDONALD'S OF HENDERSON
Address: 2999 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 88427
Facility Phone: (337) 565-6774
Issued Date: 02/01/2008
Title Description: Renewed Coverage
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20080001
Effective Date: 02/01/2008
Expiration Date: 11/30/2012
Permit Number: LAG531148
Mailing Address: PO Box 92638 Lafayette, LA 70509-2638
Effective Flag: N

Name: CJM INVESTMENTS INC - MCDONALD'S OF HENDERSON
Address: 2999 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 88427
Facility Phone: (337) 565-6774
Issued Date: 08/30/2013
Title Description: Permit
Permit Type Description: Gen-LAG53-Sanitary Class I
Program: Water
Activity Number: GEN20120001
Effective Date: 08/30/2013
Expiration Date: 11/30/2017
Permit Number: LAG531148
Mailing Address: PO Box 92638 Lafayette, LA 70509-2638
Effective Flag: N

REM:

Name: BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10
Address: 2999 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: HENDERSON, LA 70517
AI Num: 96391
Evaluated And Closed: Not reported
Program: UST
Activity Description: Not reported
Title Description: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BRENTON INVESTMENT CORP - HIT-N-RUN FOOD STORES #10 (Continued)

S109352782

EAC Type: Not reported
Comments: Not reported

22
ESE
1/8-1/4
0.249 mi.
1313 ft.

DOLLAR GENERAL #847
1053 B HENERSON HWY
BREAUX BRIDGE, LA 70517

RCRA-VSQG **1019900347**
FINDS **LAR000093435**
ECHO

Relative:
Lower

Actual:
17 ft.

RCRA Listings:
Date Form Received by Agency: 20161003
Handler Name: Dollar General #847
Handler Address: B Henerson Hwy
Handler City,State,Zip: BREAUX BRIDGE, LA 70517
EPA ID: LAR000093435
Contact Name: ERIC VOYLES
Contact Address: MISSION RIDGE
Contact City,State,Zip: GOODLETTSVILLE, TN 37072
Contact Telephone: 615-855-4024
Contact Fax: Not reported
Contact Email: ENVCOMPLIANCE@DOLLARGENERAL.COM
Contact Title: SR FACILITIES MGR
EPA Region: 06
Land Type: Private
Federal Waste Generator Description: Conditionally Exempt Small Quantity Generator
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Handler Activities
State District Owner: La
State District: AC
Mailing Address: MISSION RIDGE
Mailing City,State,Zip: GOODLETTSVILLE, TN 37072
Owner Name: Dollar General
Owner Type: Private
Operator Name: Dollar General
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No
Universal Waste Indicator: No
Universal Waste Destination Facility: No
Federal Universal Waste: No
Active Site State-Reg Handler: ---
Federal Facility Indicator: Not reported
Hazardous Secondary Material Indicator: N
Sub-Part K Indicator: Not reported
2018 GPRA Permit Baseline: Not on the Baseline
2018 GPRA Renewals Baseline: Not on the Baseline
202 GPRA Corrective Action Baseline: No
Subject to Corrective Action Universe: No

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DOLLAR GENERAL #847 (Continued)

1019900347

Non-TSDFs Where RCRA CA has Been Imposed Universe:	No
Corrective Action Priority Ranking:	No NCAPS ranking
Environmental Control Indicator:	No
Institutional Control Indicator:	No
Human Exposure Controls Indicator:	N/A
Groundwater Controls Indicator:	N/A
Significant Non-Complier Universe:	No
Unaddressed Significant Non-Complier Universe:	No
Addressed Significant Non-Complier Universe:	No
Significant Non-Complier With a Compliance Schedule Universe:	No
Financial Assurance Required:	Not reported
Handler Date of Last Change:	20161027
Recognized Trader-Importer:	No
Recognized Trader-Exporter:	No
Importer of Spent Lead Acid Batteries:	No
Exporter of Spent Lead Acid Batteries:	No
Recycler Activity Without Storage:	No
Manifest Broker:	No
Sub-Part P Indicator:	No

Hazardous Waste Summary:

Waste Code:	D001
Waste Description:	Ignitable Waste
Waste Code:	D002
Waste Description:	Corrosive Waste
Waste Code:	D005
Waste Description:	Barium
Waste Code:	D007
Waste Description:	Chromium
Waste Code:	D009
Waste Description:	Mercury
Waste Code:	D010
Waste Description:	Selenium
Waste Code:	D011
Waste Description:	Silver
Waste Code:	D016
Waste Description:	2,4-D (2,4-Dichlorophenoxyacetic Acid)
Waste Code:	D018
Waste Description:	Benzene
Waste Code:	D035
Waste Description:	Methyl Ethyl Ketone
Waste Code:	D039
Waste Description:	Tetrachloroethylene
Waste Code:	D040
Waste Description:	Trichloroethylene

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DOLLAR GENERAL #847 (Continued)

1019900347

Waste Code:	U002
Waste Description:	2-Propanone (I) (Or) Acetone (I)
Waste Code:	U154
Waste Description:	Methanol (I) (Or) Methyl Alcohol (I)
Waste Code:	U159
Waste Description:	2-Butanone (I,T) (Or) Methyl Ethyl Ketone (Mek) (I,T)
Waste Code:	U205
Waste Description:	Selenium Sulfide (Or) Selenium Sulfide Ses2 (R,T)
Waste Code:	U240
Waste Description:	2,4-D, Salts & Esters (Or) Acetic Acid, (2,4-Dichlorophenoxy)-, Salts & Esters (Or) Dichlorophenoxyacetic Acid 2,4-D
Waste Code:	U279
Waste Description:	U279

Handler - Owner Operator:

Owner/Operator Indicator:	Operator
Owner/Operator Name:	DOLLAR GENERAL
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Owner/Operator Indicator:	Owner
Owner/Operator Name:	DOLLAR GENERAL
Legal Status:	Private
Date Became Current:	Not reported
Date Ended Current:	Not reported
Owner/Operator Address:	Not reported
Owner/Operator City,State,Zip:	Not reported
Owner/Operator Telephone:	Not reported
Owner/Operator Telephone Ext:	Not reported
Owner/Operator Fax:	Not reported
Owner/Operator Email:	Not reported

Historic Generators:

Receive Date:	20161003
Handler Name:	DOLLAR GENERAL #847
Federal Waste Generator Description:	Very Small Quantity Generator (formerly Conditionally-Exempt Small Quantity Generator)
State District Owner:	La
Large Quantity Handler of Universal Waste:	No
Recognized Trader Importer:	No
Recognized Trader Exporter:	No
Spent Lead Acid Battery Importer:	No
Spent Lead Acid Battery Exporter:	No
Current Record:	Yes

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DOLLAR GENERAL #847 (Continued)

1019900347

Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:

NAICS Code: 45299
NAICS Description: All Other General Merchandise Stores

Facility Has Received Notices of Violations:

Violations: No Violations Found

Evaluation Action Summary:

Evaluations: No Evaluations Found

FINDS:

Registry ID: 110070125510

[Click Here for FRS Facility Detail Report:](#)

Environmental Interest/Information System:

The Resource Conservation and Recovery Act Information System (RCRAInfo) is EPA's comprehensive information system in support of the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. It tracks many types of information about generators, transporters, treaters, storers, and disposers of hazardous waste.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1019900347
Registry ID: 110070125510

[DFR URL:](#)

Name: DOLLAR GENERAL #847
Address: 1053 B Henerson Hwy
City,State,Zip: BREAUX BRIDGE, LA 70517

G23
SSE
1/4-1/2
0.254 mi.
1343 ft.

I-10 HENDERSON TRAVEL CENTER
3003 GRAND POINT HWY
BREAUX BRIDGE, LA 70517
Site 3 of 5 in cluster G

AUL U003922441
N/A

Relative:
Lower

Actual:
19 ft.

AUL:

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: Not reported
Type: Underground Storage Tanks
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Underground Storage Tanks
Custom Tank Desc: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003922441

Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported
Description: Not reported
PGS: Not reported
Document Link: Not reported

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: Not reported
Type: Underground Storage Tanks
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Underground Storage Tanks
Custom Tank Desc: Not reported
Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported
Description: Not reported
PGS: Not reported
Document Link: Not reported

G24
SSE
1/4-1/2
0.254 mi.
1343 ft.

I-10 HENDERSON TRAVEL CENTER
3003 GRAND POINT HWY
BREAUX BRIDGE, LA 70517
Site 4 of 5 in cluster G

LUST
UST
AUL
NPDES
REM
U003986941
N/A

Relative:
Lower

LUST:
Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 31056
Comments: UST

Actual:
19 ft.

UST:
Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
Address 2: (FKA 1018 MARTHA HEBERT RD)
City: BREAUX BRIDGE
Master Agency Id: 31056
Subject Item ID: 1

UST Tank Num: 18301
Tank Status: **Active**
Install Date: 09/01/1983
Total Capacity: 20000
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Yes
Gasohol: Not reported
Kerosene: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	18301-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	08/26/1991
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Y
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Y
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Y
Overfill prevent install date:	08/15/1994
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	08/15/1994
Cpt fibrgls plstc:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Y
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/1994
Cpp fibrgls plastic:	Y
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	02/15/1999
Install alt certificate num:	IRC-0104
Install cert worker name:	JOEY JACKSON
Install cert worker emp name:	PETRON, INC.
Install cert by mfr flag:	Y
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	Y
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/26/1991
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	18302
Tank Status:	Active
Install Date:	09/01/1983
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	18302-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	08/26/1991
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Y
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Y
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Y
Overfill prevent install date:	08/15/1994
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	08/15/1994
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Y
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/1994
Cpp fibrgls plastic:	Y
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	02/15/1999
Install alt certificate num:	IRC-0104
Install cert worker name:	JOEY JACKSON
Install cert worker emp name:	PETRON, INC.
Install cert by mfr flag:	N
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	N
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/26/1991
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	18303
Tank Status:	Active
Install Date:	10/26/1985
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	18303-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	08/26/1991
Current status end date:	Not reported
Emer gen fuel only flag:	N
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Y
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Y
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Y
Overfill prevent install date:	08/15/1994
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	08/15/1994
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Y
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/1994
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	02/15/1999
Install alt certificate num:	IRC-0104
Install cert worker name:	JOEY JACKSON
Install cert worker emp name:	PETRON, INC.
Install cert by mfr flag:	N
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chkfst comp flag:	N
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/26/1991
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	18304
Tank Status:	Active
Install Date:	09/01/1983
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Yes
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	18304-gasoline
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	08/26/1991
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Y
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Y
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Y
Overfill prevent install date:	08/15/1994
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	08/15/1994
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Y
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/1994
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	02/15/1999
Install alt certificate num:	IRC-0104

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Install cert worker name:	JOEY JACKSON
Install cert worker emp name:	PETRON, INC.
Install cert by mfr flag:	N
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	N
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/26/1991
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	18305
Tank Status:	Active
Install Date:	09/01/1983
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	18305-diesel
Service change date:	Not reported
Last service date:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Current status start date:	08/26/1991
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported
Mcp galvanized steel:	Not reported
Mcp part stl fibrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Y
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Y
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Y
Overfill prevent install date:	08/15/1994
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	08/15/1994
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Y
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/1994
Cpp fibrgls plastic:	Y
Cpp part stl fibrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	02/15/1999
Install alt certificate num:	IRC-0104
Install cert worker name:	JOEY JACKSON
Install cert worker emp name:	PETRON, INC.
Install cert by mfr flag:	N
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklist comp flag:	N

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported
Active:	08/26/1991
Bankrupt:	Not reported
Closed:	Not reported
Deferred:	Not reported
Filled:	Not reported
Hold:	Not reported
Inactive:	Not reported
Removed:	Not reported
Sold:	Not reported
Temp out of service:	Not reported

UST Tank Num:	18306
Tank Status:	Active
Install Date:	09/01/1983
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
Subject item desc:	18306-diesel
Service change date:	Not reported
Last service date:	Not reported
Current status start date:	08/26/1991
Current status end date:	Not reported
Emer gen fuel only flag:	Not reported
Tank inert material desc:	Not reported
Mct fibrgls plastic:	Not reported
Mcp bare steel:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Mcp galvanized steel:	Not reported
Mcp part stl fbrgls lines:	Not reported
Mcp copper:	Not reported
Mcp double walled:	Y
Mcp secondary contain:	Not reported
Mcp unknown:	Not reported
Mcp other:	Not reported
Rdt manual gauging:	Not reported
Rdt tank tightness:	Y
Rdt invent control:	Not reported
Rdt auto guage:	Y
Rdt grndwtr monitor:	Not reported
Rdt intr mon dwall:	Not reported
Rdt intr mon secd:	Not reported
Rdt vapor monitor:	Not reported
Rdt other:	Y
Rdp line tightness:	Not reported
Rdp grndwtr monitor:	Not reported
Rdp intr mon dwall:	Not reported
Rdp intr mon secd:	Not reported
Rdp vapor monitor:	Not reported
Rdp other:	Y
Overfill prevent install date:	08/15/1994
Alt spill overfill equip flag:	N
Alt spill overfill equip desc:	Not reported
Tank ext corr protect date:	08/15/1994
Cpt fibrgls plstc:	Not reported
Cpt stl fbr plastic:	Not reported
Cpt expert no leak:	Not reported
Cpt dielectric coat:	Y
Cpt impressed curr:	Not reported
Cpt cathodic protect:	Not reported
Cpt interior lining:	Not reported
Cpt lined cathod prot:	Not reported
Cpt other:	Not reported
Pipe ext corr protect date:	08/15/1994
Cpp fibrgls plastic:	Y
Cpp part stl fbrgls:	Not reported
Cpp expert no leak:	Not reported
Cpp dielectric coat:	Not reported
Cpp impressed curr:	Not reported
Cpp cathodic protect:	Not reported
Cpp other:	Not reported
Install certification date:	02/15/1999
Install alt certificate num:	IRC-0104
Install cert worker name:	JOEY JACKSON
Install cert worker emp name:	PETRON, INC.
Install cert by mfr flag:	N
Install insp by reg eng flag:	Not reported
Install insp by dept flag:	Not reported
Install mfr chklst comp flag:	N
Install cert alt method flag:	Not reported
Install cert alt method desc:	Not reported
Closure certification date:	Not reported
Closure alt cert num:	Not reported
Closure cert worker name:	Not reported
Closure cert worker emp name:	Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Active: 08/26/1991
Bankrupt: Not reported
Closed: Not reported
Deferred: Not reported
Filled: Not reported
Hold: Not reported
Inactive: Not reported
Removed: Not reported
Sold: Not reported
Temp out of service: Not reported

AUL:

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility ID: 31056
Type: Remediation
Incident Number: Not reported
Agency Interest Id: Not reported
PPM Project Number: Not reported
Parish: St. Martin
Comments: Remediation Oversight
Custom Tank Desc: Not reported
Document ID: Not reported
Document Type: Not reported
Document Sub Type: Not reported
Date: Not reported
Description: INS-Conveyance Notice
PGS: Not reported
Document Link: Not reported

NPDES:

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY (FKA 1018 MARTHA HEBERT RD)
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: (337) 332-6608
Issued Date: 03/28/2016
Title Description: LAG48 renewal
Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN20150001
Effective Date: 03/28/2016
Expiration Date: 11/30/2020
Permit Number: LAG480657
Mailing Address: PO Box 539 Cottonport, LA 71327-0539
Effective Flag: N

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: 3373326608
Issued Date: 11/01/1998
Title Description: Fiscal Migration: LA0092312
Permit Type Description: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Program: Water
Activity Number: PER19970001
Effective Date: Not reported
Expiration Date: Not reported
Permit Number: Not reported
Mailing Address: Not reported
Effective Flag: Not reported

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY, (FKA 1018 MARTHA HEBERT RD)
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: (337) 332-6608
Issued Date: 03/08/2021
Title Description: LAG48 Reauthorization
Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN20210001
Effective Date: 03/08/2021
Expiration Date: 12/15/2025
Permit Number: LAG480657
Mailing Address: PO Box 539 Cottonport, LA 71327-0539
Effective Flag: Y

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: (337) 332-6608
Issued Date: 10/15/2003
Title Description: LAG480301 Permit
Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN20030001
Effective Date: 10/15/2003
Expiration Date: 03/29/2005
Permit Number: LAG480301
Mailing Address: PO Box 539 Cottonport, LA 71327-0539
Effective Flag: N

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: (337) 332-6608
Issued Date: 03/29/2005
Title Description: LAG480301 Transfer
Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN20050001
Effective Date: 03/30/2005
Expiration Date: 06/01/2011
Permit Number: LAG480301
Mailing Address: PO Box 539 Cottonport, LA 71327-0539
Effective Flag: N

Name: I-10 HENDERSON TRAVEL CENTER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

I-10 HENDERSON TRAVEL CENTER (Continued)

U003986941

Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: (337) 332-6608
Issued Date: 02/21/2006
Title Description: LAG541379 Permit
Permit Type Description: Gen-LAG54-Sanitary Class II
Program: Water
Activity Number: GEN20050002
Effective Date: 02/21/2006
Expiration Date: 09/17/2008
Permit Number: LAG541379
Mailing Address: PO Box 539 Cottonport, LA 71327-0539
Effective Flag: N

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
City,State,Zip: BREAUX BRIDGE, LA 70517
Facility Id: 31056
Facility Phone: (337) 332-6608
Issued Date: 10/19/2011
Title Description: Permit
Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN20110001
Effective Date: 10/19/2011
Expiration Date: 03/27/2016
Permit Number: LAG480657
Mailing Address: PO Box 539 Cottonport, LA 71327-0539
Effective Flag: N

REM:

Name: I-10 HENDERSON TRAVEL CENTER
Address: 3003 GRAND POINT HWY
Address 2: Not reported
City,State,Zip: BREAUX BRIDGE, LA 70517
AI Num: 31056
Evaluated And Closed: 01/23/2012
Program: UST
Activity Description: Not reported
Title Description: Remediation Oversight
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 8325117

G25
SE
1/4-1/2
0.273 mi.
1440 ft.

WILLIAMS TRAVEL CENTERS #3170
1018 MARTHA HEBERT RD
BREAUX BRIDGE, LA 70517
Site 5 of 5 in cluster G

HIST LUST **S106034374**
SPILLS **N/A**

Relative:
Lower

HIST LUST:

Actual:
19 ft.

Facility ID: 50-006699
Facility Parish: ST. MARTIN
Substance Name: DIESEL
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WILLIAMS TRAVEL CENTERS #3170 (Continued)

S106034374

Date Confirmed: 02/18/1991
Date Confirmed 2: Not reported
Incident Number: 91-4-0084
Incident Date: 03/16/1991
Type of Incident: DISPENSER LEAK
Type of Incident No2: Not reported
Reported By: NEAL HEBERT/DEQ WATER DIVISION
Reported By 2: Not reported
Owner ID: 00184600
Owner Name: MAPCO PETROLEUM
Owner Address: 1101 KERMIT DR, SUITE 800
Owner City,St,Zip: NASHVILLE, TN 37217
Assessment Pending Info: No
Assessment Request Date: 04/01/1991
Assessment Plan Due Date: 06/20/1991
Assessment Plan Received Date: 07/24/1991
Assessment Approved Date: 07/24/1991
Assessment Contractor: CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: 03/03/1994
Corrective Plan Approved Date: 04/21/1994
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: SEE INCIDENT # 91-4-0335

LA HIST LUST ASSESMENT:

Comments: RESPONSE TO DIESEL DISCHARGE INTO DITCH. #13 DISPENSER SHUTDOWN FOR 2 WEEKS BEFORE THIS INCIDENT. LINE TO SATELLITEDISPENSER PROBABLE LEAK. EVERYTHING SHUT DOWN ON 3/17/91. TANK ANDLINE TIGHTNESS TEST TO BE PERFORMED. SEE INCIDENT NO. 91-4-0335AND 92-4-0070.

LA HIST LUST CORRECTIVE ACTION:

Comments: RECEIVED CORRECTIVE ACTION IMPLEMENTATION STATUS REPORT ON9-8-94. REC'D SUMMARY OF SITE ACTIVITIES 1-4-95.

Facility ID: 50-006699
Facility Parish: ST. MARTIN
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-4-0084
Incident Date: 03/16/1991
Type of Incident: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WILLIAMS TRAVEL CENTERS #3170 (Continued)

S106034374

Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00184600
Owner Name: MAPCO PETROLEUM
Owner Address: 1101 KERMIT DR, SUITE 800
Owner City,St,Zip: NASHVILLE, TN 37217
Assessment Pending Info: No
Assessment Request Date: 04/01/1991
Assessment Plan Due Date: 06/20/1991
Assessment Plan Received Date: 07/24/1991
Assessment Approved Date: 07/24/1991
Assessment Contractor: CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: 03/03/1994
Corrective Plan Approved Date: 04/21/1994
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: SEE INCIDENT # 91-4-0335

LA HIST LUST ASSESMENT:

Comments: RESPONSE TO DIESEL DISCHARGE INTO DITCH. #13 DISPENSER SHUTDOWN FOR 2 WEEKS BEFORE THIS INCIDENT. LINE TO SATELLITEDISPENSER PROBABLE LEAK. EVERYTHING SHUT DOWN ON 3/17/91. TANK ANDLINE TIGHTNESS TEST TO BE PERFORMED. SEE INCIDENT NO. 91-4-0335AND 92-4-0070.

LA HIST LUST CORRECTIVE ACTION:

Comments: RECEIVED CORRECTIVE ACTION IMPLEMENTATION STATUS REPORT ON9-8-94. REC'D SUMMARY OF SITE ACTIVITIES 1-4-95.

Facility ID: 50-006699
Facility Parish: ST. MARTIN
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: 100 GAL
Quantity 2: Not reported
Date Confirmed: 09/24/1991
Date Confirmed 2: Not reported
Incident Number: 91-4-0335
Incident Date: 09/24/1991
Type of Incident: PIPING LEAK
Type of Incident No2: Not reported
Reported By: MARK SCHUTT/ MAPCO PETROLEUM
Reported By 2: Not reported
Owner ID: 00184600
Owner Name: MAPCO PETROLEUM

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WILLIAMS TRAVEL CENTERS #3170 (Continued)

S106034374

Owner Address: 1101 KERMIT DR, SUITE 800
Owner City,St,Zip: NASHVILLE, TN 37217
Assessment Pending Info: Yes
Assessment Request Date: 10/04/1991
Assessment Plan Due Date: 12/24/1991
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: 08/23/1993
Corrective Plan Received Date: 03/07/1994
Corrective Plan Approved Date: 04/06/1995
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: SITE AKA DELTA EXPRESS. BACKHOE BREAKING UP CONCRETE BROKE PRODUCTLINE. SITE JUST COMPLETED A SITE ASSESSMENT. DEQ INSPECT. SEPT. 20, 24AND OCT. 3, 1991 OBSERVED EXCAVATION AND LINE REPAIR.SEE INCIDENT NO. 92-4-0070.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: REC'D HYDROCARBON ASSESS. & CORRECTIVE ACTION ALTERNATIVES REPORTDATED 8/30/93: VACUUM ENHANCED PUMPING. QTLY REPORTS SUBMITTED.

Facility ID: 50-006699
Facility Parish: ST. MARTIN
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-4-0335
Incident Date: 09/24/1991
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00184600
Owner Name: MAPCO PETROLEUM
Owner Address: 1101 KERMIT DR, SUITE 800
Owner City,St,Zip: NASHVILLE, TN 37217
Assessment Pending Info: Yes
Assessment Request Date: 10/04/1991
Assessment Plan Due Date: 12/24/1991
Assessment Plan Received Date: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WILLIAMS TRAVEL CENTERS #3170 (Continued)

S106034374

Assessment Approved Date: Not reported
Assessment Contractor: CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: 08/23/1993
Corrective Plan Received Date: 03/07/1994
Corrective Plan Approved Date: 04/06/1995
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: SITE AKA DELTA EXPRESS. BACKHOE BREAKING UP CONCRETE BROKE PRODUCTLINE. SITE JUST COMPLETED A SITE ASSESSMENT. DEQ INSPECT. SEPT. 20, 24AND OCT. 3, 1991 OBSERVED EXCAVATION AND LINE REPAIR.SEE INCIDENT NO. 92-4-0070.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: REC'D HYDROCARBON ASSESS. & CORRECTIVE ACTION ALTERNATIVES REPORTDATED 8/30/93: VACUUM ENHANCED PUMPING. QTLY REPORTS SUBMITTED.

Facility ID: 50-006699
Facility Parish: ST. MARTIN
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 03/18/1992
Date Confirmed 2: Not reported
Incident Number: 92-4-0070
Incident Date: 03/16/1992
Type of Incident: UNKNOWN
Type of Incident No2: Not reported
Reported By: MARK SCHUTT/MAPCO
Reported By 2: Not reported
Owner ID: 00184600
Owner Name: MAPCO PETROLEUM
Owner Address: 1101 KERMIT DR, SUITE 800
Owner City,St,Zip: NASHVILLE, TN 37217
Assessment Pending Info: No
Assessment Request Date: 03/25/1992
Assessment Plan Due Date: 06/14/1992
Assessment Plan Received Date: 09/11/1992
Assessment Approved Date: 06/05/1992
Assessment Contractor: CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: 11/03/1992
Assess Date Add Info Recd: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WILLIAMS TRAVEL CENTERS #3170 (Continued)

S106034374

Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: 08/23/1993
Corrective Plan Received Date: 01/27/1994
Corrective Plan Approved Date: 04/21/1994
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: SEE INCIDENT # 91-4-0335 AND 91-4-0084. AKA DELTA EXPRESS. REC'D QTLYREPORT ON 2/23/95: CONSULTANT REQUEST TERMINATION OF REMEDIATION.

LA HIST LUST ASSESMENT:

Comments: GAS FOUND ABOVE 3 GASOLINE TANK IN MAN WAYS. IN PROCESS OFHAVING TANKS AND LINES TESTED. ACCORDING TO SITE ASSESSMENT PSHWAS NOTED DURING THE INSTALLATION, DEVELOPMENT AND SAMPLING OF MW-6.TPH-G WAS DETECTED IN SOIL SAMPLES FROM 2 OF THE 4 BORINGS (MW-6&MW-9)PSH RECOVERED FROM BAILING AND VACUUMING MW-6.

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 7/23/96 TO ADJACENT PROPERTY OWNER (DAVID CORMIER) THATMAPCO'S CONSULTANT SHOULD PERFORM AN CONTAMINATION ASSESS. ON HISPROPERTY. REC'D HYDROCARBON ASSESS. AND CORRECTIVE ACTION REPORT ON8/30/93.

Facility ID: 50-006699
Facility Parish: ST. MARTIN
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 92-4-0070
Incident Date: 03/16/1992
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00184600
Owner Name: MAPCO PETROLEUM
Owner Address: 1101 KERMIT DR, SUITE 800
Owner City,St,Zip: NASHVILLE, TN 37217
Assessment Pending Info: No
Assessment Request Date: 03/25/1992
Assessment Plan Due Date: 06/14/1992
Assessment Plan Received Date: 09/11/1992
Assessment Approved Date: 06/05/1992
Assessment Contractor: CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: 08/23/1993

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

WILLIAMS TRAVEL CENTERS #3170 (Continued)

S106034374

Corrective Plan Received Date: 01/27/1994
Corrective Plan Approved Date: 04/21/1994
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: PUMP AND TREATMENT, VACUUM ENHANCED PUMP
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

Comments: SEE INCIDENT # 91-4-0335 AND 91-4-0084. AKA DELTA EXPRESS. REC'D QTLYREPORT ON 2/23/95: CONSULTANT REQUEST TERMINATION OF REMEDIATION.

LA HIST LUST ASSESMENT:

Comments: GAS FOUND ABOVE 3 GASOLINE TANK IN MAN WAYS. IN PROCESS OFHAVING TANKS AND LINES TESTED. ACCORDING TO SITE ASSESSMENT PSHWAS NOTED DURING THE INSTALLATION, DEVELOPMENT AND SAMPLING OF MW-6.TPH-G WAS DETECTED IN SOIL SAMPLES FROM 2 OF THE 4 BORINGS (MW-6&MW-9)PSH RECOVERED FROM BAILING AND VACUUMING MW-6.

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 7/23/96 TO ADJACENT PROPERTY OWNER (DAVID CORMIER) THATMAPCO'S CONSULTANT SHOULD PERFORM AN CONTAMINATION ASSESS. ON HISPROPERTY. REC'D HYDROCARBON ASSESS. AND CORRECTIVE ACTION REPORT ON8/30/93.

SPILLS:

Name: Not reported
Address: 1018 Martha Hebert Rd
City,State,Zip: BREAUUX BRIDGE, LA
Receive Date: 06/17/2005
Incident Date: 08/05/2004
Quantity: Not reported
Units: Not reported
Parameter: Not reported
Incident ID: 79921
Other Description: Not reported
AI ID: 31056
Incident Status: Referred to Remediation
Media Desc: Soil
Location Description: 1018 Martha Hebert Rd Breauux Bridge
Start Date: Not reported
Region: Not reported
Reporter Name: Not reported
Mailing Address: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Organization Name: I-10 Henderson Travel Center
Incident Desc: s05-2051 Diesel concentrations in soil were above RECAP. CMD
Incident Type Desc: Not reported
Comments: Not reported

Count: 0 records.

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
NO SITES FOUND					

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Lists of Federal NPL (Superfund) sites

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 09/29/2025	Source: EPA
Date Data Arrived at EDR: 10/01/2025	Telephone: N/A
Date Made Active in Reports: 10/28/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 27	Next Scheduled EDR Contact: 01/05/2026
	Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 09/29/2025	Source: EPA
Date Data Arrived at EDR: 10/01/2025	Telephone: N/A
Date Made Active in Reports: 10/28/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 27	Next Scheduled EDR Contact: 01/05/2026
	Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

Lists of Federal Delisted NPL sites

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 09/29/2025
Date Data Arrived at EDR: 10/01/2025
Date Made Active in Reports: 10/28/2025
Number of Days to Update: 27

Source: EPA
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

Lists of Federal sites subject to CERCLA removals and CERCLA orders

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 06/20/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 68

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Varies

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly known as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 09/29/2025
Date Data Arrived at EDR: 10/01/2025
Date Made Active in Reports: 10/28/2025
Number of Days to Update: 27

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Quarterly

Lists of Federal CERCLA sites with NFRAP

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 09/29/2025	Source: EPA
Date Data Arrived at EDR: 10/01/2025	Telephone: 800-424-9346
Date Made Active in Reports: 10/28/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 27	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Quarterly

Lists of Federal RCRA facilities undergoing Corrective Action

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/02/2025	Source: EPA
Date Data Arrived at EDR: 06/03/2025	Telephone: 800-424-9346
Date Made Active in Reports: 06/16/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 13	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Quarterly

Lists of Federal RCRA TSD facilities

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/02/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 06/04/2025	Telephone: 214-665-6444
Date Made Active in Reports: 06/16/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 12	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Quarterly

Lists of Federal RCRA generators

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 06/04/2025	Telephone: 214-665-6444
Date Made Active in Reports: 06/16/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 12	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/02/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 06/04/2025	Telephone: 214-665-6444
Date Made Active in Reports: 06/16/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 12	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Quarterly

RCRA-VSQG: RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators)

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Very small quantity generators (VSQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/02/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 06/04/2025	Telephone: 214-665-6444
Date Made Active in Reports: 06/16/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 12	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Quarterly

Federal institutional controls / engineering controls registries

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 03/11/2025	Source: Department of the Navy
Date Data Arrived at EDR: 04/02/2025	Telephone: 843-820-7326
Date Made Active in Reports: 06/24/2025	Last EDR Contact: 10/28/2025
Number of Days to Update: 83	Next Scheduled EDR Contact: 02/16/2026
	Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 05/19/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 05/20/2025	Telephone: 703-603-0695
Date Made Active in Reports: 07/29/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 70	Next Scheduled EDR Contact: 12/02/2024
	Data Release Frequency: Varies

US INST CONTROLS: Institutional Controls Sites List

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 05/19/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 05/20/2025	Telephone: 703-603-0695
Date Made Active in Reports: 07/29/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 70	Next Scheduled EDR Contact: 12/01/2025
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 06/10/2025

Date Data Arrived at EDR: 06/12/2025

Date Made Active in Reports: 06/16/2025

Number of Days to Update: 4

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180

Last EDR Contact: 10/01/2025

Next Scheduled EDR Contact: 12/29/2025

Data Release Frequency: Quarterly

Lists of state- and tribal hazardous waste facilities

SHWS: Potential and Confirmed Sites List

Confirmed status denotes that assessments have been performed and a determination made that (1) hazardous waste(s) or substance(s) are present at the site and (2) these sites are under the jurisdiction of the LDEQ/RSD. Potential status is an indicator that sites are either waiting to be assessed or the assessment is in progress.

Date of Government Version: 07/09/2025

Date Data Arrived at EDR: 07/09/2025

Date Made Active in Reports: 09/10/2025

Number of Days to Update: 63

Source: Department of Environmental Quality

Telephone: 225-219-3181

Last EDR Contact: 10/01/2025

Next Scheduled EDR Contact: 01/19/2026

Data Release Frequency: Quarterly

Lists of state and tribal landfills and solid waste disposal facilities

SWF/LF: Landfill List

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/16/2025

Date Data Arrived at EDR: 06/16/2025

Date Made Active in Reports: 09/11/2025

Number of Days to Update: 87

Source: Department of Environmental Quality

Telephone: 225-219-3181

Last EDR Contact: 08/26/2025

Next Scheduled EDR Contact: 12/15/2025

Data Release Frequency: Annually

DEBRIS: LDEQ Approved Debris Sites

A listing of LDEQ Approved Debris Sites where hurricane debris is dumped.

Date of Government Version: 05/29/2025

Date Data Arrived at EDR: 05/29/2025

Date Made Active in Reports: 08/25/2025

Number of Days to Update: 88

Source: Department of Environmental Quality

Telephone: 225-219-3953

Last EDR Contact: 09/03/2025

Next Scheduled EDR Contact: 12/15/2025

Data Release Frequency: Varies

HIST DEBRIS: LDEQ Approved Debris Sites

A listing of LDEQ Approved Debris Sites where hurricane debris is dumped.

Date of Government Version: 02/07/2007

Date Data Arrived at EDR: 11/14/2008

Date Made Active in Reports: 11/21/2008

Number of Days to Update: 7

Source: Department of Environmental Quality

Telephone: 225-219-3070

Last EDR Contact: 03/23/2009

Next Scheduled EDR Contact: 06/22/2009

Data Release Frequency: No Update Planned

Lists of state and tribal leaking storage tanks

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

LUST: Leaking Underground Storage Tanks

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 07/09/2025	Source: Department of Environmental Quality
Date Data Arrived at EDR: 07/09/2025	Telephone: 225-219-3181
Date Made Active in Reports: 09/10/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 63	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Quarterly

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land

Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 04/21/2025	Source: EPA, Region 5
Date Data Arrived at EDR: 07/10/2025	Telephone: 312-886-7439
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 04/21/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 07/10/2025	Telephone: 415-972-3372
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 05/22/2025	Source: EPA Region 7
Date Data Arrived at EDR: 07/10/2025	Telephone: 913-551-7003
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/22/2025	Source: EPA Region 8
Date Data Arrived at EDR: 07/10/2025	Telephone: 303-312-6271
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 04/21/2025	Source: EPA Region 6
Date Data Arrived at EDR: 07/10/2025	Telephone: 214-665-6597
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/27/2025	Source: EPA Region 10
Date Data Arrived at EDR: 07/10/2025	Telephone: 206-553-2857
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 04/21/2025	Source: EPA Region 1
Date Data Arrived at EDR: 07/10/2025	Telephone: 617-918-1313
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 04/21/2025	Source: EPA Region 4
Date Data Arrived at EDR: 07/10/2025	Telephone: 404-562-8677
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

HIST LUST: Underground Storage Tank Case History Incidents

This listing includes detailed information for Leaking Underground Storage Tanks reported through November 1999. It is no longer updated. Current LUST incidents, without detail, can be found in the Leaking Underground Storage Tank Database

Date of Government Version: 11/01/1999	Source: Department of Environmental Quality
Date Data Arrived at EDR: 02/16/2000	Telephone: N/A
Date Made Active in Reports: 05/01/2000	Last EDR Contact: 12/04/2001
Number of Days to Update: 75	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

Lists of state and tribal registered storage tanks

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 04/08/2025	Source: FEMA
Date Data Arrived at EDR: 04/23/2025	Telephone: 202-646-5797
Date Made Active in Reports: 04/24/2025	Last EDR Contact: 10/16/2025
Number of Days to Update: 1	Next Scheduled EDR Contact: 01/12/2026
	Data Release Frequency: Varies

UST: Louisiana Underground Storage Tank Database

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 07/08/2025	Source: Department of Environmental Quality
Date Data Arrived at EDR: 07/09/2025	Telephone: 225-219-3181
Date Made Active in Reports: 10/03/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 86	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 04/21/2025	Source: EPA, Region 1
Date Data Arrived at EDR: 07/10/2025	Telephone: 617-918-1313
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 04/21/2025	Source: EPA Region 6
Date Data Arrived at EDR: 07/10/2025	Telephone: 214-665-7591
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 05/27/2025	Source: EPA Region 10
Date Data Arrived at EDR: 07/10/2025	Telephone: 206-553-2857
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 04/21/2025	Source: EPA Region 4
Date Data Arrived at EDR: 07/10/2025	Telephone: 404-562-9424
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 04/21/2025	Source: EPA Region 9
Date Data Arrived at EDR: 07/10/2025	Telephone: 415-972-3368
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 05/22/2025	Source: EPA Region 8
Date Data Arrived at EDR: 07/10/2025	Telephone: 303-312-6137
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 05/22/2025	Source: EPA Region 7
Date Data Arrived at EDR: 07/10/2025	Telephone: 913-551-7003
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 04/21/2025	Source: EPA Region 5
Date Data Arrived at EDR: 07/10/2025	Telephone: 312-886-6136
Date Made Active in Reports: 10/02/2025	Last EDR Contact: 10/15/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

AUL: Listing of Institutional and/or Engineering Controls

A notice of contamination (nature and levels of contaminants) and restriction of property to non-residential use are placed in the conveyance records for the property.

Date of Government Version: 03/27/2025	Source: Department of Environmental Quality
Date Data Arrived at EDR: 03/27/2025	Telephone: 225-219-3168
Date Made Active in Reports: 06/17/2025	Last EDR Contact: 09/23/2025
Number of Days to Update: 82	Next Scheduled EDR Contact: 01/12/2026
	Data Release Frequency: Varies

Lists of state and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015	Source: EPA, Region 1
Date Data Arrived at EDR: 09/29/2015	Telephone: 617-918-1102
Date Made Active in Reports: 02/18/2016	Last EDR Contact: 09/09/2025
Number of Days to Update: 142	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Varies

VCP: Voluntary Remediation Program Sites

Sites that have entered the Department of Environmental Quality's Voluntary Remediation Program

Date of Government Version: 07/03/2025	Source: Department of Environmental Quality
Date Data Arrived at EDR: 07/03/2025	Telephone: 225-219-3181
Date Made Active in Reports: 09/22/2025	Last EDR Contact: 10/07/2025
Number of Days to Update: 81	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Quarterly

INDIAN VCP R7: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008	Source: EPA, Region 7
Date Data Arrived at EDR: 04/22/2008	Telephone: 913-551-7365
Date Made Active in Reports: 05/19/2008	Last EDR Contact: 07/08/2021
Number of Days to Update: 27	Next Scheduled EDR Contact: 07/20/2009
	Data Release Frequency: Varies

Lists of state and tribal brownfield sites

BROWNFIELDS: Brownfields Inventory

Brownfields are abandoned, idled, or underused industrial or commercial real property, the expansion, redevelopment or reuse of which may be complicated by the presence of or potential presence of a hazardous substance, pollutant, or contaminant.

Date of Government Version: 07/09/2025	Source: Department of Environmental Quality
Date Data Arrived at EDR: 07/09/2025	Telephone: 225-219-3167
Date Made Active in Reports: 09/09/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 62	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 09/09/2024	Source: Environmental Protection Agency
Date Data Arrived at EDR: 09/11/2024	Telephone: 202-566-2777
Date Made Active in Reports: 12/06/2024	Last EDR Contact: 10/01/2025
Number of Days to Update: 86	Next Scheduled EDR Contact: 12/22/2025
	Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

SWRCY: Recycling Directory

A listing of recycling facilities.

Date of Government Version: 06/12/2025	Source: Department of Environmental Quality
Date Data Arrived at EDR: 06/13/2025	Telephone: 225-219-3181
Date Made Active in Reports: 09/09/2025	Last EDR Contact: 09/10/2025
Number of Days to Update: 88	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Varies

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998	Source: Environmental Protection Agency
Date Data Arrived at EDR: 12/03/2007	Telephone: 703-308-8245
Date Made Active in Reports: 01/24/2008	Last EDR Contact: 10/15/2025
Number of Days to Update: 52	Next Scheduled EDR Contact: 02/02/2026
	Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985	Source: Environmental Protection Agency
Date Data Arrived at EDR: 08/09/2004	Telephone: 800-424-9346
Date Made Active in Reports: 09/17/2004	Last EDR Contact: 06/09/2004
Number of Days to Update: 39	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009	Source: EPA, Region 9
Date Data Arrived at EDR: 05/07/2009	Telephone: 415-947-4219
Date Made Active in Reports: 09/21/2009	Last EDR Contact: 10/07/2025
Number of Days to Update: 137	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

IHS OPEN DUMPS: Open Dumps on Indian Land

A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 02/07/2024

Date Data Arrived at EDR: 11/13/2024

Date Made Active in Reports: 11/19/2024

Number of Days to Update: 6

Source: Department of Health & Human Services, Indian Health Service

Telephone: 301-443-1452

Last EDR Contact: 10/23/2025

Next Scheduled EDR Contact: 02/02/2026

Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 04/04/2025

Date Data Arrived at EDR: 06/02/2025

Date Made Active in Reports: 08/12/2025

Number of Days to Update: 71

Source: Drug Enforcement Administration

Telephone: 202-307-1000

Last EDR Contact: 08/21/2025

Next Scheduled EDR Contact: 12/01/2025

Data Release Frequency: No Update Planned

CDL: Clandestine Drug Lab

A list of residential real properties that have been reported as potentially contaminated.

Date of Government Version: 05/19/2025

Date Data Arrived at EDR: 05/20/2025

Date Made Active in Reports: 08/07/2025

Number of Days to Update: 79

Source: Department of Environmental Quality

Telephone: 225-219-5337

Last EDR Contact: 08/21/2025

Next Scheduled EDR Contact: 12/01/2025

Data Release Frequency: Semi-Annually

DEL SHWS: Deleted Potential & Confirmed Sites

A listing of sites removed from the Potential and Confirmed Listing.

Date of Government Version: 07/09/2025

Date Data Arrived at EDR: 07/09/2025

Date Made Active in Reports: 09/10/2025

Number of Days to Update: 63

Source: Department of Environmental Quality

Telephone: 225-219-3168

Last EDR Contact: 10/01/2025

Next Scheduled EDR Contact: 01/19/2026

Data Release Frequency: Quarterly

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 04/04/2025

Date Data Arrived at EDR: 06/02/2025

Date Made Active in Reports: 08/12/2025

Number of Days to Update: 71

Source: Drug Enforcement Administration

Telephone: 202-307-1000

Last EDR Contact: 08/21/2025

Next Scheduled EDR Contact: 12/01/2025

Data Release Frequency: Quarterly

Local Land Records

LIENS: Environmental Liens

An Environmental Lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property, including (but not limited to) liens imposed pursuant to CERCLA 42 USC 9607(1) and similar state or local laws. In other words: a lien placed upon a property's title due to an environmental condition.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 02/25/2025
Date Data Arrived at EDR: 04/08/2025
Date Made Active in Reports: 06/30/2025
Number of Days to Update: 83

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Varies

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 09/29/2025
Date Data Arrived at EDR: 10/01/2025
Date Made Active in Reports: 10/28/2025
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Semi-Annually

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 06/11/2025
Date Data Arrived at EDR: 06/12/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 4

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

SPILLS: Emergency Response Section Incidents

Spills and/or releases, to land, reported to the Emergency Response Section.

Date of Government Version: 05/05/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 07/30/2025
Number of Days to Update: 84

Source: Department of Environmental Quality
Telephone: 225-219-3620
Last EDR Contact: 10/28/2025
Next Scheduled EDR Contact: 02/16/2026
Data Release Frequency: Varies

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 10/30/2012
Date Data Arrived at EDR: 01/03/2013
Date Made Active in Reports: 03/07/2013
Number of Days to Update: 63

Source: FirstSearch
Telephone: N/A
Last EDR Contact: 01/03/2013
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 06/16/2025
Number of Days to Update: 12

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 07/23/2025	Source: U.S. Army Corps of Engineers
Date Data Arrived at EDR: 07/23/2025	Telephone: 202-528-4285
Date Made Active in Reports: 07/29/2025	Last EDR Contact: 07/23/2025
Number of Days to Update: 6	Next Scheduled EDR Contact: 11/24/2025
	Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 06/07/2021	Source: USGS
Date Data Arrived at EDR: 07/13/2021	Telephone: 888-275-8747
Date Made Active in Reports: 03/09/2022	Last EDR Contact: 10/07/2025
Number of Days to Update: 239	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 04/02/2018	Source: U.S. Geological Survey
Date Data Arrived at EDR: 04/11/2018	Telephone: 888-275-8747
Date Made Active in Reports: 11/06/2019	Last EDR Contact: 10/02/2025
Number of Days to Update: 574	Next Scheduled EDR Contact: 01/12/2026
	Data Release Frequency: N/A

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 07/30/2021	Source: Environmental Protection Agency
Date Data Arrived at EDR: 02/03/2023	Telephone: 615-532-8599
Date Made Active in Reports: 02/10/2023	Last EDR Contact: 08/07/2025
Number of Days to Update: 7	Next Scheduled EDR Contact: 11/17/2025
	Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 06/02/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 06/03/2025	Telephone: 202-566-1917
Date Made Active in Reports: 06/16/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 13	Next Scheduled EDR Contact: 12/29/2025
	Data Release Frequency: Quarterly

EPA WATCH LIST: EPA Watch List

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 10/22/2025
Next Scheduled EDR Contact: 02/09/2026
Data Release Frequency: No Update Planned

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 09/30/2017
Date Data Arrived at EDR: 05/08/2018
Date Made Active in Reports: 07/20/2018
Number of Days to Update: 73

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2020
Date Data Arrived at EDR: 06/14/2022
Date Made Active in Reports: 03/24/2023
Number of Days to Update: 283

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 09/11/2025
Next Scheduled EDR Contact: 12/22/2025
Data Release Frequency: Every 4 Years

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/11/2025
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 7

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Annually

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 07/14/2025
Date Data Arrived at EDR: 07/14/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 91

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 10/14/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Annually

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 07/29/2025
Date Data Arrived at EDR: 08/04/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 8

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 07/01/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 07/29/2025	Telephone: 202-564-8600
Date Made Active in Reports: 10/28/2025	Last EDR Contact: 10/08/2025
Number of Days to Update: 91	Next Scheduled EDR Contact: 01/26/2026
	Data Release Frequency: Varies

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995	Source: EPA
Date Data Arrived at EDR: 07/03/1995	Telephone: 202-564-4104
Date Made Active in Reports: 08/07/1995	Last EDR Contact: 06/02/2008
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/01/2008
	Data Release Frequency: No Update Planned

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 06/26/2025	Source: EPA
Date Data Arrived at EDR: 07/01/2025	Telephone: 202-564-6023
Date Made Active in Reports: 07/29/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 28	Next Scheduled EDR Contact: 11/10/2025
	Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 07/01/2024	Source: EPA
Date Data Arrived at EDR: 10/02/2024	Telephone: 202-566-0500
Date Made Active in Reports: 01/10/2025	Last EDR Contact: 09/30/2025
Number of Days to Update: 100	Next Scheduled EDR Contact: 01/12/2026
	Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016	Source: Environmental Protection Agency
Date Data Arrived at EDR: 11/23/2016	Telephone: 202-564-2501
Date Made Active in Reports: 02/10/2017	Last EDR Contact: 09/23/2025
Number of Days to Update: 79	Next Scheduled EDR Contact: 01/12/2026
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 08/18/2017
Next Scheduled EDR Contact: 12/04/2017
Data Release Frequency: No Update Planned

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/07/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 27

Source: Nuclear Regulatory Commission
Telephone: 301-415-0717
Last EDR Contact: 10/23/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Quarterly

COAL ASH DOE: Steam-Electric Plant Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 10/16/2024
Date Made Active in Reports: 01/14/2025
Number of Days to Update: 90

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 08/28/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 01/12/2017
Date Data Arrived at EDR: 03/05/2019
Date Made Active in Reports: 11/11/2019
Number of Days to Update: 251

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/08/2025
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 09/13/2019
Date Data Arrived at EDR: 11/06/2019
Date Made Active in Reports: 02/10/2020
Number of Days to Update: 96

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/10/2025
Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 07/01/2019
Date Data Arrived at EDR: 07/01/2019
Date Made Active in Reports: 09/23/2019
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 09/17/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

DOT OPS: Incident and Accident Data

Department of Transportation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 06/30/2025
Date Data Arrived at EDR: 07/17/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 88

Source: Department of Transportation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 10/20/2025
Next Scheduled EDR Contact: 02/02/2026
Data Release Frequency: Quarterly

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 06/30/2025
Date Data Arrived at EDR: 07/29/2025
Date Made Active in Reports: 10/28/2025
Number of Days to Update: 91

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 09/23/2025
Next Scheduled EDR Contact: 01/13/2026
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2023
Date Data Arrived at EDR: 02/19/2025
Date Made Active in Reports: 03/07/2025
Number of Days to Update: 16

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Biennially

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 09/29/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Semi-Annually

FUSRAP: Formerly Utilized Sites Remedial Action Program

DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 03/03/2023
Date Data Arrived at EDR: 03/03/2023
Date Made Active in Reports: 06/09/2023
Number of Days to Update: 98

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 10/22/2025
Next Scheduled EDR Contact: 02/09/2026
Data Release Frequency: Varies

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 05/15/2025
Date Data Arrived at EDR: 05/15/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 75

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 08/11/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Varies

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 09/29/2025
Date Data Arrived at EDR: 10/01/2025
Date Made Active in Reports: 10/28/2025
Number of Days to Update: 27

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/05/2026
Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931 and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 09/26/2017
Next Scheduled EDR Contact: 01/08/2018
Data Release Frequency: Annually

MINES VIOLATIONS: MSHA Violation Assessment Data

Mines violation and assessment information. Department of Labor, Mine Safety & Health Administration.

Date of Government Version: 07/01/2025
Date Data Arrived at EDR: 07/01/2025
Date Made Active in Reports: 09/24/2025
Number of Days to Update: 85

Source: DOL, Mine Safety & Health Admini
Telephone: 202-693-9424
Last EDR Contact: 07/01/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Quarterly

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/01/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 70

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 08/18/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 04/08/2025
Date Data Arrived at EDR: 05/20/2025
Date Made Active in Reports: 08/12/2025
Number of Days to Update: 84

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

MINES MRDS: Mineral Resources Data System Mineral Resources Data System

Date of Government Version: 06/04/2024
Date Data Arrived at EDR: 11/22/2024
Date Made Active in Reports: 02/18/2025
Number of Days to Update: 88

Source: USGS
Telephone: 703-648-6533
Last EDR Contact: 08/21/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 05/28/2025	Source: Department of Interior
Date Data Arrived at EDR: 05/28/2025	Telephone: 202-208-2609
Date Made Active in Reports: 06/03/2025	Last EDR Contact: 09/09/2025
Number of Days to Update: 6	Next Scheduled EDR Contact: 12/15/2025
	Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/22/2025	Source: EPA
Date Data Arrived at EDR: 05/05/2025	Telephone: (214) 665-2200
Date Made Active in Reports: 05/21/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 16	Next Scheduled EDR Contact: 12/08/2025
	Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites

A listing of unexploded ordnance site locations

Date of Government Version: 02/14/2025	Source: Department of Defense
Date Data Arrived at EDR: 03/11/2025	Telephone: 703-704-1564
Date Made Active in Reports: 06/03/2025	Last EDR Contact: 10/01/2025
Number of Days to Update: 84	Next Scheduled EDR Contact: 01/19/2026
	Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 05/06/2021	Source: Environmental Protection Agency
Date Data Arrived at EDR: 05/21/2021	Telephone: 202-564-0527
Date Made Active in Reports: 08/11/2021	Last EDR Contact: 08/12/2025
Number of Days to Update: 82	Next Scheduled EDR Contact: 12/01/2025
	Data Release Frequency: Varies

ECHO: Enforcement & Compliance History Information

ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 06/22/2025	Source: Environmental Protection Agency
Date Data Arrived at EDR: 06/25/2025	Telephone: 202-564-2280
Date Made Active in Reports: 08/27/2025	Last EDR Contact: 09/26/2025
Number of Days to Update: 63	Next Scheduled EDR Contact: 01/12/2026
	Data Release Frequency: Quarterly

FUELS PROGRAM: EPA Fuels Program Registered Listing

This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 05/07/2025
Date Data Arrived at EDR: 05/13/2025
Date Made Active in Reports: 07/29/2025
Number of Days to Update: 77

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 08/07/2025
Next Scheduled EDR Contact: 11/24/2025
Data Release Frequency: Quarterly

PFAS NPL: Superfund Sites with PFAS Detections Information

EPA's Office of Land and Emergency Management and EPA Regional Offices maintain data describing what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 703-603-8895
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS FEDERAL SITES: Federal Sites PFAS Information

Several federal entities, such as the federal Superfund program, Department of Defense, National Aeronautics and Space Administration, Department of Transportation, and Department of Energy provided information for sites with known or suspected detections at federal facilities.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS TRIS: List of PFAS Added to the TRI

Section 7321 of the National Defense Authorization Act for Fiscal Year 2020 (NDAA) immediately added certain per- and polyfluoroalkyl substances (PFAS) to the list of chemicals covered by the Toxics Release Inventory (TRI) under Section 313 of the Emergency Planning and Community Right-to-Know Act (EPCRA) and provided a framework for additional PFAS to be added to TRI on an annual basis.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-566-0250
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS TSCA: PFAS Manufacture and Imports Information

EPA issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. EPA publishes non-confidential business information (non-CBI) and includes descriptive information about each site, corporate parent, production volume, other manufacturing information, and processing and use information.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS RCRA MANIFEST: PFAS Transfers Identified In the RCRA Database Listing

To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: PFAS, PFOA, PFOS, PERFL, AFFF, GENX, GEN-X (plus the VT waste codes). These keywords were searched for in the following text fields: Manifest handling instructions (MANIFEST_HANDLING_INSTR), Non-hazardous waste description (NON_HAZ_WASTE_DESCRIPTION), DOT printed information (DOT_PRINTED_INFORMATION), Waste line handling instructions (WASTE_LINE_HANDLING_INSTR), Waste residue comments (WASTE_RESIDUE_COMMENTS).

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 09/24/2025
Number of Days to Update: 90

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ATSDR: PFAS Contamination Site Location Listing

PFAS contamination site locations from the Department of Health & Human Services, Center for Disease Control & Prevention. ATSDR is involved at a number of PFAS-related sites, either directly or through assisting state and federal partners. As of now, most sites are related to drinking water contamination connected with PFAS production facilities or fire training areas where aqueous film-forming firefighting foam (AFFF) was regularly used.

Date of Government Version: 11/12/2024
Date Data Arrived at EDR: 07/21/2025
Date Made Active in Reports: 10/13/2025
Number of Days to Update: 84

Source: Department of Health & Human Services
Telephone: 202-741-5770
Last EDR Contact: 10/15/2025
Next Scheduled EDR Contact: 02/02/2026
Data Release Frequency: Varies

PFAS WQP: Ambient Environmental Sampling for PFAS

The Water Quality Portal (WQP) is a part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations and individuals submit project details and sampling results to this public repository. The information is commonly used for research and assessments of environmental quality.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS NPDES: Clean Water Act Discharge Monitoring Information

Any discharger of pollutants to waters of the United States from a point source must have a National Pollutant Discharge Elimination System (NPDES) permit. The process for obtaining limits involves the regulated entity (permittee) disclosing releases in a NPDES permit application and the permitting authority (typically the state but sometimes EPA) deciding whether to require monitoring or monitoring with limits. Caveats and Limitations: Less than half of states have required PFAS monitoring for at least one of their permittees and fewer states have established PFAS effluent limits for permittees. New rulemakings have been initiated that may increase the number of facilities monitoring for PFAS in the future.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS PROJECT: NORTHEASTERN UNIVERSITY PFAS PROJECT

The PFAS Contamination Site Tracker records qualitative and quantitative data from each site in a chart, specifically examining discovery, contamination levels, government response, litigation, health impacts, media coverage, and community characteristics. All data presented in the chart were extracted from government websites, such as state health departments or the Environmental Protection Agency, and news articles.

Date of Government Version: 05/15/2024
Date Data Arrived at EDR: 03/06/2025
Date Made Active in Reports: 06/03/2025
Number of Days to Update: 89

Source: Social Science Environmental Health Research Institute
Telephone: N/A
Last EDR Contact: 09/02/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Varies

PFAS ECHO: Facilities in Industries that May Be Handling PFAS Listing

Regulators and the public have expressed interest in knowing which regulated entities may be using PFAS. EPA has developed a dataset from various sources that show which industries may be handling PFAS. Approximately 120,000 facilities subject to federal environmental programs have operated or currently operate in industry sectors with processes that may involve handling and/or release of PFAS.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS ECHO FIRE TRAIN: Facilities in Industries that May Be Handling PFAS Listing

A list of fire training sites was added to the Industry Sectors dataset using a keyword search on the permitted facility's name to identify sites where fire-fighting foam may have been used in training exercises. Additionally, you may view an example spreadsheet of the subset of fire training facility data, as well as the keywords used in selecting or deselecting a facility for the subset. as well as the keywords used in selecting or deselecting a facility for the subset. These keywords were tested to maximize accuracy in selecting facilities that may use fire-fighting foam in training exercises, however, due to the lack of a required reporting field in the data systems for designating fire training sites, this methodology may not identify all fire training sites or may potentially misidentify them.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PFAS PT 139 AIRPORT: All Certified Part 139 Airports PFAS Information Listing

Since July 1, 2006, all certified part 139 airports are required to have fire-fighting foam onsite that meet military specifications (MIL-F-24385) (14 CFR 139.317). To date, these military specification fire-fighting foams are fluorinated and have been historically used for training and extinguishing. The 2018 FAA Reauthorization Act has a provision stating that no later than October 2021, FAA shall not require the use of fluorinated AFFF. This provision does not prohibit the use of fluorinated AFFF at Part 139 civilian airports; it only prohibits FAA from mandating its use. The Federal Aviation Administration's document AC 150/5210-6D - Aircraft Fire Extinguishing Agents provides guidance on Aircraft Fire Extinguishing Agents, which includes Aqueous Film Forming Foam (AFFF).

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-272-0167
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

AQUEOUS FOAM NRC: Aqueous Foam Related Incidents Listing

The National Response Center (NRC) serves as an emergency call center that fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. The spreadsheets posted to the NRC website contain initial incident data that has not been validated or investigated by a federal/state response agency. Response center calls from 1990 to the most recent complete calendar year where there was indication of Aqueous Film Forming Foam (AFFF) usage are included in this dataset. NRC calls may reference AFFF usage in the ?Material Involved? or ?Incident Description? fields.

Date of Government Version: 06/23/2025
Date Data Arrived at EDR: 06/26/2025
Date Made Active in Reports: 08/27/2025
Number of Days to Update: 62

Source: Environmental Protection Agency
Telephone: 202-267-2675
Last EDR Contact: 09/26/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

PCS: Permit Compliance System

PCS is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

Date of Government Version: 12/16/2016
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 03/10/2017
Number of Days to Update: 63

Source: EPA, Office of Water
Telephone: 202-564-2496
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PCS ENF: Enforcement data

No description is available for this data

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 02/05/2015
Date Made Active in Reports: 03/06/2015
Number of Days to Update: 29

Source: EPA
Telephone: 202-564-2497
Last EDR Contact: 09/24/2025
Next Scheduled EDR Contact: 01/12/2026
Data Release Frequency: Varies

BIOSOLIDS: ICIS-NPDES Biosolids Facility Data

The data reflects compliance information about facilities in the biosolids program.

Date of Government Version: 07/06/2025
Date Data Arrived at EDR: 07/10/2025
Date Made Active in Reports: 10/02/2025
Number of Days to Update: 84

Source: Environmental Protection Agency
Telephone: 202-564-4700
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

UST FINDER: UST Finder Database

EPA developed UST Finder, a web map application containing a comprehensive, state-sourced national map of underground storage tank (UST) and leaking UST (LUST) data. It provides the attributes and locations of active and closed USTs, UST facilities, and LUST sites from states and from Tribal lands and US territories. UST Finder contains information about proximity of UST facilities and LUST sites to: surface and groundwater public drinking water protection areas; estimated number of private domestic wells and number of people living nearby; and flooding and wildfires.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/04/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 106

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Varies

UST FINDER RELEASE: UST Finder Releases Database

US EPA's UST Finder data is a national composite of leaking underground storage tanks. This data contains information about, and locations of, leaking underground storage tanks. Data was collected from state sources and standardized into a national profile by EPA's Office of Underground Storage Tanks, Office of Research and Development, and the Association of State and Territorial Solid Waste Management Officials.

Date of Government Version: 06/08/2023
Date Data Arrived at EDR: 10/31/2023
Date Made Active in Reports: 01/18/2024
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-0394
Last EDR Contact: 08/13/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: Semi-Annually

E MANIFEST: Hazardous Waste Electronic Manifest System

EPA established a national system for tracking hazardous waste shipments electronically. This system, known as e-Manifest, will modernize the nation's cradle-to-grave hazardous waste tracking process while saving valuable time, resources, and dollars for industry and states.

Date of Government Version: 06/02/2025
Date Data Arrived at EDR: 06/04/2025
Date Made Active in Reports: 08/13/2025
Number of Days to Update: 70

Source: Environmental Protection Agency
Telephone: 833-501-6826
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 12/29/2025
Data Release Frequency: Varies

PFAS: Per- and Polyfluoroalkyl Substances (PFAS) Data

Site locations where pfas contamination, that have impacted to soil and groundwater have been confirmed.

Date of Government Version: 07/22/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/14/2025
Number of Days to Update: 83

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 10/22/2025
Next Scheduled EDR Contact: 02/09/2026
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AQUEOUS FOAM: A listing of reported incidents involving firefighting foam.

A listing of reported incidents involving firefighting foam.

Date of Government Version: 05/05/2025

Date Data Arrived at EDR: 05/07/2025

Date Made Active in Reports: 07/30/2025

Number of Days to Update: 84

Source: Department of Environmental Quality

Telephone: 225-219-3640

Last EDR Contact: 10/28/2025

Next Scheduled EDR Contact: 02/16/2026

Data Release Frequency: Varies

AIRS: Air Permit List

A listing of facilities with air permits issued by the Air Permits Division

Date of Government Version: 05/09/2025

Date Data Arrived at EDR: 05/14/2025

Date Made Active in Reports: 07/30/2025

Number of Days to Update: 77

Source: Department of Environmental Quality

Telephone: 225-219-3417

Last EDR Contact: 10/28/2025

Next Scheduled EDR Contact: 02/16/2026

Data Release Frequency: Varies

ASBESTOS: Asbestos Projects List

Asbestos demolition and renovation notification projects locations in the state.

Date of Government Version: 12/31/2024

Date Data Arrived at EDR: 04/08/2025

Date Made Active in Reports: 06/27/2025

Number of Days to Update: 80

Source: Department of Environmental Quality

Telephone: 225-219-3181

Last EDR Contact: 10/06/2025

Next Scheduled EDR Contact: 01/19/2026

Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Sites

A listing of coal ash impoundments.

Date of Government Version: 06/26/2025

Date Data Arrived at EDR: 06/26/2025

Date Made Active in Reports: 09/19/2025

Number of Days to Update: 85

Source: Department of Environmental Quality

Telephone: 225-219-3168

Last EDR Contact: 09/23/2025

Next Scheduled EDR Contact: 01/12/2026

Data Release Frequency: Varies

DRYCLEANERS: Drycleaner Facility Listing

A listing of drycleaner facilities.

Date of Government Version: 07/03/2025

Date Data Arrived at EDR: 07/03/2025

Date Made Active in Reports: 09/22/2025

Number of Days to Update: 81

Source: Department of Environmental Quality

Telephone: 225-219-3168

Last EDR Contact: 10/01/2025

Next Scheduled EDR Contact: 01/19/2026

Data Release Frequency: Varies

FIN ASSURANCE 1: Financial Assurance Information

Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay

Date of Government Version: 07/23/2025

Date Data Arrived at EDR: 07/23/2025

Date Made Active in Reports: 10/15/2025

Number of Days to Update: 84

Source: Department of Environmental Quality

Telephone: 225-219-3168

Last EDR Contact: 10/08/2025

Next Scheduled EDR Contact: 01/26/2026

Data Release Frequency: Varies

FIN ASSURANCE 2: Financial Assurance Information Listing

Information for solid waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 07/23/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 84

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 10/08/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

NPDES: LPDES Permits Database

A listing of sites with a Louisiana Pollutant Discharge Elimination System (LPDES) program issued permit.

Date of Government Version: 07/23/2025
Date Data Arrived at EDR: 07/23/2025
Date Made Active in Reports: 10/15/2025
Number of Days to Update: 84

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 10/08/2025
Next Scheduled EDR Contact: 01/26/2026
Data Release Frequency: Varies

REM: Division of Remediation Services Database

Facilities or sites come to the Underground Storage Tank and Remediation Division either through self notification or referral. These sites are designated for remediation via the following regulatory paths: Solid Waste (SW), Hazardous Waste (Haz Waste), Groundwater (Grwater), Inactive & Abandoned Sites (Confirmed or Potential), or Underground Storage Tanks (UST).

Date of Government Version: 07/09/2025
Date Data Arrived at EDR: 07/09/2025
Date Made Active in Reports: 09/10/2025
Number of Days to Update: 63

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Quarterly

UIC: Underground Injection Wells Listing

A listing of underground injection well locations.

Date of Government Version: 08/20/2025
Date Data Arrived at EDR: 08/20/2025
Date Made Active in Reports: 08/26/2025
Number of Days to Update: 6

Source: Department of Natural Resources
Telephone: 225-342-5515
Last EDR Contact: 08/20/2025
Next Scheduled EDR Contact: 12/01/2025
Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historical Auto Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historical Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR RECOVERED GOVERNMENT ARCHIVES

Exclusive Recovered Govt. Archives

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List

The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List

The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/15/2014
Number of Days to Update: 198

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank

The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2025
Date Data Arrived at EDR: 07/31/2025
Date Made Active in Reports: 10/16/2025
Number of Days to Update: 77

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 07/31/2025
Next Scheduled EDR Contact: 11/17/2025
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 12/31/2019
Date Data Arrived at EDR: 11/30/2023
Date Made Active in Reports: 12/01/2023
Number of Days to Update: 1

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 10/23/2025
Next Scheduled EDR Contact: 02/02/2026
Data Release Frequency: Quarterly

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 06/30/2018
Date Data Arrived at EDR: 07/19/2019
Date Made Active in Reports: 09/10/2019
Number of Days to Update: 53

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 10/01/2025
Next Scheduled EDR Contact: 01/19/2026
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 05/31/2018
Date Data Arrived at EDR: 06/19/2019
Date Made Active in Reports: 09/03/2019
Number of Days to Update: 76

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 08/27/2025
Next Scheduled EDR Contact: 12/15/2025
Data Release Frequency: Annually

Oil/Gas Pipelines

Source: Endeavor Business Media

Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Electric Power Transmission Line Data

Source: Endeavor Business Media

This map includes information copyrighted by Endeavor Business Media. This information is provided on a best effort basis and Endeavor Business Media does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of Endeavor Business Media.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

Current USGS 7.5 Minute Topographic Map

Source: U.S. Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK[®] - PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

HENDERSON I-10 SITE
I-10
BREAUX BRIDGE, LA 70517

TARGET PROPERTY COORDINATES

Latitude (North):	30.317196 - 30° 19' 1.91"
Longitude (West):	91.835519 - 91° 50' 7.87"
Universal Tranverse Mercator:	Zone 15
UTM X (Meters):	611958.7
UTM Y (Meters):	3354327.2
Elevation:	20 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	16395679 CECILIA, LA
Version Date:	2020

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

Flood Plain Panel at Target Property

22099C0150H

Additional Panels in search area:

Not Reported

FEMA Source Type

FEMA FIRM Flood data

FEMA Source Type

NATIONAL WETLAND INVENTORY

NWI Quad at Target Property
CECILIA

NWI Electronic
Data Coverage
YES - refer to the Overview Map and Detail Map

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles
Status: Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

<u>MAP ID</u>	<u>LOCATION FROM TP</u>	<u>GENERAL DIRECTION GROUNDWATER FLOW</u>
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT


Era:	Cenozoic
System:	Quaternary
Series:	Holocene
Code:	Qh (decoded above as Era, System & Series)

GEOLOGIC AGE IDENTIFICATION

Category: Stratified Sequence

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

SSURGO SOIL MAP - 8156261.2s



- ★ Target Property
- SSURGO Soil
- Water

0 1/16 1/8 1/4 Miles



SITE NAME: Henderson I-10 Site
ADDRESS: I-10
Breau Bridge LA 70517
LAT/LONG: 30.317196 / 91.835519

CLIENT: Chenier Environmental Consulting
CONTACT: Aaron Bass
INQUIRY #: 8156261.2s
DATE: October 29, 2025 3:20 pm

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. The following information is based on Soil Conservation Service SSURGO data.

Soil Map ID: 1

Soil Component Name: Tensas

Soil Surface Texture: silty clay loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 61 inches

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
1	0 inches	11 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 14.11 Min: 1.41	Max: 7.3 Min: 5.1
2	11 inches	43 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 14.11 Min: 1.41	Max: 7.3 Min: 5.1
3	43 inches	79 inches	very fine sandy loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 14.11 Min: 1.41	Max: 7.3 Min: 5.1

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Map ID: 2

Soil Component Name: Dundee

Soil Surface Texture: silt loam

Hydrologic Group: Class C - Slow infiltration rates. Soils with layers impeding downward movement of water, or soils with moderately fine or fine textures.

Soil Drainage Class: Somewhat poorly drained

Hydric Status: Not hydric

Corrosion Potential - Uncoated Steel: High

Depth to Bedrock Min: > 0 inches

Depth to Watertable Min: > 77 inches

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Saturated hydraulic conductivity micro m/sec	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
1	0 inches	7 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 4.23	Max: 7.3 Min: 4.5
2	7 inches	42 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 4.23	Max: 7.3 Min: 4.5
3	42 inches	70 inches	silt loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay	Max: 14.11 Min: 4.23	Max: 7.3 Min: 4.5

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

<u>DATABASE</u>	<u>SEARCH DISTANCE (miles)</u>
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 0.001 miles
State Database	1.000

FEDERAL USGS WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>
A1	USGS40000395280	1/4 - 1/2 Mile SSE
F64	USGS40000395208	1/2 - 1 Mile SE
J76	USGS40000395272	1/2 - 1 Mile ESE
K80	USGS40000395639	1/2 - 1 Mile NE
85	USGS40000395149	1/2 - 1 Mile SE
L89	USGS40000395143	1/2 - 1 Mile SW

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>
B2	LATD60000113611	1/4 - 1/2 Mile SE
B3	LATD60000113854	1/4 - 1/2 Mile SE
B4	LATD60000113858	1/4 - 1/2 Mile SE
A5	LATD60000111198	1/4 - 1/2 Mile SSE
A6	LATD60000187254	1/4 - 1/2 Mile SE
A7	LATD60000191524	1/4 - 1/2 Mile SE
A8	LATD60000187253	1/4 - 1/2 Mile SE
A9	LATD60000186832	1/4 - 1/2 Mile SE
A10	LATD60000186833	1/4 - 1/2 Mile SE
A11	LATD60000191525	1/4 - 1/2 Mile SE
A12	LATD60000206259	1/4 - 1/2 Mile SE
A13	LATD60000206260	1/4 - 1/2 Mile SE
A14	LATD60000206117	1/4 - 1/2 Mile SE
A15	LATD60000198621	1/4 - 1/2 Mile SE
A16	LATD60000198622	1/4 - 1/2 Mile SE
A17	LATD60000111596	1/4 - 1/2 Mile SSE
A18	LATD60000110548	1/4 - 1/2 Mile SSE
A19	LATD60000180164	1/4 - 1/2 Mile SSE
A20	LATD60000113959	1/4 - 1/2 Mile SSE
A21	LATD60000114028	1/4 - 1/2 Mile SSE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A22	LATD60000111595	1/4 - 1/2 Mile SSE
A23	LATD60000110546	1/4 - 1/2 Mile SSE
A24	LATD60000109516	1/4 - 1/2 Mile SSE
A25	LATD60000109513	1/4 - 1/2 Mile SSE
A26	LATD60000109514	1/4 - 1/2 Mile SSE
A27	LATD60000109515	1/4 - 1/2 Mile SSE
A28	LATD60000113748	1/4 - 1/2 Mile SSE
A29	LATD60000113747	1/4 - 1/2 Mile SSE
A30	LATD60000113749	1/4 - 1/2 Mile SSE
A31	LATD60000113751	1/4 - 1/2 Mile SSE
A32	LATD60000113750	1/4 - 1/2 Mile SSE
A33	LATD60000113706	1/4 - 1/2 Mile SSE
A34	LATD60000112490	1/4 - 1/2 Mile SSE
A35	LATD60000000425	1/4 - 1/2 Mile SSE
A36	LATD60000112491	1/4 - 1/2 Mile SSE
A37	LATD60000113705	1/4 - 1/2 Mile SSE
A38	LATD60000113704	1/4 - 1/2 Mile SSE
A39	LATD60000184628	1/4 - 1/2 Mile SSE
A40	LATD60000113996	1/4 - 1/2 Mile SSE
A41	LATD60000184629	1/4 - 1/2 Mile SSE
A42	LATD60000184631	1/4 - 1/2 Mile SSE
A43	LATD60000184630	1/4 - 1/2 Mile SSE
A44	LATD60000113995	1/4 - 1/2 Mile SSE
A45	LATD60000113753	1/4 - 1/2 Mile SSE
A46	LATD60000113752	1/4 - 1/2 Mile SSE
A47	LATD60000113818	1/4 - 1/2 Mile SSE
A48	LATD60000113994	1/4 - 1/2 Mile SSE
A49	LATD60000113819	1/4 - 1/2 Mile SSE
50	LATD60000110448	1/4 - 1/2 Mile WNW
C51	LATD60000114003	1/2 - 1 Mile South
C52	LATD60000113943	1/2 - 1 Mile South
C53	LATD60000114004	1/2 - 1 Mile South
C54	LATD60000114006	1/2 - 1 Mile South
C55	LATD60000114005	1/2 - 1 Mile South
56	LATD60000179878	1/2 - 1 Mile West
57	LATD60000113127	1/2 - 1 Mile NW
D58	LATD60000111988	1/2 - 1 Mile NNE
59	LATD60000109185	1/2 - 1 Mile NE
60	LATD60000113181	1/2 - 1 Mile ESE
D61	LATD60000111990	1/2 - 1 Mile NNE
62	LATD60000111066	1/2 - 1 Mile NW
E63	LATD60000110013	1/2 - 1 Mile NNE
F65	LATD60000184917	1/2 - 1 Mile SE
E66	LATD60000157485	1/2 - 1 Mile NNE
G67	LATD60000109291	1/2 - 1 Mile East
G68	LATD60000109292	1/2 - 1 Mile East
G69	LATD60000109293	1/2 - 1 Mile East
70	LATD60000178938	1/2 - 1 Mile SE
H71	LATD60000113594	1/2 - 1 Mile SW
H72	LATD60000113595	1/2 - 1 Mile SW
73	LATD60000110871	1/2 - 1 Mile West
I74	LATD60000110285	1/2 - 1 Mile NE

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

STATE DATABASE WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
I75	LATD60000109172	1/2 - 1 Mile NE
I77	LATD60000110286	1/2 - 1 Mile NE
J78	LATD60000113586	1/2 - 1 Mile ESE
K79	LATD60000109681	1/2 - 1 Mile NE
81	LATD60000186511	1/2 - 1 Mile South
J82	LATD60000176542	1/2 - 1 Mile ESE
83	LATD60000181265	1/2 - 1 Mile ENE
84	LATD60000110287	1/2 - 1 Mile West
86	LATD60000109425	1/2 - 1 Mile NE
L87	LATD60000212076	1/2 - 1 Mile SW
88	LATD60000191994	1/2 - 1 Mile East
L90	LATD60000113906	1/2 - 1 Mile SW

OTHER STATE DATABASE INFORMATION

STATE OIL/GAS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
1	LAOG13000035313	0 - 1/8 Mile ENE
2	LAOG13000165595	1/4 - 1/2 Mile WNW
3	LAOG13000026663	1/4 - 1/2 Mile North
4	LAOG13000131977	1/4 - 1/2 Mile East
A5	LAOG13000118473	1/4 - 1/2 Mile WNW
A6	LAOG13000212503	1/4 - 1/2 Mile WNW
7	LAOG13000029868	1/4 - 1/2 Mile ENE
B9	LAOG13000143685	1/2 - 1 Mile WNW
B8	LAOG13000138723	1/2 - 1 Mile WNW
10	LAOG13000213370	1/2 - 1 Mile WSW
11	LAOG13000233535	1/2 - 1 Mile West
12	LAOG13000216329	1/2 - 1 Mile NW
C13	LAOG13000021888	1/2 - 1 Mile West
C14	LAOG13000117683	1/2 - 1 Mile West
15	LAOG13000136056	1/2 - 1 Mile WSW
C16	LAOG13000182288	1/2 - 1 Mile West
C17	LAOG13000228598	1/2 - 1 Mile West
18	LAOG13000184160	1/2 - 1 Mile NW
D20	LAOG13000139137	1/2 - 1 Mile West
D19	LAOG13000038102	1/2 - 1 Mile West
21	LAOG13000144124	1/2 - 1 Mile WNW
22	LAOG13000172201	1/2 - 1 Mile West
E23	LAOG13000216331	1/2 - 1 Mile West
E24	LAOG13000071156	1/2 - 1 Mile West

PHYSICAL SETTING SOURCE MAP - 8156261.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

0 1/4 1/2 1 Miles

- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil, gas or related wells



SITE NAME: Henderson I-10 Site
 ADDRESS: I-10
 Breaux Bridge LA 70517
 LAT/LONG: 30.317196 / 91.835519

CLIENT: Chenier Environmental Consulting
 CONTACT: Aaron Bass
 INQUIRY #: 8156261.2s
 DATE: October 29, 2025 3:19 pm

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

A1
SSE
1/4 - 1/2 Mile
Lower

FED USGS USGS40000395280

Organization ID:	USGS-LA	Organization Name:	USGS Louisiana Water Science Center
Monitor Location:	SMn- 52	Type:	Well
Description:	Not Reported	HUC:	08080102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Coastal lowlands aquifer system		
Formation Type:	Atchafalaya Aquifer	Aquifer Type:	Not Reported
Construction Date:	19400101	Well Depth:	143
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

B2
SE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113611

Well ID:	099-5928Z	Local Well #:	5928Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	01	Owner:	WURSTER OIL
Well Depth:	13	Date Drilled:	08/90
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	PETRON, INC.
Driller #:	328	Hole Depth:	13
Elevation:	18	Depth From Surface:	5.00
Measured Date:	08/27/90	Date Added by Agency:	2002-01-22
Date Registered by Agency:	08/90	Date Plugged:	06/01
Plugged By:	PETRON, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	3-13	Assoc Well Serial #:	Not Reported
Well Name:	824-05	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Well String Removed And Borehole Cemented		
Remarks:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

B3
SE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113854

Well ID:	099-5929Z	Local Well #:	5929Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	02	Owner:	WURSTER OIL
Well Depth:	13	Date Drilled:	08/90
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	PETRON, INC.
Driller #:	328	Hole Depth:	13
Elevation:	18	Depth From Surface:	5.70
Measured Date:	08/27/90	Date Added by Agency:	2002-01-22
Date Registered by Agency:	08/90	Date Plugged:	06/01
Plugged By:	PETRON, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	3-13	Assoc Well Serial #:	Not Reported
Well Name:	824-06	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Well String Was Removed And The Borehole Was Cemented		
Remarks:	Not Reported		

B4
SE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113858

Well ID:	099-5930Z	Local Well #:	5930Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	03	Owner:	WURSTER OIL
Well Depth:	13	Date Drilled:	08/90
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	PETRON, INC.
Driller #:	328	Hole Depth:	13
Elevation:	18	Depth From Surface:	5.30
Measured Date:	08/27/90	Date Added by Agency:	2002-01-22
Date Registered by Agency:	08/90	Date Plugged:	06/01

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Plugged By:	PETRON, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	3-13	Assoc Well Serial #:	Not Reported
Well Name:	824-07	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Well String Was Cemented In Place		
Remarks:	Not Reported		

A5
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000111198

Well ID:	099-52	Local Well #:	52
Well Use:	domestic	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	DUPOIS, A	Well Depth:	143
Date Drilled:	1940	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DUPOIS	Driller #:	000
Hole Depth:	0	Elevation:	Not Reported
Depth From Surface:	0.00	Measured Date:	Not Reported
Date Added by Agency:	1996-09-03	Date Registered by Agency:	Not Reported
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	5	Drawdown on Test:	Not Reported
Casing Diameter:	2	Casing Material:	Not Reported
Screen Diameter:	Not Reported	Screen Interval:	123-143
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A6
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000187254

Well ID: 099-7762Z Well Use: monitor Well Status: Active Owner: HIT N RUN FOOD STORES Date Drilled: 3/10/14 Mechanic Test: N Bio Analysis: N Driller: JONES ENVIRONMENTAL, INC. Hole Depth: 20 Depth From Surface: 2.16 Date Added by Agency: Not Reported Date Plugged: Not Reported Yield on Pump Test: Not Reported Casing Diameter: 4 Screen Diameter: 4 Assoc Well Serial #: Not Reported Pumpdown Method: Not Reported Top of Extension Pipe: Not Reported Screen Material Type: PLASTIC Ground Elevation: Not Reported Avg Heat Pump Depth: 0 Annular Space Cemented Depth: 2 Screen Slot Size: .01 Pump Depth: Not Reported Planned Pumpage (GPM): 0 Planned Pumpage (days/yr): Not Reported Measured Method: Not Reported Pump Test Date: 0 Static Measurement Method: Not Reported Pump Test Done: Not Reported P and A Comments: Not Reported Casing Length: 7 Owner ID: 68650 Remarks: Not Reported	Local Well #: 7762Z Sub-use: Not Reported Seq #: 01 Well Depth: 20 Geo Unit: 112MRVAC Chemical Analysis: N Pump Test: N Driller #: 308 Elevation: Not Reported Measured Date: 3-10-14 Date Registered by Agency: 4-17-14 Plugged By: Not Reported Drawdown on Test: Not Reported Casing Material: PLASTIC Screen Interval: Not Reported Well Name: MW-2 Extension Pipe Length: Not Reported Bottom of Extension Pipe: Not Reported Gravel Packed: N Screen Diameter: Not Reported Heat Pump Hole #: Not Reported Screen interval Length: 13 Inspection Comments: Not Reported Pump Horse Power: Not Reported Planned Pumpage (hr/day): 0 Pump Rate (Gal/day): Not Reported Hrs of Test: Not Reported Static Water Level: Not Reported Water Level Post-Test: Not Reported Cementing Method: P P and A Details: Not Reported Driller Owner: Not Reported Comments: Not Reported
--	--

A7
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000191524

Well ID: 099-7830Z Well Use: monitor Well Status: Active Owner: HIT N RUN FOOD STORES Date Drilled: 05/18/2014 Mechanic Test: N Bio Analysis: N Driller: JONES ENVIRONMENTAL, INC Hole Depth: 20	Local Well #: 7830Z Sub-use: Not Reported Seq #: 04 Well Depth: 20 Geo Unit: 112MRVAC Chemical Analysis: N Pump Test: N Driller #: 308 Elevation: Not Reported
--	--

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Depth From Surface:	3.15	Measured Date:	06/03/2015
Date Added by Agency:	Not Reported	Date Registered by Agency:	06/26/2015
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-5
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A8
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000187253

Well ID:	099-7761Z	Local Well #:	7761Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	00
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	3/10/14	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC.	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	3.15	Measured Date:	3-10-14
Date Added by Agency:	Not Reported	Date Registered by Agency:	4-17-14
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-1
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.01	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A9
SE
1/4 - 1/2 Mile
Lower

LA WELLS **LATD60000186832**

Well ID:	099-7763Z	Local Well #:	7763Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	02
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	3/10/14	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC.	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	2.49	Measured Date:	3-10-14
Date Added by Agency:	Not Reported	Date Registered by Agency:	4-17-14
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-3
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.01	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A10
SE
1/4 - 1/2 Mile
Lower

LA WELLS **LATD60000186833**

Well ID:	099-7764Z	Local Well #:	7764Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	03
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	3/10/14	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Driller:	JONES ENVIRONMENTAL, INC.	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	2.83	Measured Date:	3-10-14
Date Added by Agency:	Not Reported	Date Registered by Agency:	4-17-14
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-4
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.01	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A11
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000191525

Well ID:	099-7831Z	Local Well #:	7831Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	05
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	05/18/2015	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	3.64	Measured Date:	06/03/2015
Date Added by Agency:	Not Reported	Date Registered by Agency:	06/26/2015
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-6
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A12
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000206259

Well ID:	099-8024Z	Local Well #:	8024Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	09
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	09/29/2017	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	5.63	Measured Date:	09/29/2017
Date Added by Agency:	Not Reported	Date Registered by Agency:	10/17/2017
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-10
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	15
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	5	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A13
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000206260

Well ID:	099-8025Z	Local Well #:	8025Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	10
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	09/29/2017	Geo Unit:	112MRVAC

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	3.88	Measured Date:	09/29/2017
Date Added by Agency:	Not Reported	Date Registered by Agency:	10/17/2017
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-11
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	15
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	5	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A14
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000206117

Well ID:	099-8023Z	Local Well #:	8023Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	08
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	09/29/2017	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	4.35	Measured Date:	09/29/2017
Date Added by Agency:	Not Reported	Date Registered by Agency:	10/17/2017
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-9
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	15
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	5	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A15
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000198621

Well ID:	099-7945Z	Local Well #:	7945Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	06
Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	11/08/2016	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	3.1	Measured Date:	11/15/2016
Date Added by Agency:	Not Reported	Date Registered by Agency:	11/16/2016
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-7
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

A16
SE
1/4 - 1/2 Mile
Lower

LA WELLS LATD60000198622

Well ID:	099-7946Z	Local Well #:	7946Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Active	Seq #:	07

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Owner:	HIT N RUN FOOD STORES	Well Depth:	20
Date Drilled:	11/08/2016	Geo Unit:	112MRVAC
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	JONES ENVIRONMENTAL, INC	Driller #:	308
Hole Depth:	20	Elevation:	Not Reported
Depth From Surface:	3.08	Measured Date:	11/15/2016
Date Added by Agency:	Not Reported	Date Registered by Agency:	11/16/2016
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-8
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	PLASTIC	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	2	Screen interval Length:	13
Screen Slot Size:	.010	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	P
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	7	Driller Owner:	Not Reported
Owner ID:	68650	Comments:	Not Reported
Remarks:	Not Reported		

**A17
SSE
1/4 - 1/2 Mile
Higher**

LA WELLS LATD60000111596

Well ID:	099-5733Z	Local Well #:	5733Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	01	Date Drilled:	06/92
Well Depth:	10	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	G & E
Pump Test:	Not Reported	Hole Depth:	10
Driller #:	292	Depth From Surface:	2.11
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	07/01/92	Date Plugged:	05/00
Date Registered by Agency:	07/92	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	1-10	Pumpdown Method:	Not Reported
Well Name:	MW-7	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A18
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000110548

Well ID:	099-5736Z	Local Well #:	5736Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	02	Date Drilled:	06/92
Well Depth:	10	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	G & E
Pump Test:	Not Reported	Hole Depth:	10
Driller #:	292	Depth From Surface:	1.55
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	07/01/92	Date Plugged:	05/00
Date Registered by Agency:	07/92	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	1-10	Pumpdown Method:	Not Reported
Well Name:	MW-9	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

A19
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000180164

Well ID:	099-6052Z	Local Well #:	6052Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	01	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	06/91
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	G & E
Driller #:	292	Hole Depth:	12
Elevation:	20	Depth From Surface:	0.90
Measured Date:	07/02/91	Date Added by Agency:	1995-05-30
Date Registered by Agency:	07/91	Date Plugged:	05/95
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	1-11	Assoc Well Serial #:	Not Reported
Well Name:	MW-4	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A20
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113959

Well ID:	099-7493Z	Local Well #:	7493Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	01
Owner:	WILLIAMS TRAVEL	Well Depth:	12
Date Drilled:	06/09	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	13	Elevation:	20
Depth From Surface:	2.00	Measured Date:	06/18/09
Date Added by Agency:	2009-07-17	Date Registered by Agency:	07/09
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	2-12
Assoc Well Serial #:	Not Reported	Well Name:	MW-11
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 2 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A21
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000114028

Well ID:	099-7494Z	Local Well #:	7494Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	02
Owner:	WILLIAMS TRAVEL	Well Depth:	12
Date Drilled:	06/09	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	13	Elevation:	20
Depth From Surface:	2.00	Measured Date:	06/18/09
Date Added by Agency:	2009-07-17	Date Registered by Agency:	07/09
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	2-12
Assoc Well Serial #:	Not Reported	Well Name:	MW-10
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

P and A Details:	10 Feet Of Screen And 2 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A22
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000111595

Well ID:	099-5732Z	Local Well #:	5732Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	02	Owner:	MAPCO PETRO
Well Depth:	10	Date Drilled:	06/92
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	G & E
Driller #:	292	Hole Depth:	10
Elevation:	20	Depth From Surface:	1.13
Measured Date:	07/01/92	Date Added by Agency:	2000-06-15
Date Registered by Agency:	07/92	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	1-10	Assoc Well Serial #:	Not Reported
Well Name:	MW-6	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A23
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000110546

Well ID:	099-5734Z	Local Well #:	5734Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	01	Owner:	MAPCO PETRO
Well Depth:	10	Date Drilled:	06/92
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pump Test:	Not Reported	Driller:	G & E
Driller #:	292	Hole Depth:	10
Elevation:	20	Depth From Surface:	2.30
Measured Date:	07/01/92	Date Added by Agency:	2000-06-09
Date Registered by Agency:	07/92	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	1-10	Assoc Well Serial #:	Not Reported
Well Name:	MW-8	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**A24
SSE
1/4 - 1/2 Mile
Higher**

LA WELLS LATD60000109516

Well ID:	099-6053Z	Local Well #:	6053Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	01	Date Drilled:	06/91
Well Depth:	16	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	G & E
Pump Test:	Not Reported	Hole Depth:	16
Driller #:	292	Depth From Surface:	1.20
Elevation:	20	Date Added by Agency:	1995-05-30
Measured Date:	07/02/91	Date Plugged:	05/95
Date Registered by Agency:	07/91	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	1-16	Pumpdown Method:	Not Reported
Well Name:	MW-5	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A25
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000109513

Well ID: 099-6049Z Well Use: plugged and abandoned monitor Sub-use: Plugged Seq #: 01 Well Depth: 17 Geo Unit: 112MRVAC Chemical Analysis: Not Reported Pump Test: Not Reported Driller #: 292 Elevation: 20 Measured Date: 07/02/91 Date Registered by Agency: 07/91 Plugged By: SEMS, INC. Drawdown on Test: Not Reported Casing Material: PLASTIC Screen Interval: 1-17 Well Name: MW-1 Extension Pipe Length: Not Reported Bottom of Extension Pipe: Not Reported Gravel Packed: N Screen Diameter: Not Reported Heat Pump Hole #: Not Reported Screen interval Length: Not Reported Inspection Comments: Not Reported Pump Horse Power: Not Reported Planned Pumpage (hr/day): 0 Pump Rate (Gal/day): Not Reported Hrs of Test: Not Reported Static Water Level: Not Reported Water Level Post-Test: Not Reported Cementing Method: Not Reported P and A Details: Not Reported Driller Owner: Not Reported Comments: Not Reported	Local Well #: 6049Z Well Status: Plugged and Abandoned Owner: MAPCO PETRO Date Drilled: 06/91 Mechanic Test: Not Reported Bio Analysis: Not Reported Driller: G & E Hole Depth: 17 Depth From Surface: 1.40 Date Added by Agency: 1996-05-29 Date Plugged: 05/95 Yield on Pump Test: Not Reported Casing Diameter: 4 Screen Diameter: 4 Assoc Well Serial #: Not Reported Pumpdown Method: Not Reported Top of Extension Pipe: Not Reported Screen Material Type: Not Reported Ground Elevation: Not Reported Avg Heat Pump Depth: 0 Annular Space Cemented Depth: Not Reported Screen Slot Size: Not Reported Pump Depth: Not Reported Planned Pumpage (GPM): 0 Planned Pumpage (days/yr): Not Reported Measured Method: Not Reported Pump Test Date: 0 Static Measurement Method: Not Reported Pump Test Done: Not Reported P and A Comments: Not Reported Casing Length: Not Reported Owner ID: 0 Remarks: Not Reported
---	--

A26
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000109514

Well ID: 099-6050Z Well Use: plugged and abandoned monitor Sub-use: Plugged Seq #: 02 Well Depth: 16	Local Well #: 6050Z Well Status: Plugged and Abandoned Owner: MAPCO PETRO Date Drilled: 06/91
--	--

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	G & E
Driller #:	292	Hole Depth:	16
Elevation:	20	Depth From Surface:	1.10
Measured Date:	07/02/91	Date Added by Agency:	1995-05-30
Date Registered by Agency:	07/91	Date Plugged:	05/95
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	1-16	Assoc Well Serial #:	Not Reported
Well Name:	MW-2	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A27
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000109515

Well ID:	099-6051Z	Local Well #:	6051Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	03	Date Drilled:	06/91
Well Depth:	16	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	G & E
Pump Test:	Not Reported	Hole Depth:	16
Driller #:	292	Depth From Surface:	1.10
Elevation:	20	Date Added by Agency:	1996-05-29
Measured Date:	07/02/91	Date Plugged:	05/95
Date Registered by Agency:	07/91	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	1-16	Pumpdown Method:	Not Reported
Well Name:	MW-3	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A28
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113748

Well ID:	099-6251Z	Local Well #:	6251Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	02	Date Drilled:	05/94
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	1.40
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	06/13/94	Date Plugged:	05/00
Date Registered by Agency:	06/94	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	3170
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-13	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

A29
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113747

Well ID:	099-6250Z	Local Well #:	6250Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Seq #:	01	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	05/94
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	0.95
Measured Date:	06/13/94	Date Added by Agency:	2000-06-09
Date Registered by Agency:	06/94	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-12	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A30
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113749

Well ID:	099-6252Z	Local Well #:	6252Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	03	Date Drilled:	05/94
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	1.38
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	06/13/94	Date Plugged:	05/00
Date Registered by Agency:	06/94	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	3170
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-14	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**A31
SSE
1/4 - 1/2 Mile
Higher**

LA WELLS LATD60000113751

Well ID:	099-6254Z	Local Well #:	6254Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	05	Date Drilled:	05/94
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	2.47
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	06/13/94	Date Plugged:	05/00
Date Registered by Agency:	06/94	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	3170
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-16	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

A32
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113750

Well ID:	099-6253Z	Local Well #:	6253Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	04	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	05/94
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	1.06
Measured Date:	06/13/94	Date Added by Agency:	2000-06-09
Date Registered by Agency:	06/94	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-15	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A33
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113706

Well ID:	099-7316Z	Local Well #:	7316Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	21
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	12/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	15	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-8
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

**A34
SSE
1/4 - 1/2 Mile
Higher**

LA WELLS LATD60000112490

Well ID:	099-7310Z	Local Well #:	7310Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	15
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	11/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	20	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-2
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A35
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000000425

Well ID:	099-6255Z	Local Well #:	6255Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	06	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	05/94
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	1.53
Measured Date:	06/13/94	Date Added by Agency:	2000-06-09
Date Registered by Agency:	06/94	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-17	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A36
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000112491

Well ID:	099-7311Z	Local Well #:	7311Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	16
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	11/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	15	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-3
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A37
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113705

Well ID:	099-7315Z	Local Well #:	7315Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	20
Owner:	WILLIAMS TRAVEL	Well Depth:	12
Date Drilled:	12/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	14	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	2-12
Assoc Well Serial #:	Not Reported	Well Name:	MW-7
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A38
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113704

Well ID:	099-7314Z	Local Well #:	7314Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	19
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	12/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	15	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-6
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

A39
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000184628

Well ID:	099-7309Z	Local Well #:	7309Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	14
Owner:	WILLIAMS TRAVEL	Well Depth:	12
Date Drilled:	11/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	12	Elevation:	20
Depth From Surface:	2.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	MW-1
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 2 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A40
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113996

Well ID:	099-6417Z	Local Well #:	6417Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	10	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	10/94
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	2.00
Measured Date:	10/04/94	Date Added by Agency:	2000-06-09

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Date Registered by Agency:	05/96	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-20	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A41
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000184629

Well ID:	099-7312Z	Local Well #:	7312Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	17
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	11/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	15	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-4
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A42
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000184631

Well ID:	099-7317Z	Local Well #:	7317Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	22
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	11/06	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	15	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-9
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A43
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000184630

Well ID:	099-7313Z	Local Well #:	7313Z
Well Use:	monitor	Sub-use:	Not Reported
Well Status:	Plugged and Abandoned	Seq #:	18
Owner:	WILLIAMS TRAVEL	Well Depth:	15
Date Drilled:	11/06	Geo Unit:	00000000

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	SEMS, INC.	Driller #:	464
Hole Depth:	15	Elevation:	20
Depth From Surface:	3.00	Measured Date:	12/08/06
Date Added by Agency:	2007-01-24	Date Registered by Agency:	01/07
Date Plugged:	12-21-10	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	5-15
Assoc Well Serial #:	Not Reported	Well Name:	MW-5
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported		
P and A Details:	10 Feet Of Screen And 5 Feet Of Riser Pipe Was Removed From Borehole. Borehole Was Plugged With Bentonite-Cement Mixture		
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

A44
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113995

Well ID:	099-6416Z	Local Well #:	6416Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	09	Date Drilled:	10/94
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	2.00
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	10/04/94	Date Plugged:	05/00
Date Registered by Agency:	05/96	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	3170
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-19	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**A45
SSE
1/4 - 1/2 Mile
Higher**

LA WELLS LATD60000113753

Well ID:	099-6418Z	Local Well #:	6418Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	11	Date Drilled:	10/94
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	2.00
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	10/04/94	Date Plugged:	05/00
Date Registered by Agency:	05/96	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	3170
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-21	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

A46
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113752

Well ID:	099-6256Z	Local Well #:	6256Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	07	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	05/94
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	1.39
Measured Date:	06/13/94	Date Added by Agency:	2000-06-09
Date Registered by Agency:	06/94	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-18	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A47
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113818

Well ID:	099-6419Z	Local Well #:	6419Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	12	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	08/93
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	3.00
Measured Date:	08/12/93	Date Added by Agency:	2000-06-09
Date Registered by Agency:	05/96	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-10	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

A48
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113994

Well ID:	099-6415Z	Local Well #:	6415Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	MAPCO PETRO
Seq #:	08	Date Drilled:	08/93
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	3.00
Elevation:	20	Date Added by Agency:	2000-06-09
Measured Date:	08/12/93	Date Plugged:	05/00
Date Registered by Agency:	05/96	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	3170
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-11	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Comments: Not Reported Remarks: Not Reported

A49
SSE
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000113819

Well ID:	099-6420Z	Local Well #:	6420Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	13	Owner:	MAPCO PETRO
Well Depth:	12	Date Drilled:	10/94
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	20	Depth From Surface:	2.00
Measured Date:	10/04/94	Date Added by Agency:	2000-06-09
Date Registered by Agency:	05/96	Date Plugged:	05/00
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	3170
Well Name:	MW-22	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

50
WNW
1/4 - 1/2 Mile
Higher

LA WELLS LATD60000110448

Well ID:	099-5198Z	Local Well #:	5198Z
Well Use:	oil/gas well rig supply	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	AMOCO PROD CO	Well Depth:	161
Date Drilled:	10/85	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	GUICHARD	Driller #:	190
Hole Depth:	167	Elevation:	22
Depth From Surface:	18.00	Measured Date:	10/23/85
Date Added by Agency:	2000-08-08	Date Registered by Agency:	11/85

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	95	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	STEEL
Screen Diameter:	4	Screen Interval:	141-161
Assoc Well Serial #:	201632	Well Name:	BAPTISTE 2
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

C51
South
1/2 - 1 Mile
Higher

LA WELLS LATD60000114003

Well ID:	099-6883Z	Local Well #:	6883Z
Well Use:	plugged and abandoned monitor		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	02	Owner:	WILLIAMS TRAVEL
Well Depth:	12	Date Drilled:	10/01
Geo Unit:	112MRVAC	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	SEMS, INC.
Driller #:	464	Hole Depth:	12
Elevation:	23	Depth From Surface:	2.51
Measured Date:	10/11/01	Date Added by Agency:	2003-06-27
Date Registered by Agency:	10/01	Date Plugged:	06/03
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	Not Reported
Well Name:	MW-2	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

C52
South
1/2 - 1 Mile
Higher

LA WELLS LATD60000113943

Well ID:	099-6882Z	Local Well #:	6882Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	WILLIAMS TRAVEL
Seq #:	01	Date Drilled:	10/01
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	2.98
Elevation:	23	Date Added by Agency:	2003-06-27
Measured Date:	10/11/01	Date Plugged:	06/03
Date Registered by Agency:	10/01	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-1	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

C53
South
1/2 - 1 Mile
Higher

LA WELLS LATD60000114004

Well ID:	099-6884Z	Local Well #:	6884Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	WILLIAMS TRAVEL
Seq #:	03	Date Drilled:	10/01
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Elevation:	23	Depth From Surface:	2.90
Measured Date:	10/11/01	Date Added by Agency:	2003-06-27
Date Registered by Agency:	10/01	Date Plugged:	06/03
Plugged By:	SEMS, INC.	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	2-12	Assoc Well Serial #:	Not Reported
Well Name:	MW-3	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

C54
South
1/2 - 1 Mile
Higher

LA WELLS LATD60000114006

Well ID:	099-6886Z	Local Well #:	6886Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	WILLIAMS TRAVEL
Seq #:	05	Date Drilled:	10/01
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	4.03
Elevation:	23	Date Added by Agency:	2003-06-27
Measured Date:	10/11/01	Date Plugged:	06/03
Date Registered by Agency:	10/01	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-5	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

C55
South
1/2 - 1 Mile
Higher

LA WELLS LATD60000114005

Well ID:	099-6885Z	Local Well #:	6885Z
Well Use:	plugged and abandoned monitor	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	WILLIAMS TRAVEL
Seq #:	04	Date Drilled:	10/01
Well Depth:	12	Mechanic Test:	Not Reported
Geo Unit:	112MRVAC	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	SEMS, INC.
Pump Test:	Not Reported	Hole Depth:	12
Driller #:	464	Depth From Surface:	1.88
Elevation:	23	Date Added by Agency:	2003-06-27
Measured Date:	10/11/01	Date Plugged:	06/03
Date Registered by Agency:	10/01	Yield on Pump Test:	Not Reported
Plugged By:	SEMS, INC.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	2-12	Pumpdown Method:	Not Reported
Well Name:	MW-4	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

56
West
1/2 - 1 Mile
Higher

LA WELLS LATD60000179878

Well ID:	099-5061Z	Local Well #:	5061Z
Well Use:	plugged and abandoned rig supply	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	AMOCO PROD CO
Seq #:	01	Date Drilled:	11/81
Well Depth:	160	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pump Test:	Not Reported	Driller:	RIG WATER
Driller #:	005	Hole Depth:	165
Elevation:	Not Reported	Depth From Surface:	0.00
Measured Date:	Not Reported	Date Added by Agency:	1995-02-09
Date Registered by Agency:	Not Reported	Date Plugged:	02/82
Plugged By:	RIG WATER	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	STEEL	Screen Diameter:	4
Screen Interval:	140-160	Assoc Well Serial #:	Not Reported
Well Name:	BROUSSAR 6	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**57
NW
1/2 - 1 Mile
Higher**

LA WELLS LATD60000113127

Well ID:	099-6380Z	Local Well #:	6380Z
Well Use:	plugged and abandoned rig supply	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	TOCE OIL
Seq #:	01	Date Drilled:	11/95
Well Depth:	160	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	RIG WATER
Pump Test:	Not Reported	Hole Depth:	170
Driller #:	005	Depth From Surface:	25.00
Elevation:	22	Date Added by Agency:	1996-09-03
Measured Date:	11/14/95	Date Plugged:	05/96
Date Registered by Agency:	12/95	Yield on Pump Test:	Not Reported
Plugged By:	RIG WATER	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	218538
Screen Interval:	150-160	Pumpdown Method:	Not Reported
Well Name:	GUIDRY 1	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

D58
NNE
1/2 - 1 Mile
Higher

LA WELLS LATD60000111988

Well ID:	099-6974Z	Local Well #:	6974Z
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	DUHON, CARROLL	Well Depth:	145
Date Drilled:	09/02	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOUSAYE	Driller #:	447
Hole Depth:	150	Elevation:	20
Depth From Surface:	20.00	Measured Date:	09/06/02
Date Added by Agency:	2003-02-07	Date Registered by Agency:	09/02
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	3	Casing Material:	PLASTIC
Screen Diameter:	3	Screen Interval:	135-145
Assoc Well Serial #:	Not Reported	Well Name:	#2
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

59
NE
1/2 - 1 Mile
Higher

LA WELLS LATD60000109185

Well ID:	099-7157Z	Local Well #:	7157Z
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	KIDDER, JACKIE	Well Depth:	138
Date Drilled:	05/05	Geo Unit:	112ACFL

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOUSSAYE	Driller #:	447
Hole Depth:	140	Elevation:	20
Depth From Surface:	16.00	Measured Date:	05/10/05
Date Added by Agency:	2006-04-21	Date Registered by Agency:	05/05
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	3	Casing Material:	PLASTIC
Screen Diameter:	3	Screen Interval:	Not Reported
Assoc Well Serial #:	Not Reported	Well Name:	#1
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0		
Comments:	Well Is Used To Maintain Water Level In Pond.		
Remarks:	Not Reported		

60
ESE
1/2 - 1 Mile
Lower

LA WELLS LATD60000113181

Well ID:	099-6858Z	Local Well #:	6858Z
Well Use:	domestic	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	FREDDIE J. BREAUX JR.	Well Depth:	127
Date Drilled:	07/01	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	BUMBLE 'B'S	Driller #:	610
Hole Depth:	130	Elevation:	20
Depth From Surface:	22.00	Measured Date:	07/08/01
Date Added by Agency:	2002-06-11	Date Registered by Agency:	07/01
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	107-127
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	167082	Comments:	Not Reported
Remarks:	Not Reported		

**D61
NNE
1/2 - 1 Mile
Higher**

LA WELLS LATD60000111990

Well ID:	099-6976Z	Local Well #:	6976Z
Well Use:	plugged and abandoned domestic	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	DUHON, CARROLL
Seq #:	01	Date Drilled:	Not Reported
Well Depth:	120	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	UNKNOWN
Pump Test:	Not Reported	Hole Depth:	0
Driller #:	000	Depth From Surface:	0.00
Elevation:	20	Date Added by Agency:	2003-02-07
Measured Date:	Not Reported	Date Plugged:	09/02
Date Registered by Agency:	Not Reported	Yield on Pump Test:	Not Reported
Plugged By:	DELAHOUSAYE	Casing Diameter:	2
Drawdown on Test:	Not Reported	Screen Diameter:	Not Reported
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	Not Reported	Pumpdown Method:	Not Reported
Well Name:	#1	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

**62
NW
1/2 - 1 Mile
Higher**

LA WELLS LATD60000111066

Well ID:	099-5060Z	Local Well #:	5060Z
Well Use:	plugged and abandoned rig supply		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	01	Owner:	AMOCO PROD CO
Well Depth:	160	Date Drilled:	11/81
Geo Unit:	112ACFL	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	RIG WATER
Driller #:	005	Hole Depth:	165
Elevation:	Not Reported	Depth From Surface:	0.00
Measured Date:	Not Reported	Date Added by Agency:	1995-02-09
Date Registered by Agency:	Not Reported	Date Plugged:	01/82
Plugged By:	RIG WATER	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	STEEL	Screen Diameter:	4
Screen Interval:	140-160	Assoc Well Serial #:	Not Reported
Well Name:	BROUSSAR 5	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

E63
NNE
1/2 - 1 Mile
Higher

LA WELLS LATD60000110013

Well ID:	099-7434Z	Local Well #:	7434Z
Well Use:	domestic	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	GERALD HEBERT	Well Depth:	137
Date Drilled:	05/08	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOSSAYE	Driller #:	447
Hole Depth:	140	Elevation:	20
Depth From Surface:	19.00	Measured Date:	05/21/08
Date Added by Agency:	2008-08-12	Date Registered by Agency:	06/08
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	3	Casing Material:	PLASTIC
Screen Diameter:	3	Screen Interval:	127-137
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	167358	Comments:	Not Reported
Remarks:	Not Reported		

F64
SE
1/2 - 1 Mile
Lower

FED USGS USGS40000395208

Organization ID:	USGS-LA	Organization Name:	USGS Louisiana Water Science Center
Monitor Location:	SMn- 51	Type:	Well
Description:	Not Reported	HUC:	08080102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Coastal lowlands aquifer system		
Formation Type:	Atchafalaya Aquifer	Aquifer Type:	Not Reported
Construction Date:	19090101	Well Depth:	125
Well Depth Units:	ft	Well Hole Depth:	Not Reported
Well Hole Depth Units:	Not Reported		

Ground water levels, Number of Measurements:	65	Level reading date:	1959-04-14
Feet below surface:	5.36	Feet to sea level:	Not Reported
Note:	Not Reported		
Level reading date:	1958-09-04	Feet below surface:	5.56
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1958-04-28	Feet below surface:	2.34
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1957-09-24	Feet below surface:	9.65
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1957-04-22	Feet below surface:	6.96
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1957-04-04	Feet below surface:	7.67
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1956-09-04	Feet below surface:	11.38
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1956-04-02	Feet below surface:	6.11
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1955-08-29	Feet below surface:	9.23
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1955-03-14	Feet below surface:	7.90
Feet to sea level:	Not Reported	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1954-09-16	Feet below surface:	9.06
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1954-03-15	Feet below surface:	5.73
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1953-09-28	Feet below surface:	7.48
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1953-04-06	Feet below surface:	4.20
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1952-04-28	Feet below surface:	3.10
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1951-03-06	Feet below surface:	3.08
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1950-12-12	Feet below surface:	7.24
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1950-09-27	Feet below surface:	5.58
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1950-06-29	Feet below surface:	2.17
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1950-03-20	Feet below surface:	0.99
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1949-12-20	Feet below surface:	8.06
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1949-06-22	Feet below surface:	4.87
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1949-03-14	Feet below surface:	3.05
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1948-12-09	Feet below surface:	9.06
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1948-07-06	Feet below surface:	7.13
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1948-04-05	Feet below surface:	2.97
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1948-01-05	Feet below surface:	7.44
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-11-07	Feet below surface:	9.88
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-10-07	Feet below surface:	8.94
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-09-08	Feet below surface:	7.79
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-07-14	Feet below surface:	3.09
Feet to sea level:	Not Reported	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1947-05-13	Feet below surface:	1.96
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-03-10	Feet below surface:	4.04
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-02-03	Feet below surface:	2.88
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1947-01-06	Feet below surface:	4.67
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-11-05	Feet below surface:	7.75
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-10-08	Feet below surface:	7.10
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-09-09	Feet below surface:	2.40
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-08-05	Feet below surface:	3.57
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-07-09	Feet below surface:	1.84
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-06-11	Feet below surface:	2.05
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-05-06	Feet below surface:	2.95
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-04-15	Feet below surface:	1.86
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-03-11	Feet below surface:	1.92
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-02-12	Feet below surface:	1.69
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1946-01-08	Feet below surface:	5.25
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1945-12-11	Feet below surface:	6.27
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1945-11-25	Feet below surface:	6.78
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1945-11-07	Feet below surface:	6.26
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1945-10-08	Feet below surface:	6.94
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1945-05-05	Feet below surface:	1.04
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1945-01-09	Feet below surface:	6.82
Feet to sea level:	Not Reported	Note:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Level reading date:	1944-12-09	Feet below surface:	8.53
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-11-09	Feet below surface:	8.94
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-10-04	Feet below surface:	8.75
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-07-26	Feet below surface:	5.27
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-06-26	Feet below surface:	2.45
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-06-13	Feet below surface:	2.01
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-06-01	Feet below surface:	1.40
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-05-16	Feet below surface:	1.74
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-04-11	Feet below surface:	2.70
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-03-24	Feet below surface:	3.63
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-03-01	Feet below surface:	5.38
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-01-28	Feet below surface:	6.26
Feet to sea level:	Not Reported	Note:	Not Reported
Level reading date:	1944-01-27	Feet below surface:	6.28
Feet to sea level:	Not Reported	Note:	Not Reported

**F65
SE
1/2 - 1 Mile
Lower**

LA WELLS LATD60000184917

Well ID:	099-51	Local Well #:	51
Well Use:	industrial	Sub-use:	Other
Well Status:	Active	Seq #:	01
Owner:	PEOPLES COTTON	Well Depth:	125
Date Drilled:	1909	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	UNKNOWN	Driller #:	000
Hole Depth:	0	Elevation:	19
Depth From Surface:	3.68	Measured Date:	01/27/44
Date Added by Agency:	1994-12-09	Date Registered by Agency:	Not Reported
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	20	Drawdown on Test:	Not Reported
Casing Diameter:	2	Casing Material:	Not Reported
Screen Diameter:	Not Reported	Screen Interval:	113-125
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

E66
NNE
1/2 - 1 Mile
Higher

LA WELLS LATD60000157485

Well ID:	099-301	Local Well #:	301
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	00
Owner:	GERARD HEBERT	Well Depth:	150
Date Drilled:	06/19/10	Geo Unit:	Not Reported
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	DELAHOUSAYE WATER WELL DRILLING & REPAIR		
Driller #:	447	Hole Depth:	170
Elevation:	20	Depth From Surface:	Not Reported
Measured Date:	06/19/10	Date Added by Agency:	Not Reported
Date Registered by Agency:	07/20/10	Date Plugged:	Not Reported
Plugged By:	Not Reported	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	6
Casing Material:	PLASTIC	Screen Diameter:	6
Screen Interval:	Not Reported	Assoc Well Serial #:	Not Reported
Well Name:	3	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	PLASTIC
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	10
Screen interval Length:	20	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	P	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	140
Driller Owner:	DELAHOUSAYE, BRIAN	Owner ID:	2458
Comments:	Not Reported	Remarks:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

G67
East
1/2 - 1 Mile
Lower

LA WELLS LATD60000109291

Well ID:	099-6929Z	Local Well #:	6929Z
Well Use:	plugged and abandoned irrigation		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	02	Owner:	ACADIANA PRIDE
Well Depth:	140	Date Drilled:	Not Reported
Geo Unit:	112ACFL	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	UNKNOWN
Driller #:	000	Hole Depth:	0
Elevation:	20	Depth From Surface:	0.00
Measured Date:	Not Reported	Date Added by Agency:	2003-02-07
Date Registered by Agency:	Not Reported	Date Plugged:	05/02
Plugged By:	DELAHOUSAYE	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	Not Reported
Screen Interval:	Not Reported	Assoc Well Serial #:	Not Reported
Well Name:	#1	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

G68
East
1/2 - 1 Mile
Lower

LA WELLS LATD60000109292

Well ID:	099-6930Z	Local Well #:	6930Z
Well Use:	plugged and abandoned irrigation		
Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	03	Owner:	ACADIANA PRIDE
Well Depth:	140	Date Drilled:	Not Reported
Geo Unit:	112ACFL	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	UNKNOWN
Driller #:	000	Hole Depth:	0
Elevation:	20	Depth From Surface:	0.00
Measured Date:	Not Reported	Date Added by Agency:	2003-02-07
Date Registered by Agency:	Not Reported	Date Plugged:	05/02
Plugged By:	DELAHOUSAYE	Yield on Pump Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	Not Reported
Screen Interval:	Not Reported	Assoc Well Serial #:	Not Reported
Well Name:	#2	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

G69
East
1/2 - 1 Mile
Lower

LA WELLS LATD60000109293

Well ID:	099-6931Z	Local Well #:	6931Z
Well Use:	aquaculture	Sub-use:	Aquaculture
Well Status:	Active	Seq #:	01
Owner:	ACADIANA PRIDE	Well Depth:	138
Date Drilled:	05/02	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOUSAYE	Driller #:	447
Hole Depth:	140	Elevation:	20
Depth From Surface:	15.00	Measured Date:	05/24/02
Date Added by Agency:	2003-02-07	Date Registered by Agency:	05/02
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	118-138
Assoc Well Serial #:	Not Reported	Well Name:	3
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Remarks: Not Reported

**70
SE
1/2 - 1 Mile
Lower**

LA WELLS LATD60000178938

Well ID:	099-156	Local Well #:	156
Well Use:	aquaculture	Sub-use:	Aquaculture
Well Status:	Active	Seq #:	01
Owner:	LEBLANC, GERALD	Well Depth:	170
Date Drilled:	06/84	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	CORMIER'S	Driller #:	043
Hole Depth:	170	Elevation:	20
Depth From Surface:	10.00	Measured Date:	06/09/84
Date Added by Agency:	Not Reported	Date Registered by Agency:	06/84
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	160-170
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

**H71
SW
1/2 - 1 Mile
Higher**

LA WELLS LATD60000113594

Well ID:	099-6760Z	Local Well #:	6760Z
Well Use:	plugged and abandoned irrigation	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	NOWELL, MIKE
Seq #:	02	Date Drilled:	Not Reported
Well Depth:	130	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	UNKNOWN
Pump Test:	Not Reported	Hole Depth:	0
Driller #:	000	Depth From Surface:	0.00
Elevation:	20	Date Added by Agency:	2001-08-22
Measured Date:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Date Registered by Agency:	Not Reported	Date Plugged:	06/00
Plugged By:	DELAHOUSSAYE	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	2
Casing Material:	METAL	Screen Diameter:	Not Reported
Screen Interval:	Not Reported	Assoc Well Serial #:	Not Reported
Well Name:	1	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**H72
SW
1/2 - 1 Mile
Higher**

LA WELLS LATD60000113595

Well ID:	099-6761Z	Local Well #:	6761Z
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	NOWELL, MIKE	Well Depth:	160
Date Drilled:	06/00	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOUSSAYE	Driller #:	447
Hole Depth:	161	Elevation:	20
Depth From Surface:	22.00	Measured Date:	06/14/00
Date Added by Agency:	2001-08-22	Date Registered by Agency:	06/00
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	2	Casing Material:	PLASTIC
Screen Diameter:	2	Screen Interval:	150-160
Assoc Well Serial #:	Not Reported	Well Name:	2
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

73
West
1/2 - 1 Mile
Higher

LA WELLS LATD60000110871

Well ID:	099-5155Z	Local Well #:	5155Z
Well Use:	plugged and abandoned rig supply	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	AMOCO PROD CO
Seq #:	01	Date Drilled:	11/84
Well Depth:	160	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	BROWN, H.
Pump Test:	Not Reported	Hole Depth:	160
Driller #:	034	Depth From Surface:	30.00
Elevation:	Not Reported	Date Added by Agency:	1995-02-09
Measured Date:	11/17/84	Date Plugged:	02/85
Date Registered by Agency:	Not Reported	Yield on Pump Test:	80
Plugged By:	BROWN, H.	Casing Diameter:	4
Drawdown on Test:	Not Reported	Screen Diameter:	4
Casing Material:	PLASTIC	Assoc Well Serial #:	Not Reported
Screen Interval:	140-160	Pumpdown Method:	Not Reported
Well Name:	POINDEXT 1	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported	Pump Test Done:	Not Reported
Water Level Post-Test:	Not Reported	P and A Comments:	Not Reported
Cementing Method:	Not Reported	Casing Length:	Not Reported
P and A Details:	Not Reported	Owner ID:	0
Driller Owner:	Not Reported	Remarks:	Not Reported
Comments:	Not Reported		

174
NE
1/2 - 1 Mile
Higher

LA WELLS LATD60000110285

Well ID:	099-6321Z	Local Well #:	6321Z
Well Use:	plugged and abandoned domestic	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	GUIDRY, JERRY
Seq #:	01	Date Drilled:	Not Reported
Well Depth:	170	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	UNKNOWN
Pump Test:	Not Reported	Hole Depth:	0
Driller #:	000		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Elevation:	20	Depth From Surface:	0.00
Measured Date:	Not Reported	Date Added by Agency:	2001-03-21
Date Registered by Agency:	Not Reported	Date Plugged:	05/95
Plugged By:	DELAHOUSAYE	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	2
Casing Material:	METAL	Screen Diameter:	Not Reported
Screen Interval:	Not Reported	Assoc Well Serial #:	Not Reported
Well Name:	Not Reported	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**I75
NE
1/2 - 1 Mile
Higher**

LA WELLS LATD60000109172

Well ID:	099-6331Z	Local Well #:	6331Z
Well Use:	plugged and abandoned domestic	Well Status:	Plugged and Abandoned
Sub-use:	Plugged	Owner:	GUIDRY, JERRY
Seq #:	02	Date Drilled:	Not Reported
Well Depth:	170	Mechanic Test:	Not Reported
Geo Unit:	112ACFL	Bio Analysis:	Not Reported
Chemical Analysis:	Not Reported	Driller:	UNKNOWN
Pump Test:	Not Reported	Hole Depth:	0
Driller #:	000	Depth From Surface:	0.00
Elevation:	20	Date Added by Agency:	2001-03-21
Measured Date:	Not Reported	Date Plugged:	05/95
Date Registered by Agency:	Not Reported	Yield on Pump Test:	Not Reported
Plugged By:	DELAHOUSAYE	Casing Diameter:	4X2
Drawdown on Test:	Not Reported	Screen Diameter:	2
Casing Material:	METAL	Assoc Well Serial #:	Not Reported
Screen Interval:	Not Reported	Pumpdown Method:	Not Reported
Well Name:	Not Reported	Top of Extension Pipe:	Not Reported
Extension Pipe Length:	Not Reported	Screen Material Type:	Not Reported
Bottom of Extension Pipe:	Not Reported	Ground Elevation:	Not Reported
Gravel Packed:	N	Avg Heat Pump Depth:	0
Screen Diameter:	Not Reported	Annular Space Cemented Depth:	Not Reported
Heat Pump Hole #:	Not Reported	Screen Slot Size:	Not Reported
Screen interval Length:	Not Reported	Pump Depth:	Not Reported
Inspection Comments:	Not Reported	Planned Pumpage (GPM):	0
Pump Horse Power:	Not Reported	Planned Pumpage (days/yr):	Not Reported
Planned Pumpage (hr/day):	0	Measured Method:	Not Reported
Pump Rate (Gal/day):	Not Reported	Pump Test Date:	0
Hrs of Test:	Not Reported	Static Measurement Method:	Not Reported
Static Water Level:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

J76
ESE
1/2 - 1 Mile
Lower

FED USGS USGS40000395272

Organization ID:	USGS-LA	Organization Name:	USGS Louisiana Water Science Center
Monitor Location:	SMn- 80	Type:	Well
Description:	Not Reported	HUC:	08080102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Coastal lowlands aquifer system	Aquifer Type:	Not Reported
Formation Type:	Atchafalaya Aquifer	Well Depth:	120
Construction Date:	19920901	Well Hole Depth:	120
Well Depth Units:	ft		
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	1	Level reading date:	1992-09-01
Feet below surface:	16.	Feet to sea level:	Not Reported
Note:	Not Reported		

I77
NE
1/2 - 1 Mile
Higher

LA WELLS LATD60000110286

Well ID:	099-6322Z	Local Well #:	6322Z
Well Use:	commercial public supply	Sub-use:	Commercial
Well Status:	Active	Seq #:	01
Owner:	CRAWFISHTOWN	Well Depth:	180
Date Drilled:	04/95	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOUSAYE	Driller #:	447
Hole Depth:	181	Elevation:	20
Depth From Surface:	17.00	Measured Date:	04/22/95
Date Added by Agency:	2001-03-21	Date Registered by Agency:	05/95
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	170-180
Assoc Well Serial #:	Not Reported	Well Name:	1
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Jerry Guidry, Owner
Remarks:	Not Reported		

J78
ESE
1/2 - 1 Mile
Lower

LA WELLS LATD60000113586

Well ID: 099-80 Well Use: industrial Well Status: Active Owner: GUIDRY CATFISH Date Drilled: 09/92 Mechanic Test: Not Reported Bio Analysis: Not Reported Driller: HUVAL, BRIAN Hole Depth: 120 Depth From Surface: 16.00 Date Added by Agency: 1993-11-04 Date Plugged: Not Reported Yield on Pump Test: Not Reported Casing Diameter: 4 Screen Diameter: 4 Assoc Well Serial #: Not Reported Pumpdown Method: Not Reported Top of Extension Pipe: Not Reported Screen Material Type: Not Reported Ground Elevation: Not Reported Avg Heat Pump Depth: 0 Annular Space Cemented Depth: Not Reported Screen Slot Size: Not Reported Pump Depth: Not Reported Planned Pumpage (GPM): 0 Planned Pumpage (days/yr): Not Reported Measured Method: Not Reported Pump Test Date: 0 Static Measurement Method: Not Reported Pump Test Done: Not Reported P and A Comments: Not Reported Casing Length: Not Reported Owner ID: 0 Remarks: Not Reported	Local Well #: 80 Sub-use: Other Seq #: 01 Well Depth: 120 Geo Unit: 112ACFL Chemical Analysis: Not Reported Pump Test: Not Reported Driller #: 426 Elevation: 18 Measured Date: 09/01/92 Date Registered by Agency: 09/92 Plugged By: Not Reported Drawdown on Test: Not Reported Casing Material: PLASTIC Screen Interval: 105-120 Well Name: Not Reported Extension Pipe Length: Not Reported Bottom of Extension Pipe: Not Reported Gravel Packed: N Screen Diameter: Not Reported Heat Pump Hole #: Not Reported Screen interval Length: Not Reported Inspection Comments: Not Reported Pump Horse Power: Not Reported Planned Pumpage (hr/day): 0 Pump Rate (Gal/day): Not Reported Hrs of Test: Not Reported Static Water Level: Not Reported Water Level Post-Test: Not Reported Cementing Method: Not Reported P and A Details: Not Reported Driller Owner: Not Reported Comments: Not Reported
--	---

K79
NE
1/2 - 1 Mile
Higher

LA WELLS LATD60000109681

Well ID: 099-157 Well Use: irrigation Well Status: Active Owner: HEBERT, PERCY Date Drilled: 06/84	Local Well #: 157 Sub-use: Not Reported Seq #: 01 Well Depth: 180 Geo Unit: 112ACFL
--	---

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	H2O	Driller #:	236
Hole Depth:	180	Elevation:	20
Depth From Surface:	0.00	Measured Date:	Not Reported
Date Added by Agency:	1987-07-24	Date Registered by Agency:	07/84
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	160-180
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0	Comments:	Not Reported
Remarks:	Not Reported		

K80
NE
1/2 - 1 Mile
Higher

FED USGS USGS40000395639

Organization ID:	USGS-LA	Organization Name:	USGS Louisiana Water Science Center
Monitor Location:	SMn- 157	Type:	Well
Description:	Not Reported	HUC:	08080102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Coastal lowlands aquifer system		
Formation Type:	Atchafalaya Aquifer	Aquifer Type:	Not Reported
Construction Date:	19840627	Well Depth:	180
Well Depth Units:	ft	Well Hole Depth:	180
Well Hole Depth Units:	ft		

81
South
1/2 - 1 Mile
Lower

LA WELLS LATD60000186511

Well ID:	099-7717Z	Local Well #:	7717Z
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	00
Owner:	NATHAN LIEBERT	Well Depth:	150
Date Drilled:	10/06/2013	Geo Unit:	112ACFL
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Driller:	BRIAN HUVAL WATER WELL DRILLING		
Driller #:	426	Hole Depth:	150
Elevation:	0020	Depth From Surface:	19
Measured Date:	10/06/2013	Date Added by Agency:	Not Reported
Date Registered by Agency:	10/13/2013	Date Plugged:	Not Reported
Plugged By:	Not Reported	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	3
Casing Material:	PLASTIC	Screen Diameter:	3
Screen Interval:	140-150	Assoc Well Serial #:	Not Reported
Well Name:	Not Reported	Pumpdown Method:	O
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	PLASTIC
Gravel Packed:	N	Ground Elevation:	16
Screen Diameter:	5.5	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	10
Screen interval Length:	10	Screen Slot Size:	.014
Inspection Comments:	02-DEC-13	Pump Depth:	50
Pump Horse Power:	.75	Planned Pumpage (GPM):	20
Planned Pumpage (hr/day):	2	Planned Pumpage (days/yr):	15
Pump Rate (Gal/day):	1800	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	TAPE MEASURE
Water Level Post-Test:	B	Pump Test Done:	Not Reported
Cementing Method:	P	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	140
Driller Owner:	Not Reported	Owner ID:	56067
Comments:	Not Reported	Remarks:	Not Reported

**J82
ESE
1/2 - 1 Mile
Lower**

LA WELLS LATD60000176542

Well ID:	099-7641Z	Local Well #:	7641Z
Well Use:	industrial food process	Sub-use:	Food and Kindred Products
Well Status:	Active	Seq #:	02
Owner:	PROCESSOR INC	Well Depth:	155
Date Drilled:	04/26/2012	Geo Unit:	112ACFL
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	DELAHOUSSEY WATER WELL DRILLING & REPAIR		
Driller #:	447	Hole Depth:	160
Elevation:	0015	Depth From Surface:	19
Measured Date:	4-26-12	Date Added by Agency:	Not Reported
Date Registered by Agency:	5-23-12	Date Plugged:	Not Reported
Plugged By:	Not Reported	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	135-155	Assoc Well Serial #:	Not Reported
Well Name:	2	Pumpdown Method:	O
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	PLASTIC
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	8.5	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	135
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	30-JUL-12	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	TAPE MEASURE
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	P	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	135
Driller Owner:	Not Reported	Owner ID:	32756
Comments:	Not Reported		
Remarks:	Well #1 - Pulled Pump 21' Got Stuck Past Means Of Retrieving. Well #2 Was Drilled To Keep Plant Working.		

83
ENE
1/2 - 1 Mile
Higher

LA WELLS LATD60000181265

Well ID:	099-7187Z	Local Well #:	7187Z
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	CAJUN PALMS RV	Well Depth:	170
Date Drilled:	07/05	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	HUVAL, BRIAN	Driller #:	426
Hole Depth:	170	Elevation:	20
Depth From Surface:	17.00	Measured Date:	07/27/05
Date Added by Agency:	2006-04-21	Date Registered by Agency:	08/05
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	4	Casing Material:	PLASTIC
Screen Diameter:	4	Screen Interval:	150-170
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	0		
Comments:	Water Used To Maintain Level In Small Fish Pond.		
Remarks:	Not Reported		

84
West
1/2 - 1 Mile
Higher

LA WELLS LATD60000110287

Well ID:	099-6327Z	Local Well #:	6327Z
Well Use:	plugged and abandoned rig supply		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Sub-use:	Plugged	Well Status:	Plugged and Abandoned
Seq #:	01	Owner:	JANEX OIL
Well Depth:	160	Date Drilled:	05/95
Geo Unit:	112ACFL	Mechanic Test:	Not Reported
Chemical Analysis:	Not Reported	Bio Analysis:	Not Reported
Pump Test:	Not Reported	Driller:	RIG WATER
Driller #:	005	Hole Depth:	170
Elevation:	Not Reported	Depth From Surface:	30.00
Measured Date:	05/24/95	Date Added by Agency:	1995-08-09
Date Registered by Agency:	06/95	Date Plugged:	07/95
Plugged By:	RIG WATER	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	4
Casing Material:	PLASTIC	Screen Diameter:	4
Screen Interval:	150-160	Assoc Well Serial #:	217899
Well Name:	POINDEXT 2	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	Not Reported
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	Not Reported
Screen interval Length:	Not Reported	Screen Slot Size:	Not Reported
Inspection Comments:	Not Reported	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	Not Reported	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	Not Reported
Driller Owner:	Not Reported	Owner ID:	0
Comments:	Not Reported	Remarks:	Not Reported

**85
SE
1/2 - 1 Mile
Lower**

FED USGS USGS40000395149

Organization ID:	USGS-LA	Organization Name:	USGS Louisiana Water Science Center
Monitor Location:	SMn- 156	Type:	Well
Description:	Not Reported	HUC:	08080102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Coastal lowlands aquifer system	Aquifer Type:	Not Reported
Formation Type:	Atchafalaya Aquifer	Well Depth:	170
Construction Date:	19840609	Well Hole Depth:	170
Well Depth Units:	ft		
Well Hole Depth Units:	ft		

Ground water levels,Number of Measurements:	1	Level reading date:	1984-06-09
Feet below surface:	10	Feet to sea level:	Not Reported
Note:	Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance
Elevation

Database EDR ID Number

86
NE
1/2 - 1 Mile
Higher

LA WELLS LATD60000109425

Well ID:	099-7408Z	Local Well #:	7408Z
Well Use:	domestic	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	GRADY PETRY	Well Depth:	138
Date Drilled:	12/07	Geo Unit:	00000000
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	DELAHOUSAYE	Driller #:	447
Hole Depth:	140	Elevation:	20
Depth From Surface:	22.00	Measured Date:	12/14/07
Date Added by Agency:	2008-02-07	Date Registered by Agency:	12/07
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	2	Casing Material:	PLASTIC
Screen Diameter:	2	Screen Interval:	128-138
Assoc Well Serial #:	Not Reported	Well Name:	1
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	167340	Comments:	Not Reported
Remarks:	Not Reported		

L87
SW
1/2 - 1 Mile
Higher

LA WELLS LATD60000212076

Well ID:	099-5450Z	Local Well #:	5450Z
Well Use:	domestic	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	CHESTER BEGNAUD	Well Depth:	130
Date Drilled:	04/87	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	CORMIER'S	Driller #:	043
Hole Depth:	130	Elevation:	20
Depth From Surface:	15.00	Measured Date:	04/13/87
Date Added by Agency:	1991-07-03	Date Registered by Agency:	05/87
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Casing Diameter:	2	Casing Material:	PLASTIC
Screen Diameter:	2	Screen Interval:	124-130
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported
P and A Comments:	Not Reported	P and A Details:	Not Reported
Casing Length:	Not Reported	Driller Owner:	Not Reported
Owner ID:	165942	Comments:	Not Reported
Remarks:	Not Reported		

88
East
1/2 - 1 Mile
Lower

LA WELLS LATD60000191994

Well ID:	099-7812Z	Local Well #:	7812Z
Well Use:	domestic	Sub-use:	Not Reported
Well Status:	Active	Seq #:	00
Owner:	HARRY SHARP	Well Depth:	140
Date Drilled:	01/22/2015	Geo Unit:	112ACFL
Mechanic Test:	N	Chemical Analysis:	N
Bio Analysis:	N	Pump Test:	N
Driller:	BRIAN HUVAL WATER WELL DRILLING		
Driller #:	426	Hole Depth:	140
Elevation:	0020	Depth From Surface:	15
Measured Date:	01/22/2015	Date Added by Agency:	Not Reported
Date Registered by Agency:	02/09/2015	Date Plugged:	Not Reported
Plugged By:	Not Reported	Yield on Pump Test:	Not Reported
Drawdown on Test:	Not Reported	Casing Diameter:	2
Casing Material:	PLASTIC	Screen Diameter:	2
Screen Interval:	Not Reported	Assoc Well Serial #:	Not Reported
Well Name:	Not Reported	Pumpdown Method:	Not Reported
Extension Pipe Length:	Not Reported	Top of Extension Pipe:	Not Reported
Bottom of Extension Pipe:	Not Reported	Screen Material Type:	PLASTIC
Gravel Packed:	N	Ground Elevation:	Not Reported
Screen Diameter:	Not Reported	Avg Heat Pump Depth:	0
Heat Pump Hole #:	Not Reported	Annular Space Cemented Depth:	10
Screen interval Length:	5	Screen Slot Size:	.014
Inspection Comments:	16-MAR-15	Pump Depth:	Not Reported
Pump Horse Power:	Not Reported	Planned Pumpage (GPM):	0
Planned Pumpage (hr/day):	0	Planned Pumpage (days/yr):	Not Reported
Pump Rate (Gal/day):	Not Reported	Measured Method:	Not Reported
Hrs of Test:	Not Reported	Pump Test Date:	0
Static Water Level:	Not Reported	Static Measurement Method:	Not Reported
Water Level Post-Test:	Not Reported	Pump Test Done:	Not Reported
Cementing Method:	G	P and A Comments:	Not Reported
P and A Details:	Not Reported	Casing Length:	135
Driller Owner:	Not Reported	Owner ID:	87868

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Comments: Not Reported
Remarks: Wwc 618 Subcontractor Matthieu Water Well Drilling, Inc

L89
SW
1/2 - 1 Mile
Higher

FED USGS USGS40000395143

Organization ID:	USGS-LA	Organization Name:	USGS Louisiana Water Science Center
Monitor Location:	SMn- 249	Type:	Well
Description:	Not Reported	HUC:	08080102
Drainage Area:	Not Reported	Drainage Area Units:	Not Reported
Contrib Drainage Area:	Not Reported	Contrib Drainage Area Unts:	Not Reported
Aquifer:	Coastal lowlands aquifer system	Aquifer Type:	Not Reported
Formation Type:	Atchafalaya Aquifer	Well Depth:	150
Construction Date:	19910813	Well Hole Depth:	150
Well Depth Units:	ft		
Well Hole Depth Units:	ft		
Ground water levels,Number of Measurements:	1	Level reading date:	1991-08-13
Feet below surface:	20.	Feet to sea level:	Not Reported
Note:	Not Reported		

L90
SW
1/2 - 1 Mile
Higher

LA WELLS LATD60000113906

Well ID:	099-249	Local Well #:	249
Well Use:	irrigation	Sub-use:	Not Reported
Well Status:	Active	Seq #:	01
Owner:	BEGNAUD, CHESTR	Well Depth:	150
Date Drilled:	08/91	Geo Unit:	112ACFL
Mechanic Test:	Not Reported	Chemical Analysis:	Not Reported
Bio Analysis:	Not Reported	Pump Test:	Not Reported
Driller:	PELLERIN'S	Driller #:	334
Hole Depth:	150	Elevation:	20
Depth From Surface:	20.00	Measured Date:	08/13/91
Date Added by Agency:	1994-12-09	Date Registered by Agency:	09/91
Date Plugged:	Not Reported	Plugged By:	Not Reported
Yield on Pump Test:	Not Reported	Drawdown on Test:	Not Reported
Casing Diameter:	Not Reported	Casing Material:	PLASTIC
Screen Diameter:	Not Reported	Screen Interval:	144-150
Assoc Well Serial #:	Not Reported	Well Name:	Not Reported
Pumpdown Method:	Not Reported	Extension Pipe Length:	Not Reported
Top of Extension Pipe:	Not Reported	Bottom of Extension Pipe:	Not Reported
Screen Material Type:	Not Reported	Gravel Packed:	N
Ground Elevation:	Not Reported	Screen Diameter:	Not Reported
Avg Heat Pump Depth:	0	Heat Pump Hole #:	Not Reported
Annular Space Cemented Depth:	Not Reported	Screen interval Length:	Not Reported
Screen Slot Size:	Not Reported	Inspection Comments:	Not Reported
Pump Depth:	Not Reported	Pump Horse Power:	Not Reported
Planned Pumpage (GPM):	0	Planned Pumpage (hr/day):	0
Planned Pumpage (days/yr):	Not Reported	Pump Rate (Gal/day):	Not Reported
Measured Method:	Not Reported	Hrs of Test:	Not Reported
Pump Test Date:	0	Static Water Level:	Not Reported
Static Measurement Method:	Not Reported	Water Level Post-Test:	Not Reported
Pump Test Done:	Not Reported	Cementing Method:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

P and A Comments:

Not Reported

Casing Length:

Not Reported

Owner ID:

0

Remarks:

Not Reported

P and A Details:

Not Reported

Driller Owner:

Not Reported

Comments:

Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

1
ENE
0 - 1/8 Mile

OIL_GAS LAOG13000035313

OIL_GAS:

Well Serial #:	106507	Well Name:	MT SU G; BERARD
Well #:	001	Well Status:	PLUGGED AND ABANDONED
Well Class:	Not Reported	Operator ID:	1730
Product:	Oil	Effective Date:	01-JAN-91
API #:	17099015800000	Operation Type:	01
Permit Date:	01-DEC-64	Spud Date:	07-DEC-64
Completion Date:	14-JAN-65	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12227	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	W. L. ESTIS
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=106507		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=106507		

2
WNW
1/4 - 1/2 Mile

OIL_GAS LAOG13000165595

OIL_GAS:

Well Serial #:	201632	Well Name:	MT SUF;S J BAPTISTE
Well #:	002-ALT	Well Status:	DRY AND PLUGGED
Well Class:	Not Reported	Operator ID:	0188
Product:	None	Effective Date:	01-DEC-85
API #:	17099211950000	Operation Type:	01
Permit Date:	24-SEP-85	Spud Date:	30-OCT-85
Completion Date:	Not Reported	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	11750	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=201632		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=201632		

3
North
1/4 - 1/2 Mile

OIL_GAS LAOG13000026663

OIL_GAS:

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well Serial #:	71943	Well Name:	MT RA SUF;BAPTISTE
Well #:	001	Well Status:	PLUGGED AND ABANDONED
Well Class:	Not Reported	Operator ID:	J008
Product:	Oil	Effective Date:	01-AUG-95
API #:	17099000500000	Operation Type:	01
Permit Date:	09-SEP-58	Spud Date:	30-SEP-58
Completion Date:	01-JAN-59	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12300	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	JANEX OIL CO., INC.
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=71943		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=71943		

4

East
1/4 - 1/2 Mile

OIL_GAS LAOG13000131977

OIL_GAS:

Well Serial #:	112223	Well Name:	MELANCON
Well #:	001	Well Status:	DRY AND PLUGGED
Well Class:	Not Reported	Operator ID:	1569
Product:	None	Effective Date:	01-DEC-76
API #:	17099016590000	Operation Type:	01
Permit Date:	26-OCT-65	Spud Date:	27-OCT-65
Completion Date:	15-NOV-65	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	11800	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	DAVIS OIL COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=112223		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=112223		

A5

WNW
1/4 - 1/2 Mile

OIL_GAS LAOG13000118473

OIL_GAS:

Well Serial #:	68701	Well Name:	BROUSSARD-BERGERON
Well #:	001	Well Status:	REVERTED TO SINGLE COMPLETION
Well Class:	Not Reported	Operator ID:	6142
Product:	None	Effective Date:	01-NOV-01
API #:	17099000510000	Operation Type:	01
Permit Date:	27-NOV-57	Spud Date:	14-JAN-58
Completion Date:	16-MAR-58	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12200	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=68701		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=68701		

A6
WNW
1/4 - 1/2 Mile

OIL_GAS **LAOG13000212503**

OIL_GAS:

Well Serial #:	70121	Well Name:	U MT B RA SUB; BROUSSARD-BERGER
Well #:	001D	Well Status:	SHUT-IN PRODUCTIVE -FUTURE UTILITY
Well Class:	Not Reported	Operator ID:	6142
Product:	Oil	Effective Date:	03-JUL-15
API #:	17099000510000	Operation Type:	01
Permit Date:	11-APR-58	Spud Date:	14-JAN-58
Completion Date:	16-MAR-58	Recompletion Date:	26-APR-94
Last Tested:	03-JUL-15	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12200	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	12	Scout Report:	17-JUN-94
Scout Measured Depth:	12200	Scout True Depth:	0
LUW Name:	U MT B RA SUB;	LUW Type:	2
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=70121		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=70121		

7
ENE
1/4 - 1/2 Mile

OIL_GAS **LAOG13000029868**

OIL_GAS:

Well Serial #:	87174	Well Name:	DUPUIS HEIRS
Well #:	001	Well Status:	DRY AND PLUGGED
Well Class:	Not Reported	Operator ID:	9999
Product:	None	Effective Date:	01-DEC-76
API #:	17099000530000	Operation Type:	01
Permit Date:	18-OCT-61	Spud Date:	22-OCT-61
Completion Date:	15-NOV-61	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12219	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	INACTIVE OPERATOR
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=87174		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Comments: Not Reported
URL: http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=87174

B9
WNW
1/2 - 1 Mile

OIL_GAS **LAOG13000143685**

OIL_GAS:

Well Serial #:	113931	Well Name:	CH 2 SUA;ED BERGERON B
Well #:	001D	Well Status:	PLUGGED AND ABANDONED
Well Class:	Not Reported	Operator ID:	0188
Product:	Gas	Effective Date:	01-MAY-79
API #:	17099016640000	Operation Type:	01
Permit Date:	18-FEB-66	Spud Date:	23-DEC-65
Completion Date:	28-MAR-66	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	11800	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=113931		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=113931		

B8
WNW
1/2 - 1 Mile

OIL_GAS **LAOG13000138723**

OIL_GAS:

Well Serial #:	112861	Well Name:	U MT B SU B; ED BERGERON B
Well #:	001	Well Status:	PLUGGED AND ABANDONED
Well Class:	Not Reported	Operator ID:	0188
Product:	Oil	Effective Date:	01-FEB-73
API #:	17099016640000	Operation Type:	01
Permit Date:	02-DEC-65	Spud Date:	23-DEC-65
Completion Date:	08-FEB-66	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	11800	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=112861		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=112861		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

10
WSW
1/2 - 1 Mile

OIL_GAS LAOG13000213370

OIL_GAS:

Well Serial #:	971869	Well Name:	CECELIA SWD
Well #:	004	Well Status:	Not Reported
Well Class:	Not Reported	Operator ID:	0188
Product:	None	Effective Date:	01-JUN-88
API #:	17099880540000	Operation Type:	01
Permit Date:	17-NOV-87	Spud Date:	Not Reported
Completion Date:	Not Reported	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	0	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=971869		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=971869		

11
West
1/2 - 1 Mile

OIL_GAS LAOG13000233535

OIL_GAS:

Well Serial #:	178656	Well Name:	MT RA SUD;J E BROUSSARD
Well #:	006	Well Status:	SHUT-IN PRODUCTIVE -FUTURE UTILITY
Well Class:	Not Reported	Operator ID:	6142
Product:	Oil	Effective Date:	31-MAR-12
API #:	17099209440000	Operation Type:	01
Permit Date:	19-NOV-81	Spud Date:	01-DEC-81
Completion Date:	01-FEB-82	Recompletion Date:	29-NOV-99
Last Tested:	31-MAR-12	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12100	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	12	Scout Report:	09-DEC-99
Scout Measured Depth:	11595	Scout True Depth:	0
LUW Name:	MT RA SUD;	LUW Type:	2
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=178656		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=178656		

12
NW
1/2 - 1 Mile

OIL_GAS LAOG13000216329

OIL_GAS:

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well Serial #:	218538	Well Name:	CB H 1 RB SUA;E P GUIDRY ETAL
Well #:	001	Well Status:	PLUGGED AND ABANDONED
Well Class:	Not Reported	Operator ID:	6142
Product:	Oil	Effective Date:	11-JUN-19
API #:	17099214620000	Operation Type:	01
Permit Date:	14-NOV-95	Spud Date:	17-NOV-95
Completion Date:	14-DEC-95	Recompletion Date:	14-DEC-95
Last Tested:	04-JUL-15	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	10656	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	10	Scout Report:	12-JAN-96
Scout Measured Depth:	10656	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=218538		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=218538		

C13
West
1/2 - 1 Mile

OIL_GAS **LAOG13000021888**

OIL_GAS:

Well Serial #:	61403	Well Name:	BROUSSARD-MASON
Well #:	001	Well Status:	REVERTED TO SINGLE COMPLETION
Well Class:	Not Reported	Operator ID:	6142
Product:	None	Effective Date:	01-NOV-01
API #:	17099000520000	Operation Type:	01
Permit Date:	09-MAY-56	Spud Date:	29-MAY-56
Completion Date:	18-OCT-56	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	14682	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=61403		
Comments:	Usdw 950 Notes: Usdw 950 Notes:		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=61403		

C14
West
1/2 - 1 Mile

OIL_GAS **LAOG13000117683**

OIL_GAS:

Well Serial #:	70482	Well Name:	MT RA SUD;BROUSSARD-MASON
Well #:	1-D-ALT	Well Status:	SHUT-IN PRODUCTIVE -FUTURE UTILITY
Well Class:	Not Reported	Operator ID:	6142
Product:	Oil	Effective Date:	31-AUG-22
API #:	17099000520000	Operation Type:	01
Permit Date:	19-MAY-58	Spud Date:	29-MAY-56
Completion Date:	16-MAY-58	Recompletion Date:	26-OCT-00
Last Tested:	31-AUG-22	Ever Orphaned:	Not Reported

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	11600	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	12	Scout Report:	15-NOV-00
Scout Measured Depth:	11600	Scout True Depth:	0
LUW Name:	MT RA SUD;	LUW Type:	2
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=70482		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=70482		

15
WSW
1/2 - 1 Mile

OIL_GAS **LAOG13000136056**

OIL_GAS:

Well Serial #:	63674	Well Name:	FRANK WYATT UNIT
Well #:	001	Well Status:	DRY AND PLUGGED
Well Class:	Not Reported	Operator ID:	9999
Product:	None	Effective Date:	01-DEC-76
API #:	17099000600000	Operation Type:	01
Permit Date:	29-OCT-56	Spud Date:	30-OCT-56
Completion Date:	06-JAN-57	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	13357	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	INACTIVE OPERATOR
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=63674		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=63674		

C16
West
1/2 - 1 Mile

OIL_GAS **LAOG13000182288**

OIL_GAS:

Well Serial #:	970795	Well Name:	CECELIA SWD
Well #:	001	Well Status:	DRY AND PLUGGED
Well Class:	5	Operator ID:	0188
Product:	None	Effective Date:	01-MAY-87
API #:	17099880200000	Operation Type:	01
Permit Date:	23-MAY-63	Spud Date:	24-MAY-63
Completion Date:	06-MAY-63	Recompletion Date:	05-FEB-87
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	II	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	2450	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=970795		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Comments: Not Reported
URL: http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=970795

C17
West
1/2 - 1 Mile

OIL_GAS **LAOG13000228598**

OIL_GAS:

Well Serial #:	970363	Well Name:	CECELIA SWD
Well #:	002	Well Status:	DRY AND PLUGGED
Well Class:	5	Operator ID:	6027
Product:	None	Effective Date:	14-JUN-00
API #:	17099880030000	Operation Type:	01
Permit Date:	15-JUL-75	Spud Date:	18-AUG-75
Completion Date:	28-AUG-75	Recompletion Date:	17-OCT-88
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	II	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	2560	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	TOCE OIL COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=970363		
Comments:	Max Sip 160 Revised Notes: Jan94		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=970363		

18
NW
1/2 - 1 Mile

OIL_GAS **LAOG13000184160**

OIL_GAS:

Well Serial #:	178002	Well Name:	J E BROUSSARD
Well #:	005	Well Status:	DRY AND PLUGGED
Well Class:	Not Reported	Operator ID:	0188
Product:	None	Effective Date:	01-JAN-82
API #:	17099209290000	Operation Type:	01
Permit Date:	13-OCT-81	Spud Date:	26-NOV-81
Completion Date:	21-JAN-82	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	10850	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=178002		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=178002		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
Direction
Distance

Database EDR ID Number

D20
West
1/2 - 1 Mile

OIL_GAS LAOG13000139137

OIL_GAS:

Well Serial #:	116623	Well Name:	CECELIA SWD
Well #:	003	Well Status:	Not Reported
Well Class:	5	Operator ID:	6142
Product:	None	Effective Date:	01-NOV-01
API #:	17099200100000	Operation Type:	01
Permit Date:	24-AUG-66	Spud Date:	23-AUG-66
Completion Date:	16-OCT-66	Recompletion Date:	10-OCT-86
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	II	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12177	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=116623		
Comments:	Uic-32 Grandfather Status Lost		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=116623		

D19
West
1/2 - 1 Mile

OIL_GAS LAOG13000038102

OIL_GAS:

Well Serial #:	117804	Well Name:	J E BROUSSARD
Well #:	004D	Well Status:	REVERTED TO SINGLE COMPLETION
Well Class:	Not Reported	Operator ID:	6142
Product:	None	Effective Date:	01-NOV-01
API #:	17099200100000	Operation Type:	01
Permit Date:	22-NOV-66	Spud Date:	23-AUG-66
Completion Date:	29-SEP-66	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12160	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=117804		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=117804		

21
WNW
1/2 - 1 Mile

OIL_GAS LAOG13000144124

OIL_GAS:

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Well Serial #:	114527	Well Name:	ELISE BERGERON
Well #:	001		
Well Status:	UNABLE TO LOCATE WELL-NO PLUGGED AND ABANDONED		
Well Class:	Not Reported	Operator ID:	M067
Product:	Gas	Effective Date:	01-OCT-93
API #:	17099016650000	Operation Type:	01
Permit Date:	05-APR-66	Spud Date:	06-APR-66
Completion Date:	04-MAY-66	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	11600	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	MW PETROLEUM CORPORATION
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	ELISE BERGERON	LUW Type:	3
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=114527		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=114527		

22
West
1/2 - 1 Mile

OIL_GAS **LAOG13000172201**

OIL_GAS:

Well Serial #:	196351	Well Name:	MT RA SUC;POINDEXTER
Well #:	001	Well Status:	ACTIVE - PRODUCING
Well Class:	Not Reported	Operator ID:	6142
Product:	Oil	Effective Date:	01-NOV-01
API #:	17099211360000	Operation Type:	01
Permit Date:	13-NOV-84	Spud Date:	24-NOV-84
Completion Date:	Not Reported	Recompletion Date:	19-MAR-85
Last Tested:	30-SEP-22	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12230	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	Not Reported	Scout Report:	Not Reported
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	MT RA SUC;	LUW Type:	2
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=196351		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=196351		

E23
West
1/2 - 1 Mile

OIL_GAS **LAOG13000216331**

OIL_GAS:

Well Serial #:	217899	Well Name:	UMT B RA SUA;POINDEXTER
Well #:	002	Well Status:	SHUT-IN PRODUCTIVE -FUTURE UTILITY
Well Class:	Not Reported	Operator ID:	6142
Product:	Oil	Effective Date:	01-MAY-17
API #:	17099214520000	Operation Type:	01
Permit Date:	11-MAY-95	Spud Date:	26-MAY-95
Completion Date:	26-JUL-95	Recompletion Date:	21-APR-97

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Last Tested:	31-MAR-22	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12100	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	J. P. VAN WAY
Scout Well:	12	Scout Report:	02-MAY-97
Scout Measured Depth:	12115	Scout True Depth:	0
LUW Name:	UMT B RA SUA;POINDEXTER	LUW Type:	2
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=217899		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=217899		

E24
West
1/2 - 1 Mile

OIL_GAS **LAOG13000071156**

OIL_GAS:

Well Serial #:	209832	Well Name:	CECELIA NS SU;POINDEXTER
Well #:	002	Well Status:	Not Reported
Well Class:	Not Reported	Operator ID:	0188
Product:	None	Effective Date:	01-OCT-89
API #:	17099213460000	Operation Type:	01
Permit Date:	12-APR-89	Spud Date:	Not Reported
Completion Date:	Not Reported	Recompletion Date:	Not Reported
Last Tested:	Not Reported	Ever Orphaned:	Not Reported
Classification:	Not Reported	Field ID:	2416
State Lease #:	Not Reported	Mud Density:	0
Well Depth:	12150	Inspection Date:	Not Reported
Field Name:	CECELIA	Well Operator:	AMOCO PRODUCTION COMPANY
Scout Well:	03	Scout Report:	13-OCT-89
Scout Measured Depth:	0	Scout True Depth:	0
LUW Name:	Not Reported	LUW Type:	Not Reported
Documents:	http://ucmwww.dnr.state.la.us/ucmsearch/FindDocuments.aspx?idx=xwellserialnumber&val=209832		
Comments:	Not Reported		
URL:	http://sonlite.dnr.state.la.us/sundown/cart_prod/cart_con_wellinfo2?p_WSN=209832		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

State Database: LA Radon

Radon Test Results

Parish	Avg pCi/L	Total Sites
ST MARTIN	0.32500	8

Federal EPA Radon Zone for ST MARTIN County: 3

Note: Zone 1 indoor average level > 4 pCi/L.
: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
: Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 70517

Number of sites tested: 4

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	0.325 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Current USGS 7.5 Minute Topographic Map

Source: U.S. Geological Survey

HYDROLOGIC INFORMATION

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.

Source: FEMA

Telephone: 877-336-2627

Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005, 2010 and 2015 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Service (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Service, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Louisiana Public Water Supply Wells

Source: Office of Public Health

Telephone: 504-568-5101

Water Well Registration Data File

Source: Department of Transportation and Development

Telephone: 225-274-4172

OTHER STATE DATABASE INFORMATION

Oil and Gas Well Database

Source: Department of Natural Resources

Telephone: 225-342-1977

Oil and gas well locations in Louisiana.

RADON

State Database: LA Radon

Source: Department of Environmental Quality

Telephone: 225-925-1752

Radon Levels

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

Appendix D: Qualifications



CHENIER ENVIRONMENTAL CONSULTING, LLC

AARON S. BASS, PH.D.

**4607 BLUEBONNET BLVD. SUITE A
BATON ROUGE, LA 70808**

Education: B.S. 1990, LSU, Business Administration
 M.S. 1993, LSU, Oceanography & Coastal Sciences
 Ph.D. 2004, LSU, Oceanography & Coastal Sciences

EXPERIENCE SUMMARY

Aaron Bass has over 27 years of experience as an environmental scientist. He has completed hundreds of Phase I Environmental Site Assessments on rural, residential, commercial, industrial, and oil and gas producing properties throughout Louisiana, Texas, Alabama, and Mississippi, and Florida

Project Experience:

Representative Phase I Environmental Site Assessment Projects

- Portfolio of Dollar General Stores throughout Louisiana and Mississippi
- Portfolio of Fresenius Kidney Care facilities throughout Louisiana
- Portfolio of Otter Self-storage facilities throughout Louisiana
- Tiger Point Pavilion Wetland Mitigation Bank, Navarre, Florida
- Panama Canal Cell Tower expansion, Gonzales, Louisiana
- Multiple Shell gas station sites, Greenwood, Mississippi
- Amazon Distribution Center, Baton Rouge, Louisiana
- Segers Aero Corporation Facility, Fairhope, Alabama
- Jared Jewelers Retail Store, Lafayette, Louisiana
- Beauregard Apartment Complex, Clinton Mississippi
- Rice Products Enriching, Packaging, and Production Facility, Crowley, Louisiana
- Hampton Inn and Suites, Natchez, Mississippi
- Campus Crossing Apartments, Lafayette, Louisiana
- Walgreens Drug Store, Kenner, Louisiana
- Riverland Mobile Home Court, Saint Rose, Louisiana
- Oak Park Mobile Home Park, Rayne, Louisiana
- Pecan Acres Mobile Home Park, Duson, Louisiana
- Multiple Cubesmart Storage Facilities, Baton Rouge, Louisiana
- Parc Garden Apartments, Lafayette, Louisiana
- Doctor's Pavilion Medical Office Building, Natchez, Mississippi
- National Tire and Battery Sites, New Orleans & Denham Springs, Louisiana
- Pit Stop Car Wash, Slidell, Louisiana
- Multiple Phase I Environmental Site assessments on large tracts of oil and gas producing properties for Chevron Environmental Management Company. Projects completed throughout Louisiana.
- Numerous properties for potential elementary school sites for Ascension Parish School Board.

- Phase I Environmental Site Assessment of 60,500-acre tract in southeast Louisiana prior to purchase by the State of Louisiana Department of Wildlife and Fisheries. This tract later became the Maurepas Swamp Wildlife Management Area.
- Phase I and Phase II Environmental Site Assessments for locally owned restaurant franchise throughout Louisiana, Mississippi, Texas, and Alabama