

**EXHIBIT 11**  
**WETLANDS DELINEATION**

STATUS EMAIL FROM U.S. ARMY CORPS OF ENGINEERS, NEW ORLEANS DISTRICT:

From: **Conerly, Frederick J MVN** <[Frederick.J.Conerly@usace.army.mil](mailto:Frederick.J.Conerly@usace.army.mil)>  
Date: Fri, Aug 21, 2015 at 1:20 PM  
Subject: RE: [EXTERNAL] Checking on PJD request (UNCLASSIFIED)  
To: Bart Pittman <[bartpittman@gmail.com](mailto:bartpittman@gmail.com)>

Classification: UNCLASSIFIED  
Caveats: NONE

Hey Bart,

Your project has been assigned to Mr. Andrew Bennett, Acct No. MVN-2015-01676-SJ. You can reach Andrew at [504-862-2277](tel:504-862-2277) and at [Andrew.J.Bennett@usace.army.mil](mailto:Andrew.J.Bennett@usace.army.mil).

-----Original Message-----

From: Bart Pittman [mailto:[bartpittman@gmail.com](mailto:bartpittman@gmail.com)]  
Sent: Friday, August 21, 2015 11:27 AM  
To: Conerly, Frederick J MVN  
Subject: [EXTERNAL] Checking on PJD request

Fred,

Just wanted to see if one of my recent request for PJD had been assigned a number and/or project manger.

Attached is my cover letter for report, it was sent by certified mail, and received/signed for by E. Wilson in your office on 8-7-15.

Thank you,  
Bart

Classification: UNCLASSIFIED  
Caveats: NONE

**Pittman Environmental Services, LLC**

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487

---

August 3, 2015

Mr. Kyle Randall, PE  
Pan American Engineers, LLC  
1717 Jackson Street  
Alexandria, LA 71301

RE: England Airpark, Site E2  
Approximately 45 Acres  
Rapides Parish, Louisiana


Dear Mr. Randall:

Pursuant to your request, a preliminary wetland delineation has been conducted for the above referenced site. Approximately 0.79 acres of the site was delineated as jurisdictional wetland (wetland drain). An additional 0.39 acres of vegetated ditch was delineated as potentially jurisdictional. The 0.39 acres of vegetated ditch has sufficient wetland indicators and similar features that I have delineated within other sites have been determined jurisdictional, the fact that these are man-made storm water conveyance features within non-wetlands offer a possibility that the COE might not consider them as jurisdictional. I did notice some small "borderline" areas with sedge species. These small pockets did not exhibit sufficient hydrology indicators at time of visit and were likely created by past disturbance. Although not likely, it is possible that the COE could visit the site to review my delineation and consider some of these "borderline" areas to be jurisdictional wetland.

**This delineation is preliminary; it is the responsibility of the U.S. Army Corps of Engineers to issue a jurisdictional determination. I will await your notice to proceed in sending a copy of this report to the COE for jurisdictional determination.**

If you have any questions, or need additional information please contact me at (601) 297-2487.

Sincerely,



Bart A. Pittman  
Environmental Specialist  
Pittman Environmental Services, LLC

## Pittman Environmental Services, LLC

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487

---

**Preliminary Wetland Delineation  
England Site E2  
Approximately 45 Acres  
Rapides Parish, Louisiana**

**August 3, 2015**

### **INTRODUCTION**

At the request of the Pan American Engineers, a preliminary wetland delineation has been conducted for approximately 45 acres located in Sections 34 & 35, Township 4 North, Range 2 West, Rapides Parish Louisiana. The site is located within the England Airpark and was historically utilized for tank farm and rail spur. A recent Jurisdictional Determination (MVK-2014-00087-SC) was issued for property adjacent to the east. The approximate center coordinates of the site are 31.334082, -92.530449. The attached maps depict the exact location and extent of the approximately 45 acre site. This report will describe the results of a preliminary wetland delineation conducted for the said property to determine the presence and approximate extent of jurisdictional wetlands and “waters of the U.S.” as defined in Section 404 of the Clean Water Act. The onsite wetland delineation was conducted by Mr. Bart Pittman on July 29<sup>th</sup> and 30<sup>th</sup>, 2015.

### **SITE DESCRIPTION**

The ±45 acre site is located within the England Airpark and was until recently utilized for a tank farm with transecting rail spur. The tank farm and a portion of the rail spur have been removed. Industrial development surrounds the site with railroad along the western limits. With exception of tree line along the eastern and northern property limits, the entire site is comprised of herbaceous species. The site is nearly level to slightly sloping. The NRCS Web Soil Survey indicates the primary soil units within the site as Coughatta silt loam (Nd) and Coughatta silty clay loam (Nw). Pictures (**Attachment 2**) depict the current site conditions.

### **METHODOLOGY**

Methods utilized for identifying and delineating wetlands follow procedures outlined in Part IV of the “Corps of Engineers Wetlands Delineation Manual” dated January 1987 and the Atlantic/Gulf Cost Plain Regional Supplement. Wetland Delineation Data Forms (Atlantic and Gulf Cost Plain Region) were completed for each vegetative community represented within the property. These attached data forms (**Attachment 3**) provide a listing of parameters/indicators to

## Pittman Environmental Services, LLC

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487

---

differentiate jurisdictional wetlands from non-wetlands. The completed forms confirm the presence or absence of the three required wetland criteria; hydrophytic vegetation, wetland hydrology, and hydric soils. The approximate location of each data point is shown on the attached preliminary wetland delineation map, (**Attachment 1**). The site was pedestrian surveyed for visual indicators of potential wetlands; soil profiles were examined in suspect areas to determine if any hydrology/hydric soil indicators were present.

### RESULTS

Once the presence and location of wetland was established, the boundaries were flagged. After flagging of boundaries was completed, mapping of the wetland areas was performed by use of a sub-meter GPS, (Ashtech Mobile Mapper). GPS data was overlaid with aerial imagery and the site limits in ArcMap 10.1 to provide the approximate location and extent of delineated features as depicted on the attached preliminary wetland delineation map, (**Attachment 1**).

After careful field review of the subject property and all available sources of information, approximately 0.79 acres of the site was delineated as jurisdictional wetland. An additional 0.39 acres of vegetated ditch was delineated as potentially jurisdictional. The location of delineated features and data points are shown in **Attachment 1**.

#### **Jurisdictional Wetland/Drain**

One wetland drain (approximately 0.79 acres) transects the site flowing northwest to Big Bayou. This drain is comprised of herbaceous vegetation with some pools of shallow inundation. FACW and OBL species is dominant within this drain. This drain collects storm water from smaller ditches that drain developed areas south of the site. Data point #4 was recorded within this wetland area.

#### **Potentially Jurisdictional Ditch**

Two vegetated ditches (approximately 0.39 acres combined) were delineated within the site. The two ditches drain storm water from the developed areas south of the site to the larger wetland drain. These ditches were created for storm water conveyance and are potentially jurisdictional.

## Pittman Environmental Services, LLC

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487

---

### Herbaceous Non-Wetland

The majority of the site is comprised of well drained, herbaceous non-wetland. Four non-wetland Data Points were recorded within the site. Dominant species include *Sorghum halepense*, *Ambrosia spp.*, *Setaria spp.*, *Campsis radicans*, and *Vernonia spp.* Hydrology and hydric soil indicators were absent within the delineated non-wetlands.


### SUMMARY

Based upon careful review of all available data and an onsite inspection, approximately 0.79 acres of the site was delineated as jurisdictional wetland. An additional 0.39 acres of vegetated ditch was delineated as potentially jurisdictional. The attached wetland delineation data forms (**Attachment 3**) confirm the conclusion of the preliminary study, indicating the presence or absence of sufficient wetland criteria at each data point. The location of delineated areas and of the data points are shown on the preliminary wetland delineation maps, **Attachment 1**.

*This wetland delineation is preliminary and should not be interpreted as a final determination. The responsibility of a final wetland determination is that of the U.S. Army Corps of Engineers, New Orleans District.*

Please call (601)-297-2487 if you have any questions or need additional information regarding this study.

Sincerely,



Bart A. Pittman  
Environmental Specialist  
Pittman Environmental Services, LLC


**Pittman Environmental Services, LLC**

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487


---

**ATTACHMENT 1  
MAPS**

**FIGURE 1**



**FIGURE 2**






Hydric Rating by Map Unit—Rapides Parish, Louisiana




Map Scale: 1:5,410 if printed on A portrait (8.5" x 11") sheet.









## MAP LEGEND

### Area of Interest (AOI)







 Area of Interest (AOI)

### Soils







#### Soil Rating Polygons

-  Hydric (100%)
-  Hydric (66 to 99%)
-  Hydric (33 to 65%)
-  Hydric (1 to 32%)
-  Not Hydric (0%)
-  Not rated or not available


#### Soil Rating Lines

-  Hydric (100%)
-  Hydric (66 to 99%)
-  Hydric (33 to 65%)
-  Hydric (1 to 32%)
-  Not Hydric (0%)
-  Not rated or not available






#### Soil Rating Points

-  Hydric (100%)
-  Hydric (66 to 99%)
-  Hydric (33 to 65%)
-  Hydric (1 to 32%)
-  Not Hydric (0%)
-  Not rated or not available

### Water Features

 Streams and Canals

### Transportation

-  Rails
-  Interstate Highways
-  US Routes
-  Major Roads
-  Local Roads

### Background

-  Aerial Photography

## MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:24,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service  
 Web Soil Survey URL: <http://websoilsurvey.nrcs.usda.gov>  
 Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Rapides Parish, Louisiana  
 Survey Area Data: Version 10, Sep 26, 2014

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Feb 12, 2011—Mar 15, 2011

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

## Hydric Rating by Map Unit

Hydric Rating by Map Unit— Summary by Map Unit — Rapides Parish, Louisiana (LA079)				
Map unit symbol	Map unit name	Rating	Acres in AOI	Percent of AOI
MnA	Moreland clay, 0 to 1 percent slopes, rarely flooded	1	0.0	0.0%
Nd	Coushatta silt loam, 0 to 1 percent slopes	1	37.5	78.9%
Nw	Coushatta silty clay loam, 0 to 1 percent slopes	1	10.0	21.1%
<b>Totals for Area of Interest</b>			<b>47.5</b>	<b>100.0%</b>

**Pittman Environmental Services, LLC**

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487

---

**ATTACHMENT 2  
SITE PHOTOGRAPHS**



Southern portion of site, facing east



Facing south from northern limits, railroad to right

Pittman Environmental Services, LLC	PROJECT:	E2 Site-England Airpark, Rapides Parish Louisiana	PHOTOS 1-2
	TITLE:	SITE PHOTOGRAPHS	



Wooded area of DP-1, northern property line



Soil matrix at DP-1

Pittman Environmental Services, LLC	PROJECT:	E2 Site-England Airpark, Rapides Parish Louisiana
	TITLE:	SITE PHOTOGRAPHS



DP-2 facing south



Soil matrix at DP-2

Pittman Environmental Services, LLC	PROJECT:	E2 Site-England Airpark, Rapides Parish Louisiana	PHOTOS 5-6
	TITLE:	SITE PHOTOGRAPHS	



DP-4, Wetland Drain facing NW



Soil matrix at DP-4

Pittman Environmental Services, LLC	PROJECT:	E2 Site-England Airpark, Rapides Parish Louisiana	PHOTOS 7-8
	TITLE:	SITE PHOTOGRAPHS	





Wet Ditch facing North



Facing north from DP-5

Pittman Environmental Services, LLC	PROJECT:	E2 Site-England Airpark, Rapides Parish Louisiana
	TITLE:	SITE PHOTOGRAPHS
		PHOTOS 9-10

**Pittman Environmental Services, LLC**

P.O. Box 1926 ▪ Purvis, MS 39475 ▪ Phone: 601-297-2487

---

**ATTACHMENT 3  
DATA FORMS**

**WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region**

Project/Site: Site E2, +/-45 Acres City/County: Alexandria/Rapides Sampling Date: 07/30/2015  
 Applicant/Owner: England Authority State: LA Sampling Point: Data Point 1  
 Investigator(s): B. Pittman Section, Township, Range: Section 34 T-4N, R-2W  
 Landform (hillslope, terrace, etc.): terrace Local relief (concave, convex, none): nearly level Slope (%): 1-2  
 Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 31.337414 Long: -92.529755 Datum: NAD 83  
 Soil Map Unit Name: Coushatta silty clay loam (Nw) NWI classification: NA

Are climatic / hydrologic conditions on the site typical for this time of year? Yes  No \_\_\_\_\_ (If no, explain in Remarks.)  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes  No \_\_\_\_\_  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
--	--

Remarks:  
 Wooded strip along northern boundary

**HYDROLOGY**

<b>Wetland Hydrology Indicators:</b> <u>Primary Indicators (minimum of one is required; check all that apply)</u> ___ Surface Water (A1)      ___ Aquatic Fauna (B13) ___ High Water Table (A2)      ___ Marl Deposits (B15) <b>(LRR U)</b> ___ Saturation (A3)      ___ Hydrogen Sulfide Odor (C1) ___ Water Marks (B1)      ___ Oxidized Rhizospheres along Living Roots (C3) ___ Sediment Deposits (B2)      ___ Presence of Reduced Iron (C4) ___ Drift Deposits (B3)      ___ Recent Iron Reduction in Tilled Soils (C6) ___ Algal Mat or Crust (B4)      ___ Thin Muck Surface (C7) ___ Iron Deposits (B5)      ___ Other (Explain in Remarks) ___ Inundation Visible on Aerial Imagery (B7) ___ Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> ___ Surface Soil Cracks (B6) ___ Sparsely Vegetated Concave Surface (B8) ___ Drainage Patterns (B10) ___ Moss Trim Lines (B16) ___ Dry-Season Water Table (C2) ___ Crayfish Burrows (C8) ___ Saturation Visible on Aerial Imagery (C9) ___ Geomorphic Position (D2) ___ Shallow Aquitard (D3) ___ FAC-Neutral Test (D5) ___ Sphagnum moss (D8) <b>(LRR T, U)</b>
---	---

<b>Field Observations:</b> Surface Water Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Water Table Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Saturation Present? (includes capillary fringe) Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____	Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:  
 No saturation, well drained.

**VEGETATION (Four Strata)** – Use scientific names of plants.

Sampling Point: \_\_\_\_\_

<u>Tree Stratum</u> (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. Liquidambar styraciflua	30	yes	FAC
2. Celtis laevigata	25	yes	FACW
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

55 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

<u>Sapling/Shrub Stratum</u> (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. Diospyros virginiana	10	yes	FAC
2. Celtis laevigata	5	yes	FACW
3. Cornus drummondii	10	yes	FAC
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

25 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

<u>Herb Stratum</u> (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. Toxicodendron radicans	4	yes	FAC
2. Campsis radicans	4	yes	FAC
3. Carex spp.	3	yes	FAC
4. Ambrosia trifida	8	yes	FAC
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____

19 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

<u>Woody Vine Stratum</u> (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____

0 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Remarks: (If observed, list morphological adaptations below).

**Dominance Test worksheet:**

Number of Dominant Species That Are OBL, FACW, or FAC: 8 (A)

Total Number of Dominant Species Across All Strata: 8 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 100 (A/B)

**Prevalence Index worksheet:**

Total % Cover of:	Multiply by:
OBL species _____	x 1 = _____
FACW species _____	x 2 = _____
FAC species _____	x 3 = _____
FACU species _____	x 4 = _____
UPL species _____	x 5 = _____
Column Totals: 0 (A)	0 (B)

Prevalence Index = B/A = \_\_\_\_\_

**Hydrophytic Vegetation Indicators:**

- 1 - Rapid Test for Hydrophytic Vegetation
- 2 - Dominance Test is >50%
- 3 - Prevalence Index is ≤3.0<sup>1</sup>
- Problematic Hydrophytic Vegetation<sup>1</sup> (Explain)

<sup>1</sup>Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

**Definitions of Four Vegetation Strata:**

**Tree** – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

**Sapling/Shrub** – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

**Herb** – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

**Woody vine** – All woody vines greater than 3.28 ft in height.

**Hydrophytic Vegetation Present?**

Yes  No

**SOIL**

Sampling Point: DP-1

**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0-5	5 YR 4/3	97%				IV	clay loam	
5-19	5YR 4/4	97%					clay loam	

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

<sup>2</sup>Location: PL=Pore Lining, M=Matrix.

**Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)**

**Indicators for Problematic Hydric Soils<sup>3</sup>:**

- |  |   |   |
|--|---|---|
| <input type="checkbox"/> Histosol (A1)                         | <input type="checkbox"/> Polyvalue Below Surface (S8) (LRR S, T, U)                 | <input type="checkbox"/> 1 cm Muck (A9) (LRR O)   |
| <input type="checkbox"/> Histic Epipedon (A2)                  | <input type="checkbox"/> Thin Dark Surface (S9) (LRR S, T, U)                       | <input type="checkbox"/> 2 cm Muck (A10) (LRR S)  |
| <input type="checkbox"/> Black Histic (A3)                     | <input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR O)                           | <input type="checkbox"/> Reduced Vertic (F18) (outside MLRA 150A,B)   |
| <input type="checkbox"/> Hydrogen Sulfide (A4)                 | <input type="checkbox"/> Loamy Gleyed Matrix (F2)                                   | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (LRR P, S, T)  |
| <input type="checkbox"/> Stratified Layers (A5)                | <input type="checkbox"/> Depleted Matrix (F3)                                       | <input type="checkbox"/> Anomalous Bright Loamy Soils (F20)   |
| <input type="checkbox"/> Organic Bodies (A6) (LRR P, T, U)     | <input type="checkbox"/> Redox Dark Surface (F6)                                    | <b>(MLRA 153B)</b>  |
| <input type="checkbox"/> 5 cm Mucky Mineral (A7) (LRR P, T, U) | <input type="checkbox"/> Depleted Dark Surface (F7)                                 | <input type="checkbox"/> Red Parent Material (TF2)  |
| <input type="checkbox"/> Muck Presence (A8) (LRR U)            | <input type="checkbox"/> Redox Depressions (F8)                                     | <input type="checkbox"/> Very Shallow Dark Surface (TF12)   |
| <input type="checkbox"/> 1 cm Muck (A9) (LRR P, T)             | <input type="checkbox"/> Marl (F10) (LRR U)   | <input type="checkbox"/> Other (Explain in Remarks)   |
| <input type="checkbox"/> Depleted Below Dark Surface (A11)     | <input type="checkbox"/> Depleted Ochric (F11) (MLRA 151)                           |   |
| <input type="checkbox"/> Thick Dark Surface (A12)              | <input type="checkbox"/> Iron-Manganese Masses (F12) (LRR O, P, T)                  | <sup>3</sup> Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic. |
| <input type="checkbox"/> Coast Prairie Redox (A16) (MLRA 150A) | <input type="checkbox"/> Umbric Surface (F13) (LRR P, T, U)                         |   |
| <input type="checkbox"/> Sandy Mucky Mineral (S1) (LRR O, S)   | <input type="checkbox"/> Delta Ochric (F17) (MLRA 151)                              |   |
| <input type="checkbox"/> Sandy Gleyed Matrix (S4)              | <input type="checkbox"/> Reduced Vertic (F18) (MLRA 150A, 150B)                     |   |
| <input type="checkbox"/> Sandy Redox (S5)                      | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (MLRA 149A)                |   |
| <input type="checkbox"/> Stripped Matrix (S6)                  | <input type="checkbox"/> Anomalous Bright Loamy Soils (F20) (MLRA 149A, 153C, 153D) |   |
| <input type="checkbox"/> Dark Surface (S7) (LRR P, S, T, U)    |   |   |

**Restrictive Layer (if observed):**

Type: \_\_\_\_\_

Depth (inches): \_\_\_\_\_

Hydric Soil Present? Yes  No

Remarks:

**WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region**

Project/Site: Site E2, +/-45 Acres City/County: Alexandria/Rapides Sampling Date: 07/30/2015  
 Applicant/Owner: England Authority State: LA Sampling Point: Data Point 2  
 Investigator(s): B. Pittman Section, Township, Range: Section 34 T-4N, R-2W  
 Landform (hillslope, terrace, etc.): terrace Local relief (concave, convex, none): nearly level Slope (%): 1-2  
 Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 31.334886 Long: -92.529454 Datum: NAD 83  
 Soil Map Unit Name: Coushatta silt loam (Nd) NWI classification: NA

Are climatic / hydrologic conditions on the site typical for this time of year? Yes  No \_\_\_\_\_ (If no, explain in Remarks.)  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes  No \_\_\_\_\_  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
--	--

Remarks:

**HYDROLOGY**

<b>Wetland Hydrology Indicators:</b> <u>Primary Indicators (minimum of one is required; check all that apply)</u> ___ Surface Water (A1)      ___ Aquatic Fauna (B13) ___ High Water Table (A2)      ___ Marl Deposits (B15) (LRR U) ___ Saturation (A3)      ___ Hydrogen Sulfide Odor (C1) ___ Water Marks (B1)      ___ Oxidized Rhizospheres along Living Roots (C3) ___ Sediment Deposits (B2)      ___ Presence of Reduced Iron (C4) ___ Drift Deposits (B3)      ___ Recent Iron Reduction in Tilled Soils (C6) ___ Algal Mat or Crust (B4)      ___ Thin Muck Surface (C7) ___ Iron Deposits (B5)      ___ Other (Explain in Remarks) ___ Inundation Visible on Aerial Imagery (B7) ___ Water-Stained Leaves (B9)	<b>Secondary Indicators (minimum of two required)</b> ___ Surface Soil Cracks (B6) ___ Sparsely Vegetated Concave Surface (B8) ___ Drainage Patterns (B10) ___ Moss Trim Lines (B16) ___ Dry-Season Water Table (C2) ___ Crayfish Burrows (C8) ___ Saturation Visible on Aerial Imagery (C9) ___ Geomorphic Position (D2) ___ Shallow Aquitard (D3) ___ FAC-Neutral Test (D5) ___ Sphagnum moss (D8) (LRR T, U)
--	--

<b>Field Observations:</b> Surface Water Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Water Table Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Saturation Present? (includes capillary fringe) Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____	Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

No saturation, well drained.

**VEGETATION (Four Strata)** – Use scientific names of plants.

Sampling Point: \_\_\_\_\_

Tree Stratum (Plot size: \_\_\_\_\_ )

	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Sapling/Shrub Stratum (Plot size: \_\_\_\_\_ )

1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Herb Stratum (Plot size: \_\_\_\_\_ )

1. <i>Setaria</i> spp.	30	yes	FAC
2. <i>Campsis radicans</i>	15	yes	FAC
3. <i>Sorghum halepense</i>	20	yes	FAC
4. <i>Vernonia altissima</i>	10	yes	FAC
5. UK grass	20	yes	FAC
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____

95 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Woody Vine Stratum (Plot size: \_\_\_\_\_ )

1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Remarks: (If observed, list morphological adaptations below).

**Dominance Test worksheet:**

Number of Dominant Species That Are OBL, FACW, or FAC: 5 \_\_\_\_\_ (A)

Total Number of Dominant Species Across All Strata: 5 \_\_\_\_\_ (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 100 \_\_\_\_\_ (A/B)

**Prevalence Index worksheet:**

Total % Cover of:	Multiply by:
OBL species _____	x 1 = _____
FACW species _____	x 2 = _____
FAC species _____	x 3 = _____
FACU species _____	x 4 = _____
UPL species _____	x 5 = _____
Column Totals: 0 _____ (A)	0 _____ (B)

Prevalence Index = B/A = \_\_\_\_\_

**Hydrophytic Vegetation Indicators:**

- 1 - Rapid Test for Hydrophytic Vegetation
- 2 - Dominance Test is >50%
- 3 - Prevalence Index is ≤3.0<sup>1</sup>
- Problematic Hydrophytic Vegetation<sup>1</sup> (Explain)

<sup>1</sup>Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

**Definitions of Four Vegetation Strata:**

**Tree** – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

**Sapling/Shrub** – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

**Herb** – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

**Woody vine** – All woody vines greater than 3.28 ft in height.

**Hydrophytic Vegetation Present?**

Yes  No

**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0-18	5 YR 5/6	80%					sandy loam	
	5YR 5/4	20%						

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

<sup>2</sup>Location: PL=Pore Lining, M=Matrix.

**Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)**

**Indicators for Problematic Hydric Soils<sup>3</sup>:**

- |  |   |   |
|--|---|---|
| <input type="checkbox"/> Histosol (A1)                         | <input type="checkbox"/> Polyvalue Below Surface (S8) (LRR S, T, U)                 | <input type="checkbox"/> 1 cm Muck (A9) (LRR O)   |
| <input type="checkbox"/> Histic Epipedon (A2)                  | <input type="checkbox"/> Thin Dark Surface (S9) (LRR S, T, U)                       | <input type="checkbox"/> 2 cm Muck (A10) (LRR S)  |
| <input type="checkbox"/> Black Histic (A3)                     | <input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR O)                           | <input type="checkbox"/> Reduced Vertic (F18) (outside MLRA 150A,B)   |
| <input type="checkbox"/> Hydrogen Sulfide (A4)                 | <input type="checkbox"/> Loamy Gleyed Matrix (F2)                                   | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (LRR P, S, T)  |
| <input type="checkbox"/> Stratified Layers (A5)                | <input type="checkbox"/> Depleted Matrix (F3)                                       | <input type="checkbox"/> Anomalous Bright Loamy Soils (F20)   |
| <input type="checkbox"/> Organic Bodies (A6) (LRR P, T, U)     | <input type="checkbox"/> Redox Dark Surface (F6)                                    | <b>(MLRA 153B)</b>  |
| <input type="checkbox"/> 5 cm Mucky Mineral (A7) (LRR P, T, U) | <input type="checkbox"/> Depleted Dark Surface (F7)                                 | <input type="checkbox"/> Red Parent Material (TF2)  |
| <input type="checkbox"/> Muck Presence (A8) (LRR U)            | <input type="checkbox"/> Redox Depressions (F8)                                     | <input type="checkbox"/> Very Shallow Dark Surface (TF12)   |
| <input type="checkbox"/> 1 cm Muck (A9) (LRR P, T)             | <input type="checkbox"/> Marl (F10) (LRR U)   | <input type="checkbox"/> Other (Explain in Remarks)   |
| <input type="checkbox"/> Depleted Below Dark Surface (A11)     | <input type="checkbox"/> Depleted Ochric (F11) (MLRA 151)                           |   |
| <input type="checkbox"/> Thick Dark Surface (A12)              | <input type="checkbox"/> Iron-Manganese Masses (F12) (LRR O, P, T)                  | <sup>3</sup> Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic. |
| <input type="checkbox"/> Coast Prairie Redox (A16) (MLRA 150A) | <input type="checkbox"/> Umbric Surface (F13) (LRR P, T, U)                         |   |
| <input type="checkbox"/> Sandy Mucky Mineral (S1) (LRR O, S)   | <input type="checkbox"/> Delta Ochric (F17) (MLRA 151)                              |   |
| <input type="checkbox"/> Sandy Gleyed Matrix (S4)              | <input type="checkbox"/> Reduced Vertic (F18) (MLRA 150A, 150B)                     |   |
| <input type="checkbox"/> Sandy Redox (S5)                      | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (MLRA 149A)                |   |
| <input type="checkbox"/> Stripped Matrix (S6)                  | <input type="checkbox"/> Anomalous Bright Loamy Soils (F20) (MLRA 149A, 153C, 153D) |   |
| <input type="checkbox"/> Dark Surface (S7) (LRR P, S, T, U)    |   |   |

**Restrictive Layer (if observed):**

Type: \_\_\_\_\_  
 Depth (inches): \_\_\_\_\_

Hydric Soil Present? Yes  No

Remarks:



**WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region**

Project/Site: Site E2, +/-45 Acres City/County: Alexandria/Rapides Sampling Date: 07/30/2015  
 Applicant/Owner: England Authority State: LA Sampling Point: Data Point 3  
 Investigator(s): B. Pittman Section, Township, Range: Section 35 T-4N, R-2W  
 Landform (hillslope, terrace, etc.): terrace Local relief (concave, convex, none): nearly level Slope (%): 1-2  
 Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 31.334017 Long: -92.531292 Datum: NAD 83  
 Soil Map Unit Name: Coushatta silt loam (Nd) NWI classification: NA

Are climatic / hydrologic conditions on the site typical for this time of year? Yes  No \_\_\_\_\_ (If no, explain in Remarks.)  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes  No \_\_\_\_\_  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
--	--

Remarks:

**HYDROLOGY**

<b>Wetland Hydrology Indicators:</b> <u>Primary Indicators (minimum of one is required; check all that apply)</u> ___ Surface Water (A1)                      ___ Aquatic Fauna (B13) ___ High Water Table (A2)                 ___ Marl Deposits (B15) <b>(LRR U)</b> ___ Saturation (A3)                            ___ Hydrogen Sulfide Odor (C1) ___ Water Marks (B1)                         ___ Oxidized Rhizospheres along Living Roots (C3) ___ Sediment Deposits (B2)                 ___ Presence of Reduced Iron (C4) ___ Drift Deposits (B3)                        ___ Recent Iron Reduction in Tilled Soils (C6) ___ Algal Mat or Crust (B4)                    ___ Thin Muck Surface (C7) ___ Iron Deposits (B5)                         ___ Other (Explain in Remarks) ___ Inundation Visible on Aerial Imagery (B7) ___ Water-Stained Leaves (B9)	<b>Secondary Indicators (minimum of two required)</b> ___ Surface Soil Cracks (B6) ___ Sparsely Vegetated Concave Surface (B8) ___ Drainage Patterns (B10) ___ Moss Trim Lines (B16) ___ Dry-Season Water Table (C2) ___ Crayfish Burrows (C8) ___ Saturation Visible on Aerial Imagery (C9) ___ Geomorphic Position (D2) ___ Shallow Aquitard (D3) ___ FAC-Neutral Test (D5) ___ Sphagnum moss (D8) <b>(LRR T, U)</b>
---	---

**Field Observations:**

Surface Water Present? Yes _____ No <input checked="" type="checkbox"/>	Depth (inches): _____
Water Table Present? Yes _____ No <input checked="" type="checkbox"/>	Depth (inches): _____
Saturation Present? (includes capillary fringe) Yes _____ No <input checked="" type="checkbox"/>	Depth (inches): _____

**Wetland Hydrology Present? Yes \_\_\_\_\_ No**

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

No saturation, well drained.

**VEGETATION (Four Strata)** – Use scientific names of plants.

Sampling Point: \_\_\_\_\_

Tree Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Sapling/Shrub Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Herb Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. Sorghum halepense	50	yes	FAC
2. Campsis radicans	25	yes	FAC
3. Ambrosia trifida	7	yes	FAC
4. Vitis spp.	10	yes	FAC
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____

92 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Woody Vine Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____

0 = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Remarks: (If observed, list morphological adaptations below).

**Dominance Test worksheet:**

Number of Dominant Species That Are OBL, FACW, or FAC: 4 (A)

Total Number of Dominant Species Across All Strata: 4 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 100 (A/B)

**Prevalence Index worksheet:**

Total % Cover of: \_\_\_\_\_ Multiply by: \_\_\_\_\_

OBL species \_\_\_\_\_ x 1 = \_\_\_\_\_

FACW species \_\_\_\_\_ x 2 = \_\_\_\_\_

FAC species \_\_\_\_\_ x 3 = \_\_\_\_\_

FACU species \_\_\_\_\_ x 4 = \_\_\_\_\_

UPL species \_\_\_\_\_ x 5 = \_\_\_\_\_

Column Totals: 0 (A) 0 (B)

Prevalence Index = B/A = \_\_\_\_\_

**Hydrophytic Vegetation Indicators:**

1 - Rapid Test for Hydrophytic Vegetation

2 - Dominance Test is >50%

3 - Prevalence Index is ≤3.0<sup>1</sup>

Problematic Hydrophytic Vegetation<sup>1</sup> (Explain)

<sup>1</sup>Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

**Definitions of Four Vegetation Strata:**

**Tree** – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

**Sapling/Shrub** – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

**Herb** – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

**Woody vine** – All woody vines greater than 3.28 ft in height.

**Hydrophytic Vegetation Present?**

Yes  No

**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0-18	5 YR 4/3	85%	5 YR 4/2	15%	R/VI	VI	sandy loam	some gravel

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.      <sup>2</sup>Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)		Indicators for Problematic Hydric Soils <sup>3</sup> :	
<input type="checkbox"/> Histosol (A1)	<input type="checkbox"/> Polyvalue Below Surface (S8) (LRR S, T, U)	<input type="checkbox"/> 1 cm Muck (A9) (LRR O)	<sup>3</sup> Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.
<input type="checkbox"/> Histic Epipedon (A2)	<input type="checkbox"/> Thin Dark Surface (S9) (LRR S, T, U)	<input type="checkbox"/> 2 cm Muck (A10) (LRR S)	
<input type="checkbox"/> Black Histic (A3)	<input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR O)	<input type="checkbox"/> Reduced Vertic (F18) (outside MLRA 150A,B)	
<input type="checkbox"/> Hydrogen Sulfide (A4)	<input type="checkbox"/> Loamy Gleyed Matrix (F2)	<input type="checkbox"/> Piedmont Floodplain Soils (F19) (LRR P, S, T)	
<input type="checkbox"/> Stratified Layers (A5)	<input type="checkbox"/> Depleted Matrix (F3)	<input type="checkbox"/> Anomalous Bright Loamy Soils (F20)	
<input type="checkbox"/> Organic Bodies (A6) (LRR P, T, U)	<input type="checkbox"/> Redox Dark Surface (F6)	<input type="checkbox"/> (MLRA 153B)	
<input type="checkbox"/> 5 cm Mucky Mineral (A7) (LRR P, T, U)	<input type="checkbox"/> Depleted Dark Surface (F7)	<input type="checkbox"/> Red Parent Material (TF2)	
<input type="checkbox"/> Muck Presence (A8) (LRR U)	<input type="checkbox"/> Redox Depressions (F8)	<input type="checkbox"/> Very Shallow Dark Surface (TF12)	
<input type="checkbox"/> 1 cm Muck (A9) (LRR P, T)	<input type="checkbox"/> Marl (F10) (LRR U)	<input type="checkbox"/> Other (Explain in Remarks)	
<input type="checkbox"/> Depleted Below Dark Surface (A11)	<input type="checkbox"/> Depleted Ochric (F11) (MLRA 151)		
<input type="checkbox"/> Thick Dark Surface (A12)	<input type="checkbox"/> Iron-Manganese Masses (F12) (LRR O, P, T)		
<input type="checkbox"/> Coast Prairie Redox (A16) (MLRA 150A)	<input type="checkbox"/> Umbric Surface (F13) (LRR P, T, U)		
<input type="checkbox"/> Sandy Mucky Mineral (S1) (LRR O, S)	<input type="checkbox"/> Delta Ochric (F17) (MLRA 151)		
<input type="checkbox"/> Sandy Gleyed Matrix (S4)	<input type="checkbox"/> Reduced Vertic (F18) (MLRA 150A, 150B)		
<input type="checkbox"/> Sandy Redox (S5)	<input type="checkbox"/> Piedmont Floodplain Soils (F19) (MLRA 149A)		
<input type="checkbox"/> Stripped Matrix (S6)	<input type="checkbox"/> Anomalous Bright Loamy Soils (F20) (MLRA 149A, 153C, 153D)		
<input type="checkbox"/> Dark Surface (S7) (LRR P, S, T, U)			

**Restrictive Layer (if observed):**

Type: \_\_\_\_\_

Depth (inches): \_\_\_\_\_

Hydric Soil Present?    Yes     No

Remarks:

area historically disturbed

**WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region**

Project/Site: Site E2, +/-45 Acres City/County: Alexandria/Rapides Sampling Date: 07/30/2015  
 Applicant/Owner: England Authority State: LA Sampling Point: Data Point 4  
 Investigator(s): B. Pittman Section, Township, Range: Section 34 T-4N, R-2W  
 Landform (hillslope, terrace, etc.): wetland drain Local relief (concave, convex, none): nearly level Slope (%): 1-2  
 Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 31.332021 Long: -92.529830 Datum: NAD 83  
 Soil Map Unit Name: Coushatta silt loam (Nd) NWI classification: NA

Are climatic / hydrologic conditions on the site typical for this time of year? Yes  No \_\_\_\_\_ (If no, explain in Remarks.)  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes  No \_\_\_\_\_  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes <input checked="" type="checkbox"/> No _____ Wetland Hydrology Present? Yes <input checked="" type="checkbox"/> No _____	Is the Sampled Area within a Wetland? Yes <input checked="" type="checkbox"/> No _____
--	--

Remarks:

**HYDROLOGY**

<p><b>Wetland Hydrology Indicators:</b></p> <p><u>Primary Indicators (minimum of one is required; check all that apply)</u></p> ___ Surface Water (A1)                      ___ Aquatic Fauna (B13) ___ High Water Table (A2)                      ___ Marl Deposits (B15) <b>(LRR U)</b> <input checked="" type="checkbox"/> Saturation (A3)                                      ___ Hydrogen Sulfide Odor (C1) ___ Water Marks (B1)                                      ___ Oxidized Rhizospheres along Living Roots (C3) ___ Sediment Deposits (B2)                                      ___ Presence of Reduced Iron (C4) ___ Drift Deposits (B3)                                      ___ Recent Iron Reduction in Tilled Soils (C6) ___ Algal Mat or Crust (B4)                                      ___ Thin Muck Surface (C7) ___ Iron Deposits (B5)                                      ___ Other (Explain in Remarks) ___ Inundation Visible on Aerial Imagery (B7) ___ Water-Stained Leaves (B9)	<p><u>Secondary Indicators (minimum of two required)</u></p> ___ Surface Soil Cracks (B6) ___ Sparsely Vegetated Concave Surface (B8) ___ Drainage Patterns (B10) ___ Moss Trim Lines (B16) ___ Dry-Season Water Table (C2) ___ Crayfish Burrows (C8) <input checked="" type="checkbox"/> Saturation Visible on Aerial Imagery (C9) ___ Geomorphic Position (D2) ___ Shallow Aquitard (D3) <input checked="" type="checkbox"/> FAC-Neutral Test (D5) ___ Sphagnum moss (D8) <b>(LRR T, U)</b>
---	---

<p><b>Field Observations:</b></p> Surface Water Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Water Table Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Saturation Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>surface</u> (includes capillary fringe)	Wetland Hydrology Present? Yes <input checked="" type="checkbox"/> No _____
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

Some pools of inundation within drain.

**VEGETATION (Four Strata) – Use scientific names of plants.**

Sampling Point: \_\_\_\_\_

Tree Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Sapling/Shrub Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Herb Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. Juncus effusus	50	yes	FACW
2. Typha latifolia	10	yes	OBL
3. Cyperus spp.	20	yes	FACW
4. Juncus spp.	10	yes	FACW
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____

90 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Woody Vine Stratum (Plot size: _____ )	Absolute % Cover	Dominant Species?	Indicator Status
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Remarks: (If observed, list morphological adaptations below).

**Dominance Test worksheet:**

Number of Dominant Species That Are OBL, FACW, or FAC: 4 \_\_\_\_\_ (A)

Total Number of Dominant Species Across All Strata: 4 \_\_\_\_\_ (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 100 \_\_\_\_\_ (A/B)

**Prevalence Index worksheet:**

Total % Cover of: \_\_\_\_\_ Multiply by: \_\_\_\_\_

OBL species \_\_\_\_\_ x 1 = \_\_\_\_\_

FACW species \_\_\_\_\_ x 2 = \_\_\_\_\_

FAC species \_\_\_\_\_ x 3 = \_\_\_\_\_

FACU species \_\_\_\_\_ x 4 = \_\_\_\_\_

UPL species \_\_\_\_\_ x 5 = \_\_\_\_\_

Column Totals: 0 \_\_\_\_\_ (A) 0 \_\_\_\_\_ (B)

Prevalence Index = B/A = \_\_\_\_\_

**Hydrophytic Vegetation Indicators:**

1 - Rapid Test for Hydrophytic Vegetation

2 - Dominance Test is >50%

3 - Prevalence Index is ≤3.0<sup>1</sup>

Problematic Hydrophytic Vegetation<sup>1</sup> (Explain)

<sup>1</sup>Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

**Definitions of Four Vegetation Strata:**

**Tree** – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

**Sapling/Shrub** – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

**Herb** – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

**Woody vine** – All woody vines greater than 3.28 ft in height.

**Hydrophytic Vegetation Present?**

Yes  No

**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0-18	5 YR 4/3	50%	5 YR 4/2	40%	KIVI	IVI	sandy loam	some gravel
			5 YR 4/1	10%	KIVI	IVI		

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

<sup>2</sup>Location: PL=Pore Lining, M=Matrix.

**Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)**

**Indicators for Problematic Hydric Soils<sup>3</sup>:**

- Histosol (A1)
- Histic Epipedon (A2)
- Black Histic (A3)
- Hydrogen Sulfide (A4)
- Stratified Layers (A5)
- Organic Bodies (A6) (LRR P, T, U)
- 5 cm Mucky Mineral (A7) (LRR P, T, U)
- Muck Presence (A8) (LRR U)
- 1 cm Muck (A9) (LRR P, T)
- Depleted Below Dark Surface (A11)
- Thick Dark Surface (A12)
- Coast Prairie Redox (A16) (MLRA 150A)
- Sandy Mucky Mineral (S1) (LRR O, S)
- Sandy Gleyed Matrix (S4)
- Sandy Redox (S5)
- Stripped Matrix (S6)
- Dark Surface (S7) (LRR P, S, T, U)
- Polyvalue Below Surface (S8) (LRR S, T, U)
- Thin Dark Surface (S9) (LRR S, T, U)
- Loamy Mucky Mineral (F1) (LRR O)
- Loamy Gleyed Matrix (F2)
- Depleted Matrix (F3)
- Redox Dark Surface (F6)
- Depleted Dark Surface (F7)
- Redox Depressions (F8)
- Marl (F10) (LRR U)
- Depleted Ochric (F11) (MLRA 151)
- Iron-Manganese Masses (F12) (LRR O, P, T)
- Umbric Surface (F13) (LRR P, T, U)
- Delta Ochric (F17) (MLRA 151)
- Reduced Vertic (F18) (MLRA 150A, 150B)
- Piedmont Floodplain Soils (F19) (MLRA 149A)
- Anomalous Bright Loamy Soils (F20) (MLRA 149A, 153C, 153D)

- 1 cm Muck (A9) (LRR O)
- 2 cm Muck (A10) (LRR S)
- Reduced Vertic (F18) (outside MLRA 150A,B)
- Piedmont Floodplain Soils (F19) (LRR P, S, T)
- Anomalous Bright Loamy Soils (F20) (MLRA 153B)
- Red Parent Material (TF2)
- Very Shallow Dark Surface (TF12)
- Other (Explain in Remarks)

<sup>3</sup>Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

**Restrictive Layer (if observed):**

Type: \_\_\_\_\_

Depth (inches): \_\_\_\_\_

Hydric Soil Present? Yes  No

Remarks:

**WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region**

Project/Site: Site E2, +/-45 Acres City/County: Alexandria/Rapides Sampling Date: 07/30/2015  
 Applicant/Owner: England Authority State: LA Sampling Point: Data Point 5  
 Investigator(s): B. Pittman Section, Township, Range: Section 34 T-4N, R-2W  
 Landform (hillslope, terrace, etc.): terrace Local relief (concave, convex, none): nearly level Slope (%): 1-2  
 Subregion (LRR or MLRA): \_\_\_\_\_ Lat: 31.331008 Long: -92.530648 Datum: NAD 83  
 Soil Map Unit Name: Coushatta silt loam (Nd) NWI classification: NA

Are climatic / hydrologic conditions on the site typical for this time of year? Yes  No \_\_\_\_\_ (If no, explain in Remarks.)  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ significantly disturbed? Are "Normal Circumstances" present? Yes  No \_\_\_\_\_  
 Are Vegetation \_\_\_\_\_, Soil \_\_\_\_\_, or Hydrology \_\_\_\_\_ naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
--	--

Remarks:

**HYDROLOGY**

<b>Wetland Hydrology Indicators:</b> <u>Primary Indicators (minimum of one is required; check all that apply)</u> ___ Surface Water (A1)                      ___ Aquatic Fauna (B13) ___ High Water Table (A2)                 ___ Marl Deposits (B15) <b>(LRR U)</b> ___ Saturation (A3)                            ___ Hydrogen Sulfide Odor (C1) ___ Water Marks (B1)                         ___ Oxidized Rhizospheres along Living Roots (C3) ___ Sediment Deposits (B2)                 ___ Presence of Reduced Iron (C4) ___ Drift Deposits (B3)                        ___ Recent Iron Reduction in Tilled Soils (C6) ___ Algal Mat or Crust (B4)                  ___ Thin Muck Surface (C7) ___ Iron Deposits (B5)                         ___ Other (Explain in Remarks) ___ Inundation Visible on Aerial Imagery (B7) ___ Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> ___ Surface Soil Cracks (B6) ___ Sparsely Vegetated Concave Surface (B8) ___ Drainage Patterns (B10) ___ Moss Trim Lines (B16) ___ Dry-Season Water Table (C2) ___ Crayfish Burrows (C8) ___ Saturation Visible on Aerial Imagery (C9) ___ Geomorphic Position (D2) ___ Shallow Aquitard (D3) ___ FAC-Neutral Test (D5) ___ Sphagnum moss (D8) <b>(LRR T, U)</b>
---	---

<b>Field Observations:</b> Surface Water Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Water Table Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Saturation Present? (includes capillary fringe) Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____	Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>
--	---

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

No saturation, well drained.

**VEGETATION (Four Strata)** – Use scientific names of plants.

Sampling Point: \_\_\_\_\_

<u>Tree Stratum</u> (Plot size: _____ )	<u>Absolute % Cover</u>	<u>Dominant Species?</u>	<u>Indicator Status</u>
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

<u>Sapling/Shrub Stratum</u> (Plot size: _____ )	<u>Absolute % Cover</u>	<u>Dominant Species?</u>	<u>Indicator Status</u>
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

<u>Herb Stratum</u> (Plot size: _____ )	<u>Absolute % Cover</u>	<u>Dominant Species?</u>	<u>Indicator Status</u>
1. Sorghum halepense	35	yes	FAC
2. Setaria spp.	20	yes	FAC
3. Ambrosia trifida	20	yes	FAC
4. Trifolium repens	15	yes	FACU
5. _____	_____	_____	_____
6. _____	_____	_____	_____
7. _____	_____	_____	_____
8. _____	_____	_____	_____
9. _____	_____	_____	_____
10. _____	_____	_____	_____
11. _____	_____	_____	_____
12. _____	_____	_____	_____

90 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

<u>Woody Vine Stratum</u> (Plot size: _____ )	<u>Absolute % Cover</u>	<u>Dominant Species?</u>	<u>Indicator Status</u>
1. _____	_____	_____	_____
2. _____	_____	_____	_____
3. _____	_____	_____	_____
4. _____	_____	_____	_____
5. _____	_____	_____	_____

0 \_\_\_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

Remarks: (If observed, list morphological adaptations below).

**Dominance Test worksheet:**

Number of Dominant Species That Are OBL, FACW, or FAC: 3 \_\_\_\_\_ (A)

Total Number of Dominant Species Across All Strata: 4 \_\_\_\_\_ (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 75 \_\_\_\_\_ (A/B)

**Prevalence Index worksheet:**

Total % Cover of: \_\_\_\_\_ Multiply by: \_\_\_\_\_

OBL species \_\_\_\_\_ x 1 = \_\_\_\_\_

FACW species \_\_\_\_\_ x 2 = \_\_\_\_\_

FAC species \_\_\_\_\_ x 3 = \_\_\_\_\_

FACU species \_\_\_\_\_ x 4 = \_\_\_\_\_

UPL species \_\_\_\_\_ x 5 = \_\_\_\_\_

Column Totals: 0 \_\_\_\_\_ (A) 0 \_\_\_\_\_ (B)

Prevalence Index = B/A = \_\_\_\_\_

**Hydrophytic Vegetation Indicators:**

1 - Rapid Test for Hydrophytic Vegetation

2 - Dominance Test is >50%

3 - Prevalence Index is ≤3.0<sup>1</sup>

Problematic Hydrophytic Vegetation<sup>1</sup> (Explain)

<sup>1</sup>Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

**Definitions of Four Vegetation Strata:**

**Tree** – Woody plants, excluding vines, 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height.

**Sapling/Shrub** – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.

**Herb** – All herbaceous (non-woody) plants, regardless of size, and woody plants less than 3.28 ft tall.

**Woody vine** – All woody vines greater than 3.28 ft in height.

**Hydrophytic Vegetation Present?**

Yes  No



**SOIL**

Sampling Point: DP-5

**Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)**

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>		
0-18	5 YR 5/8	85%	5 YR 4/2	15%	R/VI	VI	sandy loam	some gravel

<sup>1</sup>Type: C=Concentration, D=Depletion, RM=Reduced Matrix, MS=Masked Sand Grains.

<sup>2</sup>Location: PL=Pore Lining, M=Matrix.

**Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)**

**Indicators for Problematic Hydric Soils<sup>3</sup>:**

- |  |   |   |
|--|---|---|
| <input type="checkbox"/> Histosol (A1)                         | <input type="checkbox"/> Polyvalue Below Surface (S8) (LRR S, T, U)                 | <input type="checkbox"/> 1 cm Muck (A9) (LRR O)   |
| <input type="checkbox"/> Histic Epipedon (A2)                  | <input type="checkbox"/> Thin Dark Surface (S9) (LRR S, T, U)                       | <input type="checkbox"/> 2 cm Muck (A10) (LRR S)  |
| <input type="checkbox"/> Black Histic (A3)                     | <input type="checkbox"/> Loamy Mucky Mineral (F1) (LRR O)                           | <input type="checkbox"/> Reduced Vertic (F18) (outside MLRA 150A,B)   |
| <input type="checkbox"/> Hydrogen Sulfide (A4)                 | <input type="checkbox"/> Loamy Gleyed Matrix (F2)                                   | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (LRR P, S, T)  |
| <input type="checkbox"/> Stratified Layers (A5)                | <input type="checkbox"/> Depleted Matrix (F3)                                       | <input type="checkbox"/> Anomalous Bright Loamy Soils (F20)   |
| <input type="checkbox"/> Organic Bodies (A6) (LRR P, T, U)     | <input type="checkbox"/> Redox Dark Surface (F6)                                    | <b>(MLRA 153B)</b>  |
| <input type="checkbox"/> 5 cm Mucky Mineral (A7) (LRR P, T, U) | <input type="checkbox"/> Depleted Dark Surface (F7)                                 | <input type="checkbox"/> Red Parent Material (TF2)  |
| <input type="checkbox"/> Muck Presence (A8) (LRR U)            | <input type="checkbox"/> Redox Depressions (F8)                                     | <input type="checkbox"/> Very Shallow Dark Surface (TF12)   |
| <input type="checkbox"/> 1 cm Muck (A9) (LRR P, T)             | <input type="checkbox"/> Marl (F10) (LRR U)   | <input type="checkbox"/> Other (Explain in Remarks)   |
| <input type="checkbox"/> Depleted Below Dark Surface (A11)     | <input type="checkbox"/> Depleted Ochric (F11) (MLRA 151)                           | <sup>3</sup> Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic. |
| <input type="checkbox"/> Thick Dark Surface (A12)              | <input type="checkbox"/> Iron-Manganese Masses (F12) (LRR O, P, T)                  |   |
| <input type="checkbox"/> Coast Prairie Redox (A16) (MLRA 150A) | <input type="checkbox"/> Umbric Surface (F13) (LRR P, T, U)                         |   |
| <input type="checkbox"/> Sandy Mucky Mineral (S1) (LRR O, S)   | <input type="checkbox"/> Delta Ochric (F17) (MLRA 151)                              |   |
| <input type="checkbox"/> Sandy Gleyed Matrix (S4)              | <input type="checkbox"/> Reduced Vertic (F18) (MLRA 150A, 150B)                     |   |
| <input type="checkbox"/> Sandy Redox (S5)                      | <input type="checkbox"/> Piedmont Floodplain Soils (F19) (MLRA 149A)                |   |
| <input type="checkbox"/> Stripped Matrix (S6)                  | <input type="checkbox"/> Anomalous Bright Loamy Soils (F20) (MLRA 149A, 153C, 153D) |   |
| <input type="checkbox"/> Dark Surface (S7) (LRR P, S, T, U)    |   |   |

**Restrictive Layer (if observed):**

Type: \_\_\_\_\_

Depth (inches): \_\_\_\_\_

Hydric Soil Present? Yes  No

Remarks:

area historically disturbed, old tank farm location